Planning Commission



REGULAR MEETING AGENDA

Date: 11/17/2025 Time: 7:00 p.m.

Location: Zoom.us/join - ID# 846 9472 6242 and

City Council Chambers

751 Laurel St., Menlo Park, CA 94025

Members of the public can listen to the meeting and participate using the following methods.

How to participate in the meeting

- Access the live meeting, in-person, at the City Council Chambers
- Access the meeting real-time online at: zoom.us/join – Meeting ID# 846 9472 6242
- Access the meeting real-time via telephone (listen only mode) at: (669) 900-6833

Regular Meeting ID # 846 9472 6242

Press *9 to raise hand to speak

 Submit a written comment online up to 1-hour before the meeting start time: planning.commission@menlopark.gov*

Please include the agenda item number related to your comment.

*Written comments are accepted up to 1 hour before the meeting start time. Written messages are provided to the Planning Commission at the appropriate time in their meeting.

Subject to change: The format of this meeting may be altered or the meeting may be canceled. You may check on the status of the meeting by visiting the city website menlopark.gov. The instructions for logging on to the webinar and/or the access code is subject to change. If you have difficulty accessing the webinar, please check the latest online edition of the posted agenda for updated information (menlopark.gov/agendas).

Regular Meeting

- A. Call To Order
- B. Roll Call
- C. Reports and Announcements
- D. Public Comment

Under "Public Comment," the public may address the Commission on any subject not listed on the agenda. Each speaker may address the Commission once under public comment for a limit of three minutes. You are not required to provide your name or City of residence, but it is helpful. The

Planning Commission Regular Meeting Agenda November 17, 2025 Page 2

Commission cannot act on items not listed on the agenda and, therefore, the Commission cannot respond to non-agenda issues brought up under Public Comment other than to provide general information.

E. Study Session

E1. Study session/Menlo Park Fire Protection District/300 Middlefield Rd. and 114 Santa Margarita Ave.:

Request for a study session to redevelop Fire Station 1, including the demolition of the existing fire station and training tower, and subsequent construction of a new fire station (two stories), training tower (five stories), district operations center (two stories), and underground parking. The project would include rezoning from R-1-S (Single Family Suburban Residential) to PF (Public Facilities), an associated General Plan Land Use Designation amendment, a Zoning Ordinance text amendment to allow greater than 60 percent FAR (Floor Area Ratio), a General Plan text amendment to allow the proposed FAR within the Public Facilities designation, a Use Permit for the higher FAR, overall development as an emergency services facility (Special Use), and the use of hazardous materials (diesel fuel for an emergency generator and propane for training exercises), and Architectural Control for the buildings and site improvements. The applicant is also requesting use permit approval for a temporary emergency services facility (Special Use) at 114 Santa Margarita Avenue during construction of the project. (Staff report #25-051-PC)

F. Informational Items

- F1. Future Planning Commission Meeting Schedule The upcoming Planning Commission meetings are listed here, for reference. No action will be taken on the meeting schedule, although individual Commissioners may notify staff of planned absences.
 - Regular Meeting: December 1, 2025
 - Regular Meeting: December 15, 2025

G. Adjournment

At every regular meeting of the Planning Commission, in addition to the public comment period where the public shall have the right to address the Planning Commission on any matters of public interest not listed on the agenda, members of the public have the right to directly address the Planning Commission on any item listed on the agenda at a time designated by the chair, either before or during the Planning Commission's consideration of the item.

At every special meeting of the Planning Commission, members of the public have the right to directly address the Planning Commission on any item listed on the agenda at a time designated by the chair, either before or during consideration of the item. For appeal hearings, appellant and applicant shall each have 10 minutes for presentations.

If you challenge any of the items listed on this agenda in court, you may be limited to raising only those issues you or someone else raised at the public hearing described in this notice, or in written correspondence delivered to the City of Menlo Park at, or before, the public hearing.

Planning Commission Regular Meeting Agenda November 17, 2025 Page 3

Any writing that is distributed to a majority of the Planning Commission by any person in connection with an agenda item is a public record (subject to any exemption under the Public Records Act) and is available by request by emailing the city clerk at jaherren@menlopark.gov. Persons with disabilities, who require auxiliary aids or services in attending or participating in Planning Commission meetings, may call the City Clerk's Office at 650-330-6620.

Agendas are posted in accordance with Cal. Gov. Code §54954.2(a) or §54956. Members of the public can view electronic agendas and staff reports by accessing the city website at menlopark.gov/agendas and can receive email notifications of agenda postings by subscribing at menlopark.gov/subscribe. Agendas and staff reports may also be obtained by contacting City Clerk at 650-330-6620. (Posted: 11/12/2025)

Community Development



STAFF REPORT

Planning Commission

Meeting Date: 11/17/2025 Staff Report Number: 25-052-PC

Study Session: Consider and provide feedback on the proposed

Fire Station 1 redevelopment project at 300

Middlefield Road and an associated temporary fire

services station at 114 Santa Margarita Ave.

Recommendation

Staff recommends that the Planning Commission review and provide feedback on the proposed redevelopment of the Menlo Park Fire Protection District (MPFPD) Fire Station 1 located at 300 Middlefield Road. The proposed project would demolish the existing fire station and training tower and construct a new fire station building (Building A), new administrative office building (Building B), new training tower (Building C), and underground parking. The new buildings would total approximately 52,621 square feet and would accommodate fire station operations, administrative offices, and firefighter training facilities. The project would include the temporary use of 114 Santa Margarita Ave. for a fire services facility during the redevelopment of the main site. The project is anticipated to include the following actions:

- 1. **Rezoning:** To change the 300 Middlefield Road site's zoning designation from the R-1-S (Single Family Suburban Residential) district to P-F (Public Facilities) district, to allow the proposed use of the subject site to be more consistent with the appropriate zoning district.
- 2. **Zoning Ordinance Text Amendment:** To allow the maximum allowable Floor Area Ratio (FAR) in the P-F district to exceed 30 percent through a use permit, up to a maximum of 80 percent on sites with a lot area of two acres or less, where currently up to 60 percent is allowed with a use permit.
- **3. General Plan Land Use Designation Change:** To amend the 300 Middlefield Road site's General Plan Land Use designation from Low-Density Residential to Public/Quasi-Public which allows public facilities, including fire stations, government office buildings, and similar compatible uses.
- 4. **General Plan Text Amendment**: To amend the general plan text to increase the 30 percent maximum allowed FAR within the Public Facilities district to allow for up to 80 percent FAR, as approved by use permit, consistent with the Zoning Ordinance Text Amendment and project proposal.
- 5. **Use Permit:** To allow for the proposed FAR of approximately 80 percent on 300 Middlefield Road, overall development as an emergency services facility (Special Use) on both sites, and the use and storage of hazardous materials (diesel fuel for an emergency generator and propane for training exercises) at 300 Middlefield Road and possibly on 114 Santa Margarita Ave. as well.
- 6. **Architectural Control:** To review the design of the proposed fire station buildings and site improvements on both sites.
- 7. **Sign Review:** To review a comprehensive sign program for a fire station including three signs on Middle Field Road and one Sign along Santa Monica Ave. which would deviate from certain

- aspects of the Design Guidelines for Signs.
- 8. **Heritage Tree Removal:** To allow the removal of 21 heritage trees at 300 Middlefield Road and one heritage tree at 114 Santa Margarita Ave.
- 9. **Environmental Review:** To evaluate the potential impacts on both sites pursuant to California Environmental Quality Act (CEQA).

Additional actions and entitlements may be required as the project plans are refined. No formal actions will be taken at this time. The Planning Commission should review and provide individual Commissioner feedback on the project to the applicant and staff. Below are some topic areas for the Planning Commission's consideration; however, the Commission's discussion is not limited to these topics:

- Proposed uses
- · Gross floor area
- Architectural design and materials
- Parking and circulation
- Landscaping
- Offsite temporary fire station
- Overall approach

Policy Issues

Study sessions provide an opportunity for Planning Commissioners and the public to provide preliminary feedback on a project, with comments used to inform future review and consideration of the proposal.

Background

In this report, references to "primary project site" and similar terms refer to 300 Middlefield Road, while references to "temporary site" and similar terms refer to 114 Santa Margarita Ave. The primary project site consists of a single parcel totaling approximately 85,285 square feet (1.96 acres) located at 300 Middlefield Road within the R-1-S (Single Family Suburban Residential) zoning district. The site is currently developed with two structures, a fire station building and a five-story training tower, and is actively used by the Menlo Park Fire Protection District as an operational fire station and training facility.

The primary property is located at the northwest corner of Middlefield Road and Santa Monica Ave. The property line which abuts Middlefield Road is considered the front, and the side of the property which abuts Santa Monica Ave. is considered the corner side. In 2017, MPFPD expanded the site through the acquisition and consolidation of parcel area to the north and west that was previously owned by St. Patrick's Seminary, thereby increasing the station site area. Adjacent uses include St. Patrick's Seminary to the north and west, also located within the R-1-S zoning district. Commercial office uses within the C-1 (Administrative and Professional, Restrictive) district are located across Santa Monica Ave. and across Middlefield Road, and residential uses within the R-1-U (Single Family Urban Residential) district are also located farther along Santa Monica Ave.

On Santa Margarita Ave., the proposed temporary site is located within a cluster of commercial properties that are within the C-MU (Neighborhood Mixed Use) zoning district, and additional C-1 and R-1-U parcels

are located along this street as well. Location maps for both project sites are provided as Attachment A.

The project is currently being reviewed for consistency with the City's development requirements and may be subject to change as a result of the plan review process.

Project overview

The applicant is requesting approval to demolish the existing fire station and training tower to allow for the construction of three new buildings and associated site improvements on an approximately 85,344-square-foot (1.96-acre) site at 300 Middlefield Road. The proposed project includes a new two-story fire station (Building A), a two-story administrative building or district operations center (Building B), and a five-story training tower (Building C), along with related site improvements such as surface parking, a below-grade parking structure, and new landscaping. In total, the project would result in approximately 64,120 square feet of gross floor area. Table 1 below shows the breakdown of gross floor area by building. The total proposed floor area ratio (FAR) would be 0.752, or 75.2 percent. The proposed improvements are part of the Fire District's broader effort to modernize its facilities, improve operational efficiency, and enhance emergency response capabilities to better serve the community.

| Table 1: Fire Station 1 proposed buildings | | | |
|--|--------------------------|---------------------------|--|
| Building name | Building use | Gross floor area (GFA) | |
| Building A | Fire Station | 16,296 | |
| Building B | Administrative Buildings | 33,036 | |
| Building C | Training Tower | 14,788 | |

To maintain fire station operations during construction, the District proposes to establish a temporary facility at 114 Santa Margarita Ave. The temporary site would accommodate essential operations through the installation of modular buildings and supporting infrastructure. Implementation of the temporary facility would include the demolition of an existing two-story building, removal of a heritage tree, and paving and grading work to accommodate the placement of temporary structures and driveways. Once construction at 300 Middlefield Road is completed, the temporary operations would be removed from the site. MPFPD plans to keep the property as parking until there are plans for future development or the property is sold. A more detailed construction phasing plan is included on sheet A6.1 of the plan set (Attachment C).

As part of the proposal, the applicant intends to pursue the discretionary actions described in greater detail below. The applicant's project description letter is included as Attachment B. The proposed General Plan amendments, rezonings, and amendments to the text of the Zoning Ordinance would be acted on by the City Council. The Planning Commission will be acting in a recommending capacity on the rezoning and General Plan amendments for the primary project site, with those final actions on the overall project conducted by the City Council. The Planning Commission would be the acting body on the use permits, architectural control, and sign review, and the City Council would only review those items if any are appealed. Because the temporary site does not include any rezoning or General Plan actions, the Planning Commission would be the final decision-making body for that site, unless any such actions are

Staff Report #: 25-052-PC Page 4

appealed.

Analysis

Rezoning and zoning text amendment

The primary project site is currently zoned R-1-S (Single Family Suburban Residential). The applicant is requesting that this site be rezoned to the P-F (Public Facilities) District to accommodate the proposed fire station and associated uses. The P-F zoning would match how the MPFPD's two other stations within the City of Menlo Park (Station 6 at 700 Oak Grove Ave. and Station 77 at 1467 Chilco St.) are zoned. Under the current P-F zoning regulations, the floor area ratio (FAR) is generally limited to 30 percent, with the possibility of increasing up to 60 percent for sites that are less than two acres in size, through the approval of a use permit. However, the applicant is proposing a development with an FAR of approximately 75.2 percent. Therefore, in addition to the rezoning, the applicant is requesting a text amendment to the zoning ordinance to allow an FAR of up to 80 percent on a parcel less than two acres in size within the P-F zoning district through the use permit process. This amendment would provide the regulatory framework needed for the project to proceed as designed and ensure that the proposed FAR is consistent with the intended use of the site. The temporary project site would remain under its existing C-MU zoning designation, since the Special Uses section of the Zoning Ordinance would conditionally allow the temporary fire station with a use permit, without a specific FAR limit.

General Plan Land Use Diagram and text amendment

The primary project site currently has a General Plan land use designation of Low Density Residential. In conjunction with the proposed rezoning of the site to the P-F (Public Facilities) district, the applicant is requesting an amendment to the General Plan Public Facilities land use designation, which is the corresponding General Plan designation for the proposed zoning.

Currently, the General Plan limits the floor area ratio (FAR) for Public Facilities to 30 percent. However, the proposed project includes an FAR closer to 80 percent, and thus the applicant is seeking a General Plan text amendment to allow for up to 80 percent FAR under the Public Facilities designation. This amendment would ensure consistency between the project's design and the updated General Plan standards for public facilities.

The temporary site would remain under its existing General Plan land use designation of Retail/Commercial.

Floor Area Ratio and Gross Floor Area

The project proposes to develop the primary project site with a Floor Area Ratio (FAR) of approximately 75.2 percent. The Public Facilities (P-F) zoning district generally allows 30 percent FAR and allows sites of two acres or less to be developed up 60 percent with a use permit. As mentioned above, the proposed project, however, seeks an FAR of 75.2, which exceeds both the base-level and the current maximum allowed with the approval of a use permit in the P-F zoning district. Therefore, the applicant is requesting a text amendment to the zoning code and general plan text to accommodate this increased FAR.

According to Section 16.04.325(c)(3) of the Zoning Ordinance, areas of a building "devoted to covered parking and related circulation for automobiles and bicycles, including garages, carports, below grade

parking structures, and above grade parking structures" may be excluded from gross floor area. While the underground parking is excluded from the gross floor area the apparatus bays in Building A (5,792.4 square feet) and Building B (3,167.9 square feet), a total of area of 8,960.3 square feet are counted toward GFA based on past Planning Commission direction for MPFPD projects in Menlo Park.

Building A, the new fire station, would be approximately 16,296 square feet. Building B, the administrative building, would be approximately 33,036 square feet. Building C, the training tower, would be approximately 14,788 square feet. In total, the project would result in approximately 64,120 square feet of GFA, representing a floor area ratio (FAR) of 0.752 or 75.2 percent.

The temporary project site's review under the Special Uses conditional allowance does not include a specific FAR limit, but rather allows impacts to be considered holistically.

Proposed buildings

The applicant proposes to demolish all existing buildings and structures on the primary project site and construct three new buildings with associated site improvements.

Building A, the new two-story, 32-foot-tall fire station, would front Middlefield Road and include a garage with four apparatus bays that provide direct access onto Middlefield Road, allowing fire trucks to pull through from the back of the building and exit out the front. The building would be set back approximately 18.4 feet from Middlefield Road, 40.3 feet from the interior side property line, and 18.5 feet from the side street-facing property line along Santa Monica Ave.

Building A would include a four-bay garage for fire apparatus, a public lobby area showcasing an antique apparatus as well as historical firefighting equipment, and living quarters for fire personnel, along with office, work, and fitness areas to support daily operations.

Building B, the new two-story, 30-foot-tall administrative building (District Operations Center), would be located at the rear of the property, set back approximately five feet from the interior side and rear property lines, and 15.5 feet from the street-facing setback along Santa Monica Ave.

Building B would contain administrative offices, boardrooms, storage areas, and a two-bay garage for additional apparatus. The building is intended to consolidate Fire District administrative employees who are currently located at off-site facilities, allowing all staff to operate from a single, centralized location. In addition to administrative functions, Building B would also accommodate public meetings and community gatherings. The building would provide internal access to the basement level and the underground parking structure through elevators and stairwells, with the two-bay apparatus garage accessed from the interior of the site.

Building C, the five-story, 50-foot-tall training tower, would be located within the interior of the site, positioned behind Building A and in front of Building B. The tower would be set back approximately 109 feet from the rear of Building A, 44 feet from the interior side property line, and 107.3 feet from the street-facing side along Santa Monica Ave. Building C would be situated farther from Middlefield Road than Building A, providing additional separation between the training tower and the public street frontage.

Building C would serve as a training tower designed to support a wide range of firefighter training activities under various conditions. The facility would include a five-story concrete masonry unit (CMU) structure approximately 50 feet in height, along with a smaller one-story residential training prop and a basement level to accommodate additional training scenarios. The training tower is intended to provide opportunities for high-rise operations, elevator rescues, high-angle rope training, center-hallway fire simulations, confined space exercises, firefighter survival and rapid intervention crew training, and Class B (propane) live fire training. The applicant has relayed that the proposed facility would enhance the Fire District's ability to conduct realistic and comprehensive training on site.

All three buildings are designed in a contemporary architectural style that incorporates a variety of materials. The exterior finishes include black metal panels, wood-tone fiber cement panels, and CMUs in both black and tan. Building façades would feature aluminum doors and window frames finished in red or black, providing a cohesive and modern appearance. Additional design elements would include black corrugated metal accents, metal railings, and red entry doors. The roof areas would incorporate metal corrugated screening to conceal mechanical equipment and maintain a clean, integrated roofline.

To ensure continuous fire station operations during the construction period, the project proposes the establishment of a temporary fire station at 114 Santa Margarita Ave., one block over from 300 Middlefield Road to the southeast. The current site at that location includes a two-story building used as administrative offices for the Fire Department, which would be demolished as part of this proposal.

The site would then be repaved and reconfigured to accommodate a driveway and seven parking spaces and a paved area for two trailer buildings: one large trailer for living quarters and another serving as a laundry and fitness space. Additionally, an apparatus tent for fire apparatus and a power connection box would be installed. An existing shed in the rear left corner of the site would remain in place. These structures would be more utilitarian in design, which could be considered to align with the site's temporary nature.

Parking and circulation:

The primary project site proposes a total of 96 parking spaces, consisting of 18 surface spaces, 17 of which would be located interior to the site, fenced off and accessed through driveway gates and 76 spaces located within an underground parking structure beneath Buildings B and C, occupying the rear two-thirds of the site. The P-F Zoning District does not impose specific requirements for number of parking spaces, but the MPFPD has indicated 12 of the secure parking spaces are intended for the overlapping change of shift for the fire station, five spaces are for trailers owned by the Fire District, 50 spaces are needed for other staff who work on site, and the additional spaces would be used for district vehicles, overflow parking, public events and emergency personnel if needed.

Site access to the primary project site would be provided through four driveways: two along Middlefield Road and two along Santa Monica Ave. Along Middlefield Road, the first driveway, located to the left of Building A, would provide access to the site's internal circulation and surface parking area, while the second driveway would serve as an egress route for fire apparatus exiting from Building A. Along Santa Monica Ave., one driveway would provide access to the below-grade parking structure, and the second

would provide access to the interior surface parking area. Primary access to the interior portion of the site would be via the Santa Monica Ave. entrance and secondary access will be provided using the Middlefield Road entry. Both driveways would have an automobile gate entry, with access managed by employee key cards.

The temporary site would feature seven parking spaces, in addition to the apparatus tent for the fire vehicle. As part of further project review, staff will ask the applicant to justify the specific parking space number with regard to the operation of this temporary facility, to ensure that parking impacts on neighboring properties are limited.

Sign program

The applicant proposes a comprehensive sign program for the primary project site that identifies the location, size, and design of five building-mounted signs throughout the site. The proposed signage is intended to provide clear identification of the fire station and administrative functions while maintaining a cohesive and professional appearance consistent with the architectural design of the new facility.

Three signs are proposed on the front of Building A (the fire station) along the Middlefield Road frontage. These include a firefighter's medallion logo located on the left side of the building, a sign above the apparatus bays reading "Menlo Park Fire Station No. 1," and a large numeral "1". Along the Santa Monica Ave. frontage, a smaller wall-mounted sign would identify Building B, reading "Menlo Park Fire Protection District Administration Building". An additional sign would be located on the interior-facing elevation of Building B, visible from within the site, which would read "Menlo Park Fire protection District". All proposed signs are shown on Sheet AP5.0, AA5.1 and AB5.1 of project plans (Attachment C).

Staff reviews all sign applications for conformance with both the Zoning Ordinance regulations and the City's Design Guidelines for Signs. If a proposed sign meets the requirements of both documents, staff may approve the sign request administratively. However, if the proposed signage does not comply with the Zoning Ordinance or is inconsistent with the Design Guidelines, the application must be forwarded to the Planning Commission for consideration. In such cases, the review would occur either through a variance application for non-compliance with the Zoning Ordinance or as a general review for consistency with the Design Guidelines.

For this application, staff determined that the proposed signs comply with all applicable Zoning Ordinance regulations. However, the proposed sign program is not fully consistent with the Design Guidelines for Signs. Specifically, the proposal does not conform to Item B.11 of the Design Guidelines, which limits each business or tenant to one building-mounted sign on each street frontage of a parcel. Since three signs are proposed along the Middlefield Road frontage, the request exceeds this guideline and the sign program requires review and approval by the Planning Commission.

Despite this inconsistency, the proposed sign program appropriately identifies the site as a public facility and provides necessary visual cues for emergency response and community recognition. All proposed signs would serve the same occupant, and the total sign area meets the maximum allowable sign area.

Emergency generator and hazardous materials

The proposal includes multiple components involving the use and storage of hazardous materials on the primary project site. An emergency generator, 1,000-gallon diesel fuel tank, a 1,000-gallon unleaded fuel tank and a 1,000-gallon propane tank is proposed to be located within the interior of the site, situated between Building A and Building C, adjacent to the parking area and Santa Monica Ave. driveway entrance. This generator would serve as a backup power source in the event of an outage. A 1,000-gallon above-ground diesel fuel storage tank and a 1,000-gallon propane tank would be located outdoors, protected by bollards and fencing. The fuel tanks would be used for refueling fire engines, district vehicles and powering the emergency generator, while the propane tank would support training exercises within the training tower.

On the temporary site, an emergency generator is planned to provide power in the event of an emergency, although its exact site has not yet been determined. If it includes diesel fuel in excess of the relevant hazardous materials threshold, use permit approval for hazmat on this site would be considered as part of the final project actions.

The use and storage of these materials will require a use permit and will undergo environmental review in compliance with CEQA. The applicant has prepared a Hazardous Materials Business Plan (HMBP), included as Attachment E, which outlines training and protection measures in the event of an emergency.

Heritage tree removal and tree planting plan

There are a total of 23 trees, (21 of which are designated as heritage trees) on the primary project site, all of which are proposed for removal. Tree removal is proposed due to direct conflicts with the footprint of the new buildings, underground parking, and other site improvements. All existing trees are located in areas essential for construction, making their removal unavoidable. Proposed tree removals are shown on sheet L1.0 of project plans (Attachment C).

Landscaping is proposed along the Middlefield Road and Santa Monica Ave. frontages, at the corner of Middlefield Road and Santa Monica Ave., and throughout key areas of the site to enhance the streetscape, soften building edges, and provide visual buffering from surrounding uses. The applicant has submitted an arborist report (Attachment D) that details the species, size, and condition of these existing trees, assesses their current health, discusses the impacts of the proposed development, and provides recommendations for preservation or removal.

To compensate for the loss of all trees, the proposed planting plan includes the planting of 18 coast live oaks off-site on the neighboring St. Patrick's Seminary property, around the perimeter of the site. The applicant has relayed that St. Patrick's Seminary has accepted this concept of off-site planting, which would be documented more formally, and confirmed acceptable by the City Arborist, prior to project actions. On-site, the applicant would plant 23 trees along the street frontage including three trees along Middlefield Road to the left of the fire station building, and 20 trees along Santa Monica Ave. The proposed planting plan is included on sheet L1.1 of project plans (Attachment C).

On the temporary site, there are three heritage trees, two of which would be preserved. However, tree number 24, a 66-inch coast redwood tree in fair health, is proposed to be removed. The removal of tree number 24 is proposed due to conflicts with the planned parking and driveway paving areas, which would

Staff Report #: 25-052-PC Page 9

necessitate its removal to accommodate the temporary facility layout. A site plan for the temporary fire station facility is located within project plan sheet TF1.0 (Attachment C).

Impact on City Resources

The project sponsor is required to pay Planning, Building and Public Works permit fees, based on the City's Master Fee Schedule, to fully cover the cost of staff time spent on the review of the project.

Environmental Review

The City is working to finalize contract services of a consultant to provide an environmental review pursuant to the California Environmental Quality Act (CEQA). The initial CEQA work would include an Initial Study (IS) to evaluate potential impacts, which would then feed into a Negative Declaration/Mitigated Negative Declaration (ND/MND), or possibly an Environmental Impact Report (EIR) if there are significant impacts that cannot be mitigated.

Public Notice

Public notification was achieved by posting the agenda, with the agenda items being listed, at least 72 hours prior to the meeting. Public notification also consisted of publishing a legal notice in the local newspaper and notification by mail of owners and occupants within a 1,320-foot radius of both subject properties.


Attachments

- A. Location Map
- B. Project Description Letter
- C. Project Plans
- D. Arborist Report
- E. Hazardous Materials Business Plan HMBP

Report prepared by: Jacob Garcia, Contract Planner

Report reviewed by: Thomas Rogers, Principal Planner

ATTACHEMENT A






City of Menlo Park
Location Map
Fire Station 1



Scale: 1:4,000 Drawn By: THR Checked By: KTP Date: 11/17/2025 Sheet: 1





City of Menlo Park

Location Map

Fire Station 1 - Temporary Station



Scale: 1:4,000 Drawn By: THR Checked By: KTP Date: 11/17/2025 Sheet: 2



Fire Station No. 01 300 Middlefield Road, Menlo Park, CA Project Description

History

Menlo Park Fire Protection District Fire Station 1 is located at 300 Middlefield Road, Menlo Park, CA 94025. This station is located in the County of San Mateo and the authority having jurisdiction is the City of Menlo Park. The two-story fire station was built in 1955 and was seismically retrofitted in the 1990s. The station requires replacement to address its deteriorating infrastructure, to make it compliant with updated building codes, to address fire safety requirements, to incorporate advancements in technology and safety enhancements, and to provide additional space for staff, apparatus, and storage. Fire Station 1 staffs an engine and a squad which is operated by five personnel. In addition, the training division's office staff works out of the second floor of the fire station. The site includes an emergency diesel fueled generator, a 5-story training tower that is attached to the station, and an ancillary building comprised of a multi-purpose room for board meetings and training, a small mechanic shop used for storage, and an exercise room. In 2009 the District completed the remodel of the District owned office building at 170 Middlefield Road. Upon completion of this remodel the District relocated the administration and fire prevention office personnel to this new building. In 2016 the District procured 114 Santa Margarita in order to provide additional office space for its employees. In 2018, the District acquired 1.01 acres adjacent to Fire Station 1 from the Roman Catholic Church. The lot acquired has been merged with the existing lot to form a 1.96-acre lot. The property acquisition provides the District with the ability to develop the site to include a new fire station, training facility, an office building for administration, training, and fire prevention staff, a storage building for equipment and supplies and a multipurpose room that can be used as a board room, trainings and a district operations center.

Scope of Work

Menlo Park Fire District has since outgrown the existing site as well as their headquarters. MPFD intends to utilize 300 Middlefield Road as their new headquarters. The existing site and its features will be completely demolished and make way for 3 new buildings and new code compliant site features. The site will house a new Fire Station, District Administration/Storage building with a District Operation Center, and Training Tower. A temporary facility will be established at 114 Santa Margarita Ave to allow the fire station to remain fully operational during construction of the new facility.





Fire Station

The project includes a new 16,300 square foot, two-story Fire Station with enough room for future growth of the fire district. The Fire Station sits in a similar footprint to the existing station and has an approximate height of 32 feet. The new station will house four drive-through apparatus bays each capable of accommodating a tiller truck or multiple fire engines parked in tandem. The main entry drive for the drive-through bay would be accessed off of Santa Monica Avenue with a secondary entry accessed off of Middlefield Road, while the apparatus bay would exit onto Middlefield Road. In addition to the apparatus space, the first floor of the new fire station would include a public lobby showcasing an antique apparatus as well as historical firefighting equipment, offices, a fitness room and utility space. The second floor of the new fire station would be composed of living quarters for on-duty personnel, including a second story patio deck. The proposed staffing of the fire station would remain at five on-duty firefighters for each rotation. The fire station would include living and sleeping quarters to accommodate up to thirteen firefighters and one Battalion Chief to address future growth. The Fire Station designed in contemporary architectural style. Black metal panels and wood tone fiber cement plank is intended to be used. Glazing will be utilized as much as possible.

Fire Station 1 staffs an engine and a squad which is operated by five personnel. Staffing at this station is not expected to change. The Fire Station will just be staffed by emergency response personnel and its primary and only function is to serve as a fire station.

Office/Storage/District Operations Center Building

Building B will serve as an office building as well as a storage building. Upon completion of the proposed Station 1 project, the administration and fire prevention staffing of approximately 25 personnel will be relocated back to Station 1 from 170 Middlefield road and 114 Santa Margarita. In addition, the training division consisting of 4 personnel, which currently occupies Station 1 will also be relocated to the new office building. The storage portion of the building will contain spare equipment and consumables which will be used District wide as well as additional space for reserve and/or training apparatus. On the first floor of the building will be storage space, office space for the training division and also shared spaces which include locker room space, a breakroom and a multi-purpose room. The multi-purpose room will serve as a training room, a space for Board meetings and as a District Operations Center.





On the second floor of the "L" shaped building at the rear of the lot is proposed to provide office space for the administration and fire prevention personnel. This building is designed in contemporary architectural style which matches the Fire Station. Black metal panels and wood tone fiber cement plank is intended to be used.

The District currently holds public events such as Board meetings, classes, and a couple large events at Fire Station 1. The District plans to continue to hold these events post construction and has no plans to hold additional events at this time. These events include the following:

- CPR classes one Saturday a month from 9 am-5 pm
- Stop the Bleed class one Monday a month from 6:00-7:30 pm
- Red Cross Ready class one Wednesday a month from 6:00-7:30 pm
- CERT Academy twice per year- each is about 20 hours of instruction spread across either Thursday evenings or Saturday full days. In the spring, we do 5 Thursday evenings from 6-9 pm plus one Saturday 9-1. In the fall, we do 3 Saturdays from 9-4.
- We also would have periodic meetings with our CERT team and community groups, about 2-3 times a year that each last around 1-2 hours.
- We have our annual Pancake Breakfast in October from 7:30-11:00.
- Fire Board meetings monthly. Third Tuesday every month from 7pm 10pm (approximately)

Training Tower

The proposed training facility is anticipated to provide high-rise training, elevator rescue, high-angle rope, center hallway construction, confined space, firefighter survival and rapid intervention crew training, and class B (propane) fire training. This building will be comprised of a 5-story concrete masonry unit structure that is 50' in height along with a smaller 1 story residential training prop. There is also a basement to allow for additional training opportunities. The existing Training Tower has an antenna at the top of the building. This antenna will be removed and relocated to the Temporary Fire Station at the beginning of construction. Once construction is complete, the antenna will be relocated and mounted to the top of the new Training Tower.





The training building has no office space and will have no personnel operating out of it. The building will be comprised of several rooms which contain miscellaneous training props. The building will be used to train the District's emergency response personnel. Typical training consists of 1-2 crews at one time (3-7 personnel) however larger trainings such as cadet training (which we currently perform at Station 1) can include around 15-20 personnel. The number of personnel to be trained at the site would stay consistent with current training practices.

Training activities and hours will remain consistent with the existing training schedule. Training activities include all aspects of fire suppression and rescue training. Training hours are 0900-1700, with occasional evening drills. Trainings are conducted weekly in the classroom or on the drill ground.

The new facility will have class B (propane fueled) props that run on a dead man switch. They will turn off when the instructor takes their hand off the button. These will be located in rooms inside the tower and not visible from the exterior. The building is non-combustible and no smoke is generated by the propane props. Theatrical smoke will be used to simulate fire conditions but is non-toxic and white in color. The smoke will not be visible on the exterior. The fire district currently uses the theatrical smoke often at the current facility.

Training is both indoors and outdoors, depending on the topic. Much of the training will be in the classroom or inside the training tower, some will be on the drill ground surrounding the tower.

The training tower will be constructed of CMU block and intended to be dark in color.

Temporary Facility

In order to allow Station #1 to remain fully operational during the construction of the new site, crew will be housed down the street at 114 Santa Margarita Ave at a Temporary Facility. The site currently houses an existing house and is used as an admin building for Menlo Park Fire Protection District. The existing building will be demolished to allow for the following temporary structures: apparatus tent, living quarter trailer, laundry/fitness trailer, connex box, and the existing shed that will remain. Office staff currently occupying the building will be relocated to leased office space. Once construction is completed the office staff will be relocated to the new office building at 300 Middlefield Road.

The site will have a concrete apparatus driveway and 7 uncovered parking stalls. An existing Coast Redwood, that has significant defects and high risk of breakage, will be removed to allow for the apparatus driveway. A new Silver Linden will be planted as a replacement tree at the plan north-west corner of the site.





The existing building at 114 Santa Margarita was originally located at the corner of Middlefield & Willow, it was moved to its' current location in 1960, and greatly modified. The house was originally constructed in Classical or Colonial Revival style. The building is a box form with hipped shingle roof. The exterior is wrapped in horizontal lap siding. The front door is covered by a hipped shingle roof with pilasters. The building is very simple architecturally and does not have any prominent features. It is our opinion this building does not represent the work of a master or possess high artistic values.

Once the construction of new Fire Station #1 is complete, crew will move back there. The structures at the Temporary Facility will be moved at that time. The site will remain as parking for Menlo Park Fire Protection District until there are plans for future development, or the property is sold.

Purpose of Submittal

For this submittal, we are requesting review for Architectural Control, Heritage Tree Removal, Environmental Review, Zoning Amendment to P-F, Use Permit, Signage Review, and an amendment to the General Plan to allow 80% FAR.

A. Architectural Control

This project request Architectural Control to review the proposed buildings, design, site layout, etc.

B. Heritage Tree Removal

Due to the limited size of the site, it is necessary to remove all existing trees in order to develop the site to meet the needs of the Fire Protection District. The design team explored multiple site layouts to determine if it would be possible to retain any trees while still meeting the Fire District's needs. After a comprehensive analysis, it was determined the Fire District needs to re-develop the entire site. The Site Plan exhibit on AP1.2 demonstrates that all trees are in conflict with the proposed development of the site, making the removal of all trees mandatory. Please see alternate design and cost analysis for additional information.

The team paid special attention to retaining Tree #1. After investigation, it was ultimately determined it is not feasible to retain Tree #1. The arborist noted 15' clearance around the entire tree is required to protect its' existing structure. The clearance requirements around the tree does not allow for the (2) required storm





drain placement. The storm drain would need to be placed in the public right of way to avoid disrupting the tree, which is not allowed by the City.

There has been discussions with the City who have expressed desire to underground utilities along Santa Monica Ave. Recology has also expressed desire to underground the utilities so they do not provide a potential conflict with their service to the trash enclosure. The Fire District has agreed to underground (2) of the utility poles along Santa Monica. With needing to maintain the 15' clearance from the Saucer Magnolia #1, it wouldn't be feasible to underground the utilities without disrupting the tree. In addition, the tree and its' necessary clearances conflicts with building layout and design. Due to the restricting size of the site it is not feasible to relocate the portion of the proposed building that Tree #1 is in conflict with. The overhang of window shading impedes with tree canopy.

Please note that the Fire District intends to plant new trees within the planter area located south of the existing Saucer Magnolia. This landscaping enhancement will provide foliage along the Fire Station frontage and a more attractive streetscape for pedestrians and passersby on both Middlefield and Santa Monica.

At 114 Santa Margarita, we are requesting the removal of While reviewing the Arborist Report, tree #24 has a significant structural deficiency at the main trunk bifurcates into codominant leaders, this union is weak and there is a high risk of breakage. Even trying to address this defect would result in significantly affecting the trees height which will dramatically affect its appearance. This tree only has a moderate suitability for preservation. As a result, Menlo Park Fire Protection District believe it is best to remove the tree.

Tree #24 location impedes with the proposed Apparatus Drive aisle. Although the team has explored above grade paving to keep Tree #24 intact, the heavy weight of the apparatus driving daily over the roots may be impacted. Above grade paving is costly as it will require grade beams or piers. The above ground paving will also result in steep grades along the driveway which is not desirable.

As a result of the removal of Tree #24, a replacement tree will be planted on site, this project proposes the planting of a 36" Box Tilia tomentosa 'Sterling': Silver Linden. This new tree will be planted on the plan north-west corner of the site in an existing planter area.

C. Environmental Review

Since this project is not exempt from the California Environmental Quality Act (CEQA), it requires an Environmental Review. We respectfully request that the City retain an independent consultant to prepare an Initial Study for the project. Given that the





project involves an existing site currently occupied by Fire Station No. 01, we believe that the Initial Study will support the issuance of a Mitigated Negative Declaration. However, if the Initial Study determines that a Mitigated Negative Declaration is not appropriate, the project should proceed to the next applicable stage of the CEQA process in accordance with State guidelines.

D. Zoning Amendment

The current zoning does not align with project type or use. As part of this project we request for the property to re-zoned from R-1-S to P-F. The Fire Station and District Operation Center will be able to be accessed and utilized by the public and utilized to service the community. Since the project will be a public facility, this project requests a zoning amendment for this property to be zoned as PF, Public Facility, zone.

E. Use Permit

This project requests a use permit to allow for the use and storage of hazardous materials including a diesel emergency generator and large propane tank which will be utilized for training purposes by the Fire District. This project also requests a use permit to allow the maximum allowable floor area ratio to exceed the 60% FAR that is currently allowed by the Planning Commission Approval. This project requests to allow for 80% FAR. 60% FAR does not allow the Fire District adequate space to fulfill their current needs, 80% allows them to meet their current needs and allow for future growth in order to properly service the Menlo Park community.

Prior to the demolition of existing Fire Station No. 01 a temporary facility will be constructed at a different MPFD property, 114 Santa Margarita. This site will house temporary trailers and an App Bay tent. The facility will be utilized until the completion of the new Fire Station No. 01. This temporary facility is being submitted to the City and is included in this application.

F. Signage Review

This project is submitting proposed signage for the Fire Station and Administration Building, there will be no signage at the Training Tower. This project request review of signage and ultimately to receive a signage permit from the City.

G. Amendment to General Plan

As part of this project, we are requesting the property to be re-zoned to PF zone. Properties within the P-F zoning district are allowed: The floor area ratio shall not exceed thirty percent (30%), except that sixty percent (60%) may be allowed with





use permit approval on sites with a lot area of two (2) acres or less. In order to meet the needs of the Fire Protection District, FAR above 60% is required.

Due to the extensive programmatic needs of the Fire District to serve their community, approximately 75% FAR is required. This allows for a state of the art training tower to be utilized by the entire Fire District to train their staff and prepare for emergencies. The

height required of the Training Tower adds gross square footage to the FAR that is vital for the Fire District and their community members. Since this project will serve as a training center, administration headquarters, and Fire Station, ample space is needed simply to house and protect the Fire Apparatus. Substantial square footage is dedicated to Apparatus Bays which are vital for prompt emergency response.

This project is requesting an allowable FAR of 80%. This will allow the Fire District to construct the buildings they need to properly service the community. This will also allow for a small remaining percentage to allow for any necessary future growth.

The District explored options for keeping administration and/or fire prevention staffing at their current locations, however due to space limitations a significant renovation would be required along with a lot merger. The estimated cost to keep the office personnel at 170 Middlefield and 114 Santa Monica would exceed \$10 million and would not provide the needed space for growth. In addition, it is highly desirable to the Fire District to have all administrated personnel located at the same location with a preference to be at 300 Middlefield alongside the training division personnel.

Neighborhood Outreach

On 6/24/24 the Fire District met with representatives from Saint Patrick's Seminary including Father Doherty to discuss the Fire Station 1 project. The Fire District provided and discussed initial site plans and elevations. The discussion revolved around fencing, tree replacement, project phasing, and project duration. The project was well received by the representatives of St Patrick's Seminary. We discussed the District's plan for ongoing emergency response operations during construction and the possible placement of trailers on Saint Patrick's Seminary's property as well as replacement tree planting on their property to provide screening and to reduce noise. The Team has put together a package for St Pat's review and comment which includes, architectural, civil, landscape, and electrical site plans demonstrating the proposed temporary facility. The package also includes images and information for each of the tree species proposed to be planted on their property and options for fence design. Finally, the





package includes renderings of Fire Station No. 1 from the vantage point from St. Pats. St. Pats has reviewed the information provided and has provided their initial response which was included in a prior resubmittal.

In October 2025, a project flyer (previously provided in a prior planning submittal) and invitation was mailed to properties within a 700' radius. In addition, Staff went door to door and talked with several neighbors along Santa Monica Avenue. On November 10, 2025 the District held a neighborhood meeting at Fire Station 1 to present the project to the community and to obtain feedback from our neighbors.

Site Improvements

The site includes twelve secure parking spaces to accommodate the overlapping change of shift, along with five parking spaces for district owned trailers. Parallel parking will be available for public use along Santa Monica Ave. One accessible parallel stall is provided to the south of the Fire Station.

Underground parking can also be used by emergency personnel if needed. 76 total stalls (52 standard stalls, 3 accessible (1 EV), and 21 standard stalls) are provided underground for the office personnel and District vehicles, approximately 50 parking stalls are currently needed for staff. The remaining parking is available for board members, overflow and future growth. During public events the underground parking can be made available to the public in order to reduce offsite street parking. The new sidewalk along Santa Monica Ave is proposed to be located within the public right-of-way.

A new stationary generator would be located onsite in the middle of the lot which shall provide emergency power to all structures onsite in the event of a power outage. A new 1000-gallon above ground diesel fuel storage tank would be located adjacent to the emergency generator. The fuel storage tank would be used for refueling of fire engines and powering the generator. A second 1000-gallon unleaded fuel tank would be located adjacent to the diesel fuel tank for the fueling of the District's vehicles. The site would also include a 1000-gallon propane tank to fuel class B live fire training inside the training building.

To accommodate the construction of the new fire station, all 23 of the existing trees on the subject site are proposed to be removed. Twenty-one of the trees are classified as heritage trees and one is classified as a street tree. The tree inventory is comprised of





four American sweetgum, four coast live oaks, two little leaf linden, one north California black walnut, four Monterey cypress, seven olive tree, and one saucer magnolia. The trees to be removed would be replaced with new trees planted primarily along the street and property lines. Proposed trees to be planted include California buckeye,

American smoke tree, Deodar cedar, Canary island pine, Coast live oak, Cork oak, Fruitless Chinese pistache, Eastern redbud multi-trunk, California wax myrtle. Planted areas would be mulched and irrigated with a low volume irrigation system.

Construction Activities

Project construction is anticipated to occur over a four-and-a-half-year period, and the fire station would continue to operate throughout the construction process. Construction would be broken into the following seven major phases:

- Phase 1: Construct off-site temporary facility. Personnel to move out of fire station and into completed temp facility.
 - Estimated duration: 1 month
- Phase 2: Contractor to occupy site and demolish all existing buildings and site featured.
 - Estimated duration: 1 month
- Phase 3: Perform site grading and excavation
 - Estimated duration: 2 months
- Phase 4: Construct the underground parking garage
 - Estimated duration: 4 months
- Phase 5: Construct the new fire station, office/storage building and training building.
 - Estimated duration: 28 months
- Phase 6: Construct sidewalks, walkways, paving, landscaping, and install fuel tanks and generator.
 - Estimated duration: 2 months
- Phase 7: Move personnel into the new fire station, remove temporary structures, and complete site improvements.
 - Estimated duration: 2 months

END OF PROJECT DESCRIPTION



VICINITY PLAN

MENLO PARK FIRE STATION NO. 01

MENLO PARK FIRE PROTECTION DISTRICT

| ARCH SHEET INDEX | | |
|------------------|---|--|
| AP1 0 | COVER SHEET | |
| AP1.0 | AREA PLAN | |
| AP1.1 | SITE PLAN | |
| AP1.3 | SITE PLAN - LINDERGOLIND PARKING GARAGE | |
| AP1.4 | SITE DETAILS | |
| AP1.5 | PERSPECTIVE RENDERINGS | |
| AP1.6 | PERSPECTIVE RENDERINGS | |
| AP1.7 | PERSPECTIVE RENDERINGS | |
| AP2 0 | EXISTING FLOOR PLANS | |
| AP2 1 | EXISTING BUILDINGS | |
| AP3.0 | BLDG A - SQUARE FOOTAGE CALCULATION PLANS | |
| AP3 1 | BLDG B - SQUARE FOOTAGE CALCULATION PLANS | |
| AP3.2 | BLDG C - SQUARE FOOTAGE CALCULATION PLANS | |
| AP5.0 | BUILDING SIGNAGE | |
| AP6.1 | CONSTRUCTION PHASING PLAN 1-4 | |
| AP6.2 | CONSTRUCTION PHASING PLAN 5 & 6 | |
| AA2.0 | BLDG A - CODE ANALYSIS | |
| AA2.1 | BLDG A - FIRST FLOOR PLAN | |
| AA2.2 | BLDG A - SECOND FLOOR PLAN | |
| AA4.1 | BLDG A - ROOF PLAN | |
| AA5.1 | BLDG A - EXTERIOR ELEVATIONS | |
| AA5.3 | BLDG A - BUILDING SECTIONS | |
| AB2.0 | BLDG B - CODE ANALYSIS | |
| AB2.1 | BLDG B - BASEMENT | |
| AB2.2 | BLDG B - FIRST FLOOR PLAN | |

| AB2.4 | BLDG B - SECOND FLOOR PLAN |
|-------|------------------------------|
| AB4.1 | BLDG B - ROOF PLAN |
| AB5.1 | BLDG B - EXTERIOR ELEVATIONS |
| AB5.3 | BLDG B - BUILDING SECTIONS |
| AC2.1 | BLDG C - BASEMENT-3RD FLOOR |
| AC2.2 | BLDG C- 4TH-ROOF PLAN |
| AC5.1 | BLDG C - EXTERIOR ELEVATIONS |
| AC5.2 | BLDG C - BUILDING SECTIONS |
| | |

| | INDEX TEMPORARY FACILITY |
|---------|---|
| | INDEX TEMI OTART FAGILITY |
| TF1.0 | TEMP FACILITY DEMO & PROPOSED SITE PLAN |
| TF2.0 | TEMPORARY FACILITY DETAILS |
| TF-C1 | CIVIL - TEMPORARY FACILITY |
| TF-E0.1 | GENERAL NOTES, SYMBOL LIST, FIXTURE SCHEDULE, SINGLE LINE DIAGRAM AND PANEL SCHEDULE |
| TF-E0.2 | TITLE 24 COMPLIANCE FORMS |
| TF-E1.1 | SITE POWER PLAN |
| TF-E1.2 | SITE LIGHTING & PHOTOMETRIC PLANS |
| TF-E3.1 | ELECTRICAL DETAILS |

| C1.0 | COVER SHEET | |
|-------|-------------------------------|--|
| C2.0 | BOUNDARY & TOPOGRAPHIC SURVEY | |
| C3.0 | DEMOLITION PLAN | |
| C4.0 | SITE DEVELOPMENT PLAN | |
| C5.0 | GRADING & DRAINAGE PLAN | |
| C6.0 | GRADING & DRAINAGE PLAN | |
| C7.0 | CROSS SECTIONS | |
| C8.0 | UTILITY PLAN | |
| C9.0 | STORMWATER CONTROL PLAN | |
| C10.0 | CONSTRUCTION DETAILS | |
| C11.0 | EROSION CONTROL PLAN | |
| C12.0 | BEST MANAGEMENT PLAN | |

| INDEX LANDSCAPE | | |
|-----------------|-------------------|--|
| 110 | TREE REMOVAL PLAN | |
| L1.1 | PLANTING PLAN | |
| L2.0 | IRRIGATION PLAN | |
| | | |
| | | |
| | INDEX ELECTRICAL | |

| E1.0 | DEMO & NEW SITE PLAN | | | |
|------|--------------------------------------|--|--|--|
| E1.1 | SITE PHOTOMETRIC PLAN | | | |
| E1.2 | STREET LIGHTING PHOTOMETRIC PLAN | | | |
| E1.3 | CITY STANDARD AND FIXTURE DATA SHEET | | | |
| | | | | |



MENLO PARK FIRE STATION NO. 01 & TRAINING TOWER

MENLO PARK FIRE PROTECTION DISTRICT










| | DATE | PROJECT | |
|-------|---------------|----------|-------|
| | 4/24/25 | 230532 | |
| | ING HISTORY | | |
| No. | Descrip | tion | Dat |
| | | | |
| _ | | | |
| | | | |
| _ | | | |
| | | | |
| | | | |
| PL | ANNING DEPART | MENT SUB | MITTA |
| BUILD | ING NUMBER | | |
| | COVER | SHEE | Т |










C4





AERIAL VIEW



WEST VIEW FROM MIDDLEFIELD ROAD

PBK

ARCHITECT SAN LUIS OBISPO PBK,
127 Archar St, Suita 110
San Luis Obispo, CA 93401
805-229-3376 P

MENLO PARK FIRE STATION NO. 01 & TRAINING TOWER

MENI DOOD THEILD SOO WINDOW











MENLO PARK FIRE STATION NO. 01 & TRAINING TOWER MENLO PARK FIRE PROTECTION DISTRICT







| L | | | |
|-------|------------------------|------------------|----------|
| MENI | CLI O PARK FIRE PI | ENT ROTECTION | DISTRICT |
| | DATE 4/24/25 | PROJECT 230 | |
| No. | ING HISTORY Descrip | tion | Date |
| | | | |
| | | | |
| | | | |
| PL | ANNING DEPAR | TMENT SUB | MITTAL |
| BUILD | ING NUMBER | | |
| | PERSP RENDE | | _ |



VIEW FROM SANTA MONICA AVE OF DISTRICT OPERATIONS CENTER





BUILDING B - ENTRY FROM MIDDLEFIELD



NORTH-EAST VIEW FROM MIDDLEFIELD ROAD



ARCHITECT PB SAN LUS OBISPO 1327 Archar St, Suite 110 San Luis Obispo, CA 93401 805-322-3076 P 805-329-3078 F

MENLO PARK FIRE STATION NO. 01 & TRAINING TOWER


MENLO PARK FIRE STATIO







| = | | | = | | | |
|----------------|-------------------------------------|----------|--------|--|--|--|
| | CLI | | _ | | | |
| MENL | IENLO PARK FIRE PROTECTION DISTRICT | | | | | |
| | DATE | PROJECT | | | | |
| | 08/30/2024 | 230 | 532 | | | |
| | ING HISTORY | | | | | |
| No. | Descrip | | Date | | | |
| 2 | PLANNING DEP'T C' | rCLE 2 | 5/7/25 | | | |
| | | | | | | |
| | | | | | | |
| _ | | | | | | |
| | | | | | | |
| | | | | | | |
| PL | ANNING DEPART | MENT SUB | MITTAL | | | |
| BUILD | ING NUMBER | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| PERSPECTIVE | | | | | | |
| FEROFECTIVE | | | | | | |
| RENDERINGS | | | | | | |
| ILLINDEILLINGO | | | | | | |
| | | | | | | |



MENLO PARK FIRE STATION NO. 01 & TRAINING TOWER MENLO PARK FIRE PROTECTION DISTRICT





| DATE 4/24/25 | | PROJECT NUMBER 230532 | | | |
|-------------------------------|-----------------|--------------------------|------|--|--|
| | DRAWING HISTORY | | | | |
| No. | Descrip | tion | Date | | |
| | | | | | |
| | | | | | |
| _ | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| _ | | | | | |
| PLANNING DEPARTMENT SUBMITTAL | | | | | |
| BUILDING NUMBER | | | | | |
| EXISTING FLOOR | | | | | |

PLANS

AP2.0

EXISTING MENLO PARK FIRE STATION NO. 01 TO BE DEMOLISHED - WEST ELEVATION



EXISTING MENLO PARK FIRE STATION NO. 01 TO BE DEMOLISHED - SANTA MONICA ROAD ELEVATION. (EAST ELEVATION)



EXISTING MENLO PARK FIRE STATION NO. 01 TO BE DEMOLISHED - MIDDLEFIELD ROAD ELEVATION, (SOUTH ELEVATION)



EXISTING MENLO PARK FIRE STATION NO. 01 TO BE DEMOLISHED - NORTH ELEVATION (REAR)







EXISTING MENLO PARK MAINTENANCE BLOG TO BE DEMOUSHED. WEST ELEVATION.

STRING MENLO PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTING MENLO PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTING MENLO PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTING MENLO PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTING MENLO PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTING MENLO PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTING MENLO PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTING MENLO PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTING MENLO PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTING MENLO PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTING MENLO PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTING MENLO PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTING MENLO PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTING MENLO PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTING MENLO PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTING MENLO PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTENCE PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTENCE PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTENCE PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTENCE PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTENCE PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTENCE PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTENCE PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

EXISTENCE PARK MAINTENANCE BLOG TO BE DEMOUSHED. SANTA MONICA ROAD ELEVATION.

E



EXISTING MENLO PARK MAINTENANCE BLDG TO BE DEMOLISHED - ELEVATION (NOR





EXISTING MENLO PARK FIRE STATION NO. 01 & MAINTENANCE BIULDING TO BE DEMOLISHED - SANTA MONICA ROAD ELEVATION (EAST SIDE)





C2

MENLO PARK FIRE STATION NO. 01 & TRAINING TOWER

MENLO PARK FIRE PROTECTION DISTRICT

AP2.1













BUILDING B SIGN AT SANTA MONICA AVE




ADDRESS NUMBER AT SANTA MONICA AVE



BUILDING B - EXTERIOR ELEVATION EAST SIGN




ADDRESS NUMBER AT MIDDLEFIELD RD



SIGN AREA SUMMARY

44 SF 22 SF 18 SF 10 SF 4.4 SF 0.8 SF 0.8 SF

LED FIRE STATION SIGN AT MIDDLEFIELD RD






MENLO PARK FIRE STATION NO. 01 & TRAINING TOWER MENLO PARK FIRE PROTECTION DISTRICT





AP5.0


BUILDING SIGNAGE


CHECKED BY: Checker DRAWN BY: Author PLOT STAMP: 8/20/2025 2:57:45 PM




























































GENERAL NOTES

- THE CONTRACTOR SHALL THESE ALL LISE AND LOU VIO AND EMERTING REPORTS THE EXPENSION FOR THE EMERSTRAND RECORDS AND THE EMERSTRAND RECORDS AND THE EMERSTRAND RECORDS AND THE EMERSTRAND RECORDS AND THE EMERSTRAND REPORT OF THE EMERSTRAND REPORT AND THE
- THE CONTRACTOR SHALL SECURE AND PAY FOR PERFITS AND FEES NECESSARY FOR EXECUTION AND COMPLETION OF ELECTRICAL WORK, INCLUDING ALL CHARGES BY THE LOCAL
- ALL OUTLET LOCATIONS SHALL BE COORDINATED WITH ARCHITECTURAL ELEVATIONS PRIOR TO INSTALLATION.
- THIS CONTRACTOR SHALL SUPPLY POWER TO AND MAKE CONNECTION TO ALL MOTORS AND EQUIPMENT REQUIRMS ELECTRICAL CONNECTIONS AS SHOWN ON THE PLANS.
- EXACT LOCATION OF ALL CEILING MOUNTED DEVICES SHALL BE AS INDICATED ON THE ARCHITECTURAL REFLECTED CEILING PLANS.
- INLESS OTHERWISE NOTED, MOUNTING HEIGHTS INDICATED ON ELECTRICAL OUTLETS ARE FROM MINISHED PLOOR TO CENTER OF OUTLETS.
- THE CONTRACTOR SHALL BE RESPONSIBLE FOR CUT-OUTS IN TILE OR COUNTER SPLASHES WHERE RECEPTACLES, OUTLETS, ETC., OCCUR.
- ALL RECESSED DEVICES, ETC, MOINTED IN FIRE RATED CEILING SHALL BE ENCLOSED WITH AN APPROVED ENCLOSURE CARRYING THE SAME FIRE RATING AS THE CEILING. THE CEILING.
- ALL SURFACE MOUNTED LIGHTING FIXTURES SHALL BE APPROVED FOR DIRECT MOUNTING ON LOW DENSITY COMBUSTIBLE CEILINGS.
- THE INPERFAUL(8) SHOWN AT TOP LIGHT FIXTURE IDENTIFICATION SYMBOL UHICH NOICATES NAMBERS OF LIGHT FIXTURES REQUIRED SHALL NOT BE USED BY THE CONTRACTOR OR HIS GUARNITY JAMESOW AT BODDING OR FOR DETERMINATION OF HOU HANY PIXTURES UILL BE NOTALLED. THE CONTRACTOR SHALL NOTALL A LIGHT FIXTURE UHERBEYER A FIXTURE CHILD IN SHOULK OF DEALINGS.
- NO CONDUIT SHALL BE RUN HORIZONTALLY IN CONCRETE FLOOR SLABS.
- ALL FINAL CONNECTIONS TO OWNER-PURNISHED EQUIPMENT SHALL BE MADE BY THE CONTRACTORS.
- B. EQUIPMENT ANCHORAGE NOTE

ALL ELECTRICAL EQUIPMENT SHALL BE ANCHORED OR BRACED TO MEET THE HORIZONTAL AND VERTICAL PORCES PRESCRIBED IN THE 2022 CBC.

THE ATTACHMENT OF THE FOLLOWING ITEMS SHALL BE DESKINED TO RESIST THE FORCES PRESCRIBED ABOVE, BUT NEED NOT BE DETAILED ON THE PLANS:

- A. EQUIPMENT WEIGHING LESS THAN 400 POUNDS SUPPORTED DIRECTLY ON THE FLOOR OR ROOF.
- B. EQUIPMENT WEIGHING LESS THAN 20 POUNDS SUPPORTED BY VIBRATION ISOLATORS.
- C. EQUIPMENT WEIGHING LESS LESS THAN 20 POUNDS SUSPENDED FROM A ROOF OR FLOOR OR MINIS FROM A MAIL!
- THE CONTRACTOR SHALL YISH THE SITE INCLUDING SPECFICALLY ALL AREAS INDICATED ON THE DRAWINGS, HE SHALL THORAUSHLY FAMILLARIZE HIMSELF WITH THESE EXISTING CONDITIONS AND BY SUBMITTING A BID ACCEPTS CONDITIONS UNDER WHICH HE WILL BE REGUIRED TO PRIPROPET HIS WORK.
- IT SHALL BE THIS CONTRACTOR'S RESPONSIBILITY TO DO ALL CORNS, CUTTNS, PATCHNS AND REPNISHING OF WALLS AND SURFACES WHEREVER IT IS NECESSARY FOR HM TO PENTRAITE FOR BUDGES, ALL OPENINGS MADE SHALL BE SEALED TO MEET THE RATED INTEGRITY OF THE PARTICULAR WALL, FLOOR OR CEILING.
- ATTENTION IS CALLED TO THE PACT THAT THE CEILING SYSTEMS FOR THE MOST PART ARE CONSIDERED TO BE NACCESSIBLE. THE CONTRACTOR SHALL STRATEGICALLY LOCATE BOXES, ETC., IN AN ACCESSIBLE CEILING SPACE.
- WHERE EXPOSED CONDUIT IS PERMITTED BY THE ARCHITECT, SUCH CONDUIT SHALL BE PAINTED TO MATCH FINISH OF SURFACE TO WHICH IT IS ATTACHED/SUPPORTED TO.
- IS. NOTALL RACEURY SYSTEMS AS FOLLOUS:
 - A. RIGID GALVANZED STEEL IN ALL OUTDOOR LOCATIONS AND IN INDOOR LOCATIONS WHERE SUBJECT TO PHYSICAL DAMAGE.
- B. IMC. OR EMT. N ALL INDOOR AREAS.
- C. FLEXIBLE METAL CONDUIT FOR FINAL CONNECTIONS TO LIGHT FIXTURES, MOTORS, VIBRATING ELECTRICAL EQUIPMENT AND HORIZONTAL RUNS IN WOOD STUD WALLS.
- D. PVC CONDUIT FOR UNDERGROUND RUNS, USE 26 MIL PVC TAPED RIGID STEEL RISER ELBOUS AND RISERS FOR CONDUIT STUB-UPS.
- E. USE COMPRESSION TYPE FITTINGS FOR ALL METALLIC CONDUIT
- F. I' CONDUIT MINIMUM FOR UNDERGROUND INSTALLATIONS.
- CONDUIT ROUTING NDICATED ON THE PILANS IS DIAGRAPHATIC, ACTUAL ROUTING OF CONDUITS SHALL BE COORDINATED IN THE FIELD TO AVOID INTERFERENCE BITH OTHER UTILITIES AND READES. THE CONTRACTOR SHALL INSTALL ALL CONDUIT, JUNCTIONPILL BOXES, ETC., AS REQUIRED FOR A COMPLETE SYSTEM IN FILL COMPLIANCE WITH ALL APPLICABLE CODES.
- ALL EXTERIOR MOUNTED EQUIPMENT SHALL BE WEATHERPROOF OR PROVIDED IN A
- ALL POWER AND LIGHTING BRANCH CIRCUITS SHALL BE INSTALLED WITH A "12 GREEN GROUND WIRE UCN. THE COMPLETE ELECTRICAL SYSTEM SHALL BE GROUNDED IN ACCORDANCE WITH ARTICLE SOO OF THE CALL PORNIA BLEICHICAL CODE (CEC).
- IDENTIFICATION NAME PLATES FOR BRANCH CIRCUIT PANELS SHALL MATCH THE NOMENCLATURE PROVIDED BY THE OWNER AT THE END OF THE CONTRACT.
- UNLESS SPECIFICALLY SHOWN ON THESE PLAYS NO STRUCTURAL MEMBER SHALL BE CUT, DRILLED, NOR NOTCHED WITHOUT PRIOR WRITTEN AUTHORIZATION FROM THE STRUCTURAL



SINGLE LINE DIAGRAM NOTES

- METERMAN PANEL SHALL BE SCE AND BUSERC COMPLIANT, AS MANUFACTURED BY SQUARE-D OR EQUAL EATON OR SEMENS.
- 2) ALL EQUIPMENT SHALL BE LISTED BY UL. OR A CITY APPROVED THRO PARTY TESTING PACILITY.
- THE BULDING PANELS ARE PROVIDED BITS THE BULDINGS THE BULDINGS THE CONTROL OF THE PANELS AND DETERMINES THE CONTROL OF THE PANELS REQUIRED TO ROUTING THE CONDUIT AND UNREL TREPNANTICS REQUIRED THE PANEL OF THE REPORT THE RECORD CONDUITS. THE CONTRACTOR WHILL NOTIFY THE ARCHITECTSWANDER OF ANY DISCREPANCES AND OSTAN THE ARCHITECTSWANDER OF ANY DISCREPANCES AND OSTAN THE MOST THE ARCHITECTSWANDER SERVE PROCEEDING WITH THE MOST THE MOST THE MOST THE ARCHITECTS WAS THE MOST THEMOST THE MOST THE MOST



REFER TO RESIDENTIAL LOAD CALCULATION

| Trinspers Traffer Famil 6. | | |
|--|-----|-------|
| | | |
| 1. General Agleng Lovers | | |
| tige of lasting EDVO to R (see 1911 from 1911 ff) | | 144 |
| Laureite Clean's per CEC/20 KS Ex | -1- | 77. |
| A V Million | 4 | 164 |
| most Ayerson o Drugs sont gar (AT) little file as | | |
| T. S. Steller | | - 153 |
| The second of th | | 100 |
| Application of Directors Passing one CAT 201-10) | | |
| First 800 of Lake of Fdths | | 103 |
| Park SDF to 199,000 at NWS. Statement over 101 till at 2016 | | 161 |
| Total for \$1 | | - 11 |
| CONTROL OF THE PARTY OF THE PARTY. | | |
| L. Formation only Constitution Agent region. | | |
| F. R 8245 | | |
| Remote Address v. 278 Per SEC 200 MI | | 100 |
| Proper Street. | | |
| Demoid 8 HB A V C TO Fee COLD DOCKS | - | 111 |
| Religi | | |
| C. 6. 00000 | | |
| Secret Colors | | *** |
| PROGRAMME TO THE REAL PROPERTY. | | |
| Service Extend of Service Labor. | | 111 |
| Digity | | |
| Fig. State 14 | | |
| Service Present | 100 | 1.01 |
| I a Mid-laik | | |
| Server Edition Chrycle 28 St | + | 141 |
| law or et | | 0.00 |
| E. Luelo et 1979. | | |
| 7 s 1980 hA | - | 10.11 |
| Train in 49 | | 18.65 |
| ACCOUNT OF THE PARTY OF THE PAR | - | ates |
| Tired Tresposed Liver (VIII) | | |

ELECTRICAL SYMBOL LIST

CONDUIT RUN, CONCEALED IN CEILING, WALLS OR UNDER FLOOR 3/4" MIN. - - - CONDUIT RUN, UNDERGROUND.

PLEXIBLE CONDUIT, SEALTITE WHERE EXPOSED TO WEATHER, REFER TO SPECIFICATIONS FOR USE.

- CONDUIT TURNED DOWN O CONDUIT TURNED UP.

CROSS LINES ON CONDUIT RUNS INDICATE NUMBER OF 1/2 WINES CONTAINED
THEREIN. TWO 1/2 ARE INDICATED WHEN CROSS LINES ARE NOT SHOWN
NUMBERALS ADJACENT TO CROSS LINES ON CONDUIT RUNS INDICATE SIZE OF
CONDUCTORS IN LIBIT OF 1/2.

B-1,3 T CONDUIT HOME RIN TO PANELBOARD, LETTER AND NUMERALS NDICATES ELECTRICAL PANEL AND CIRCUIT NUMBER

A)

_ ERANCH CIRCUIT PANEL MOINTING AS SUGIN ON SCHEDULES

___ CIRCUIT BREAKER, REFER TO SINGLE LINE DIAGRAM.

DZ LED LIGHT FIXTURE, SHADING INDICATES FIXTURE TO BE PROVIDED WITH WITH INTEGRAL 90 MINUTE EMERGENCY BATTERY PACK.

EXISTING EQUIPMENT TO REMAIN.

DUPLEX RECEPTACLE, FLUSH IN WALL, GROUNDING TYPE (30 AMP, 120V., WALL PLATE TO MATCH DEVICE) MTD, AT 48".

DW - 3,4°C, UTH 2/0°6 CLASS 2 DATA URRE PER SUTCH LEG (DPMINS CONTROLS);

QUANTITY OF OROSS TICKS REPRESENT QUANTITY OF SUTCH LEGS UTTAIN CONDUITS.


CEILING MOUNTED JUNCTION BOX. Q,

0 EMERGENCY EXIT SIGN.

Dis 9-19V DIMER SUTCH, LETTER NOICATES SUTCH LES CONTROLLED BY DIMER NOCEL SPODINO-III OR EQUAL

FIRE ALARM SYSTEM DEFERRED APPROVAL NOTE

THE FIRE ALARM SYSTEM DRAWNOS SHALL BEAR THE STAMP AND SIGNATURE OF A STATE OF CALIFORNIA PROFESSIONAL ELECTRICAL



















| | CLIE | | , |
|------|--------------------|----------------|--------|
| IENL | O PARK FIRE PR | | |
| _ | DATE 08/22/2024 | PROJECT 230 | |
| | | 230 | 332 |
| | NG HISTORY | | |
| No. | Descript | tion | Date |
| | | | |
| - | | | |
| | | | |
| | | | |
| _ | | | |
| | | | |
| PL | ANNING DEPART | MENT SUBI | MITTAL |
| ULDI | NG NUMBER | | |
| | GENERAL | | |

SCHEDULE, SINGLE PANEL SCHEDULE

TF-E0.1

| | majo i dajdari elit dagoni majorido e i dei estrolo maj dei tipologico di | my take the tell time. | Land of Little Call Annual Contracts when a table Call Code (18 contract) to price thing profess | and using the property or digit the branch for survivor bytes, | MAC US |
|--|--|--|---|--|-------------------------------|
| ages flame than be less for | troj kaj kontar singentis. Nasio Perfere II | suffered values describe | mi anter Airy profess n fage | HDC-00423775 | Step Let |
| Sec Mess | | Interview See | Name of Street | | 811.00 |
| District interests | | 10,512 | | · · | |
| ME CHARLON | Specia fluite | | Test Statement Ferbiage by N. N. | RCF | |
| Consecution (and purpose of the Consecution of the | and Publish St 2 t Modern | this building from the Course | about most. LCA high throater extended by CA As | ngs Tomories for Appendi | |
| C Country Name and Co. | T 24 Volen | to right Arthur Arthur | | | |
| C State for time C State of the office of Control formatters | | | | | |
| | | | | | _ |
| NAME AND ASSESSED. | the arters from the author three | or of the print and the ter- | en e-markouple au | representative a | 9000 |
| 76 February Columbia (* 1861) As Tempor Columbia (*) | SACELY SPERIORS | | | | |
| | i in | s Cample with differences from | MET/175.7mS | | - |
| C Merel lastic fee | - 10 | or division for the last | months by by March | - | |
| 6.0734000 | ers to a construction of the construction of t | See Television of Lawrence & | ing Addat of Marks | (situación libritat | |
| Very money life I do | BIST LISTING WINGS SCHOOL TO | spin Humani announce. | | | |
| STREET, S. S. STREET, S. | ninder brightner dan bes | of concession the light habiture | the same of the sa | may of the Street Assessment | 4 140. |
| | | | | | |
| | | | | | |
| | | 200400 | artes | dicutement has | in tops |
| Name I and the second | | - Auction | 200,00 | Dealtrick house | |
| | | - | | | |
| Duratur Lighting | | | | Occupies to the | FERVER |
| SANTAN DE L'ANGEANGE SANTAN DES PROPERTS | energy bearing | 100 | nilige: | 1000000 | 1881-65 |
| | | The | Preprint. | | Pg-141 |
| | | | | | |
| C SHILLING HOLD HOLD TO SHILL HE WAS A SHILL HOLD TO SHILL HE WAS A SHILL HE WAS | 0.816 | | | | |
| Contract Lance | eranno. | | | | |
| A NO. SO STREET SHELD | erapes en 2 milio 2 mpost majoritativo A | PERSONAL PROPERTY. | A STATE OF THE STA | To other programme, the | ma with pa |
| To high Security of pro- | died consist states et cent | | produced to be below to the rate of | ela Appliacionale per dan | a comment (s) |
| A time follow by the resemble | distillated por parting programs of explicit Perfections of Colonies | Accompany on the parties, in reality and | their widely marks mannered to | THE PERSON NAMED IN | entert |
| People are forcists to the or | r phrillio Thousannin, Perfora Co Co | Sand Street, Street, Street | Floridy Staffelings | 1 - | |
| | | Northwe | | Anies | - |
| - AND PERSONAL | WHAT (80.00) | 30900000 (8003(/8096) | 101/W(1909) | Tax (| fer |
| Autima Manuscriptor | Promotes | Person | White terminals in 10 ther | - 1 | 1.0 |
| hatting beautiful trace | Property. | Secretar | nome | 9 | |
| Note May come of Vision (III) | Manager of the Landson | feetal | Polisi | . 9 | |
| | as Example 1 | | ufine DELANG | Strangers of Angels for the Parket Strangers of Angels o | |
| | | 3.77 | | | |
| erous mag. | | | | OWEN DO | |
| Autoloor lighting: | | | | | 0.0000000 |
| Antion lighting principle (MA HEZ | MANAGEMENT AND ADDRESS OF THE PARTY AND ADDRES | Per Per | rites | *************************************** | MET PT |
| Author lighting syntax or continued nerthern decisions | MANAGEMENT. | . His basis is a garen ber plan | ritge Amend | | MCPS POINT POINT |
| Audior Upling Proce or DMA 462 1661 feet 1660 | TO DECLARATION (ARTHURS) | | n hee | | ME PS |
| Author dighting system to come | s Deculations themselved | Loston will rangicle. | | | MC FS Page 14 FG MI |
| Outdoor Ughting printing or DAN well rest from rest little. | n Occupation presents | Lucion and projects. | | | MC FS |
| Outdoor Ughting printing or DAN well rest from rest little. | n Occupation presents | Scotcook and lampice. | | | MCFS Politi |
| Outdoor Ughting printing or DAN well rest from rest little. | TO COLUMN TO THE PROPERTY OF CONTRACT OF C | leases and samples. | | | MIC PS Page 181 PS LIMI |
| Outstand Spiritery Controlled to USAN Medical Controlled Spiritery Contr | TO DECUMENT OF COMMENTS of Considering decumentation of Considering decumentation of Considering decumentation of Considering deciments of Conside | leases and samples. | 611 611 611 611 611 611 611 611 611 611 | e | 20110 |
| Author Uphting Windlife to India and Insert term On Little Major Instruction On Little Major Instruction On Little Major Instruction On Little Major Insert I | TO DECUMENT OF COMMENTS of Considering decumentation of Considering decumentation of Considering decumentation of Considering deciments of Conside | Least and temples. | 611 611 613 State of | e | 20110 |
| Author Uphting Windlife to India and Insert term On Little Major Instruction On Little Major Instruction On Little Major Instruction On Little Major Insert I | TO DECUMENT OF COMMENTS of Considering decumentation of Considering decumentation of Considering decumentation of Considering deciments of Conside | Least continued interpretation of the continued interpretation | COLUMN TO THE PROPERTY OF T | | 20110 |
| Analos digitare, common digitare del mentione del controlle del mentione del mentio | TO COLUMN TO THE PROPERTY OF CONTRACT OF C | Least continued interpretation of the continued interpretation | And the second s | | 20110 |
| Outdoor sighting promotes to such water separate and seek to the superior seek to such dates to such | TO DECUMENT OF COMMENTS of Considering decumentation of Considering decumentation of Considering decumentation of Considering deciments of Conside | List teach and languish. | AND THE PROPERTY OF THE PROPER | | 20110 |
| Anabor sighting commone in Columbia (1974) and the col | TO DECUMENT OF COMMENTS of Considering decumentation of Considering decumentation of Considering decumentation of Considering deciments of Conside | is asknown and immediate. | SECTION OF THE PROPERTY OF THE | | 20110 |
| Outdoor sighting permitted in the service of the se | TO DECUMENT OF COMMENTS of Considering decumentation of Considering decumentation of Considering decumentation of Considering deciments of Conside | locations and removals. | Section 1991 | | 20110 |
| Anabor sighting commone in Columbia (1974) and the col | TO DECUMENT OF COMMENTS of Considering decumentation of Considering decumentation of Considering decumentation of Considering deciments of Conside | locations and removals. | SECTION OF THE PROPERTY OF THE | | 20110 |
| Outdoor sighting permitted in the service of the se | TO DECUMENT OF COMMENTS of Considering decumentation of Considering decumentation of Considering decumentation of Considering deciments of Conside | locations and removals. | Section 1991 | | 20110 |
| Andoor sighting connected to cold wide seed here. Seen to the seed here to see the seed here. See the seed here to see the seed here. See the seed here to see the seed here. See the seed here to see the seed here. See the seed here to see the seed here. It is not seen to see the seed here. It is not seen to see the seed here. It is not seen to see the seed here. It is not seen to see the seed here. It is not seen to see the seed here. It is not seen to see the seed here. It is not seen to see the seed here. It is not seen to see the seed here. It is not seen to see the seed here. It is not seen to see the seed here. It is not seen to see the seed here. It is not seen to see the seed here. It is not seen to see the seed here. It is not seen to see the seed here. It is not seen to see the seed here. | TO DECUMENT OF COMMENTS of Considering decumentation of Considering decumentation of Considering decumentation of Considering deciments of Conside | locations and removals. | Section 1991 | | 20110 |
| Anabor Sighting sometime to real water seed feet to the seed to th | TO DECUMENT OF COMMENTS of Considering decumentation of Considering decumentation of Considering decumentation of Considering deciments of Conside | locations and removals. | Section 1991 | | Section Section 1 |
| Outdoor Sighting Franchise to Down and Territoria to Down and Terri | TO DECUMENT OF COMMENTS of Considering decumentation of Considering decumentation of Considering decumentation of Considering deciments of Conside | In subseque will immediate the subsequence of the s | He is a second of the second o | Security of the security of th | |
| Andron Elgister The Provide Developed and the second and the seco | To OCCUPATE AND ADMINISTRATION OF THE PROPERTY | is stronger and immediate and | He is a second of the second o | | |

icrolumo.

| Service Control Contro | | | | | | | THE PERSON NAMED IN | eno posenor- | Distribution (in | Nine | | | | |
|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|
| Comparison of the Parison of the Comparison of | SWINDS O'COMMAN | | | | | | - Chillian | 1602 254 | piereomoro: | SWILLIST . | | | | |
| CONTINUE CON | MACE NOT BE SEEN IN THE PARTY OF THE PARTY OF | | | Appel Regis | | | | physics to | PATES. | Non-bull backet b | NAME OF | | | 100 |
| Column C | | | | | | | | Arterior . | | | | | | - |
| Construction (Construction) The state of th | | | | | | | | | S-20000000 | DETERMINED OF THE LEFT | APNOO | | | _ |
| The content of the content is a proper of the content in the content is a proper of the content in the content is a proper of the content in the content is a proper of the content in the content is a proper of the content in the content is a proper of the content in the content is a proper of the content in the content is a proper of the content in the content is a proper of the content in the content is a proper of the content in the content in the content is a proper of the content in the con | | | والمراول والمادان | | | - | - | | For advantished | of Participal Laboratory Street | and the section | receive ME-C/ | 27.1 (m) of m | er her |
| ### 15 Part | e Tara it Angelowi Gerbina (C. pulline a se | n marketing faller, while | ment being | | | | ALC: NAME OF PERSONS | or Cardinate Mari | District and the | distribut formune in the | recreated the first had been a | I safety makes to | personal mobile | 0.50 |
| Part | Editorium of Total Allegan (agenty) inc. | e interpretation | Just or Coll. No. | | | | | | States triing | accordents mattering | NAMES AND ADDRESS. | mine Strict. | okt ill i prin | - |
| STATE OF THE PROPERTY OF THE P | March 1 | 1 | | 1 1 1000 | | - | - | - | CHORSES RATIO | | | _ | | |
| 1985 | Account to the same of the sam | + Selected | - 444 | P. 1. 1944 | | imme (| THE REAL PROPERTY. | | - " | - 11 | _ | 1 10 | - 17 | \vdash |
| Subsequence (and the control of the following) 1. (Control of control of the control of the following) 1. (Control of control of the contro | SECRETAL SEC | 1 (N. 0+H) (N+1+H) | TER (Sect.) | 38.50 | 100 | nesi I | Person | 110111111111111111111111111111111111111 | 34 | toname ex | | | WANT. | 1 |
| SOLUTIONS CONTRIBUTIONS SECURITION OF CONTRIBUTION OF CONTRIB | | | | | -0 - | 202 4 | 18 | | | | | | | |
| ## Section Committed Commi | | Committee Completion 1 | the labour to her t | MARINE . | | | | | - 14 | Best | Disease | (11 | 30.000 | |
| The control of the control control beauty control to the control of the control o | Tourse Course Course | | | - 1 | | | | - 1 | - 14 | 194.05 | Direc | 39 | 46,546 | |
| ## Committee of the control of the c | | | | e annua | 2000000 | | | | | 2+0 | Sine | . # | 97,341 | |
| Part | THE RESIDENCE OF THE PERSON SHAPE IN | CHINA | | | and all like | | | | | 0+0 | Dien | - 60 | m 501 | |
| April Committee Committe | | | | | | | | | | | - | | | |
| The first product of the control of | trace and control through | And in contrast of the | tering biristerine | | | | | - | Er compression | richelle al morror de como. Pierre a solonie lastrativos | S IN LINE SEE | - | | |
| Application Comment | | | | | | | | | Processors 444 | jek darlag manifesis | that design in the | 11/100 | | - |
| Additional Content of the Content | | | | | | | | | October 54-90 | the sections wheat \$4 me | and his facility restricts | er much een | - 144 times | - |
| ## Secretary Comment of the Comment | | | | | | | | | | the second live in | eput alphore proper | CONTRACTOR OF | MATERIAL STREET, STREE | AND DESCRIPTION OF THE PERSON NAMED IN |
| ## Comment of the Com | | | | | | | | | to yourse week. | | | | | |
| The first income different income different income and all treatments and all treatments are all treatments and all treatments are all treatments and all treatments are all treatments | | | | | | | | | Department and | - | | - Seminar and | - | - |
| The first income different income different income and all treatments | | | | | | | | | | | | | | |
| The first income different income different income and all treatments | | | | | | | | | | | | | | |
| Charles (Spring) Charle | | | ** | constant. | | | Assessed | other treate | | | | | 9491 | - |
| A CONTROLLED CONTROLLE | Ottobackery Parcel Sensor Michigan | risk beneficies | Suite | **** | | - 1 | made at the land | Automobile) | Otherhadien | Charles Inches | Characterist to | marks in | Stone | - |
| Affect (spilling) Affect (spill | | | | | - | | - | | | | | | | |
| ## Comment of Comment | | | | | | | | | 246034000 | 000 | | | | |
| Interface county ALLIANORS per 2443 / VEX.NEW Interface county ALLIANORS p | | | | | | | Grown | MANY COMMITTEE STATE | | | | | | _ |
| Part | | | | Report Page | | | | 104014411 | | | Descript | | | 744 |
| A page of the part of the page of the pa | | | | See Present | | | | 937404 | | | | | | Table |
| A page of the part of the page of the pa | | | | | | | | | | | | | | |
| Section Control Cont | LEAFER POWER ALDIANCE (#128137) | TEANS. | | | | | | - | BURNALE | PROGRESSION OF | electronic control | | | |
| Section 2 of the 16 ft | | CHECKET AND TO A PERSON A | Opens - | | Town trials | | | Name of Street | | | | | | |
| The Profession and and a place of the control of th | The second contains provided by Containing C | LESS WILLIAM TO NOT HE NO | entitle. | | 111111111111111111111111111111111111111 | | - | 1 | | | | | | |
| Section of the control of the contro | Naviga di Santana ayay Navi 145 F 6 Navi 180 Navi | tote which allowings | | bedran . | Dec. | | 4000 | | | LUTWINSCO HER LIPE | | | | |
| Control for the proof of the control | Name and Address of the Control of t | it sie aften pleasery ni garlig je .n n gl te d ur her 2° illement | | (France) | | | | Decase | | | | | | _ |
| The second process of | Namica di Silvania de Park 345,74 (1915 35) Republica de Sala (1915 141 75) (1915 141 75) de UNITE CONTROL (1915 15) (1915 159) (1915 159) (1915 159) Republica (1915 159) (1915 159) (1915 159) (1915 159) (1915 159) Republica (1915 159) (1915 159) (1915 159) (1915 159) (1915 159) | frjie oftijk plaagery na godig ja on of de e or hen I ⁴ Eksperen na godinara K.A. De | NAME OF THE OWNER | | 3401 | 1941 | - | 4010 | | STROPH TURE | | | | |
| des production (Control of the Control of the Contr | Medicage subjections any final LET (LESS) of the important property (and LET (LESS) (LESS)) in such the common particle, the cost topic for the LET (LESS) can be also topic for the cost of the LET (LESS) can be also topic for the cost of the LET (LESS) can be also topic for the the LET (LESS) can be also topic for the the LET (LESS) can be also topic for the LET (LESS) can be also topic topic for the LET (LESS) can be also topic to | Este after elizabeth se quelle je ve est de d er her 1º Elemen re renivere en re- nacement Africa se | non et e extense | off I forest | Sept. | | - | 4010 | THE SERVICE AND ADDRESS OF THE PERSON NAMED IN COLUMN TWO IN COLUMN TO THE PERSON NAMED IN COLUM | | | | | _ |
| Section Sect | Medicage subjections any final LET (LESS) of the important property (and LET (LESS) (LESS)) in such the common particle, the cost topic for the LET (LESS) can be also topic for the cost of the LET (LESS) can be also topic for the cost of the LET (LESS) can be also topic for the the LET (LESS) can be also topic for the the LET (LESS) can be also topic for the LET (LESS) can be also topic topic for the LET (LESS) can be also topic to | Egypte of the filter of the country | non et e extense | off I forest | Sept. | | | 4010 | S. INTEREST | NO TIONS FOREIGNA | JOWNSCI Sew | TOTAL STORY | | |
| Supplies Val | Methods indication stays fine 1.46.7 A Tipus 1.47. Management (1.47. Extra 14.7. Extra 14.4. Extra 1 | Core physical characters on parties for more fine or for fire of these or or provinces Advantage on the core for the core | tich e'v | A Track (March | Sept. 1 | ST ST | mari peri | The second | S. INTEREST | NO TIONS FOREIGNA | JOWNSCI Sew | Wind and I | | = |
| Promote Production | Methods indication stays fine 1.46.7 A Tipus 1.47. Management (1.47. Extra 14.7. Extra 14.4. Extra 1 | Core phigh phosphary on parties for many the draw for the Triberson or providing for the draw for the Triberson or providing for the draw for the dr | side of the state | A Toronto | The Circle Section 1 | OF Winter Advantage | OR CONTRACT Disease | Terrorea April 100 | A regress of Processing of | NATIONS PARKET A | JOHNACI Me | V2.V2 | | |
| The state of the s | Amendment visionemen sport freish 144 f. of 146 f. of 14 | Company of the control of the contro | nich (V extra) pl ege (know) ple toet (1007) | A Transference On William (A Assessment Strycts) | The Committee Land | OF PRINCE AND Market Shirt (bull) | THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TRANSPORT NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TRANSPORT NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TRANSPORT NAMED IN COLUMN TWO IS NAMED IN COLUMN T | THE TOTAL PARTY OF THE TOTAL PAR | N. PETROS ES POSSESSOR ES MILATORIS PARTO ESTA | na moto rusem a | DOWNERS OF THE | Name . | | |
| Section of Intel® Vision Research (S. 6.4.4) Note the end for this intellection (S. 6.4.4) Note that intellection (S. | Memoran visioneme super finant ARI 7 A Miller (1) Miller State of the ARI 7 A Miller | Core chiefe (Flowing) on a surfage (in one of the chiefe (in one o | Total of a straining of the straining of | SA TO A STATE OF THE SAN OF THE S | Title Climit Member (might Mill Edit | OF STREET AND STREET ST | SE STATE OF | Section of the sectio | N. PETROS ES POSSESSOR ES MILATORIS PARTO ESTA | na moto rusem a | DOWNERS OF THE | Name . | on Artes | - |
| Name Section Name | Memoran visioneme super finant ARI 7 A Miller (1) Miller State of the ARI 7 A Miller | Core chiefe (Flowing) on a surfage (in one of the chiefe (in one o | Total of a straining of the straining of | SA TO A STATE OF THE SAN OF THE S | Title Committee Control Contro | OF White And Advances | TOTAL DESIGNATION OF THE PERSON OF T | Total Control of April | N. PROPERTY OF STREET, | SATION FOREST SCHOOL STATES OF THE STATES OF THE STATES OF THE STATES | LOWING SERVICE | Name . | on Artes | - |
| Update majorite FELDINGO majorite | Memoran visioneme super finant ARI 7 A Miller (1) Miller State of the ARI 7 A Miller | Core chiefe (Flowing) on a surfage (in one of the chiefe (in one o | Total of a straining of the straining of | SA TO A STATE OF THE SAN OF THE S | The Committee Confession of Committee Confession Confes | OF CHIPTER AND THE PARTY OF THE | Total Disease (A) | Total Control of April | N. PROPERTY OF STREET, | SATION FOREST SCHOOL STATES OF THE STATES OF THE STATES OF THE STATES | LOWING SERVICE | Name . | on Artes | - |
| CLOSTED ADDRESS: MEXA PROCESSES CLOS | Memoran visioneme super finant ARI 7 A Miller (1) Miller State of the ARI 7 A Miller | Core chiefe (Flowing) on a surfage (in one of the chiefe (in one o | Total of a straining of the straining of | SA TO A STATE OF THE SAN OF THE S | TO CONTROL OF THE PARTY OF THE | OF STREET AND STREET ST | THE PART OF THE PA | The second secon | N. FEST AND SE THE SECOND SE SECOND SECOND S | MATERIA POPULA MATERIA POPULA MATERI | COMMENT NEWS | Names First | on Artes | - |
| LIOTE E.CORREC. MAIN RESTANT | Memoran visioneme super finant ARI 7 A Miller (1) Miller State of the ARI 7 A Miller | Core chiefe (Flowing) on a surfage (in one of the chiefe (in one o | Total of a straining of the straining of | SA TO A STATE OF THE SAN OF THE S | TO CONTROL OF THE PARTY OF THE | OF STREET AND STREET ST | THE PART OF THE PA | The second secon | PARTIES AND PARTIE | THE PERSON NAMED AS A PARTY OF T | COMMENT NAME OF THE PERSON | NAMES OF THE PERSON | 2.632 | * |
| | **Contract Section 1. And Total | Core chiefe (Flowing) on a surfage (in one of the chiefe (in one o | Total of a straining of the straining of | SA TO A STATE OF THE SAN OF THE S | TO CONTROL OF THE PARTY OF THE | OF STREET AND STREET ST | THE PART OF THE PA | The second secon | A PRIDATE OF THE PRINCIPLE OF T | TOTAL PROPERTY OF THE PROPERTY | TOWNS IN ALL STREET | Market Property of the Control of th | You see to | 100 |
| REDIRESPORTMAN PLANTE | Medicate Ministration and part Party (AE) A Ministration of the Commission of the Co | Core chiefe (Flowing) on a surfage (in one of the chiefe (in one o | Total of a straining of the straining of | SA TO A STATE OF THE SAN OF THE S | TO CONTROL OF THE PARTY OF THE | OF STREET AND STREET ST | THE PART OF THE PA | The second secon | PETERSON OF THE PETERSON OF T | THE THE PARTY OF T | DEPENDED OF THE PARTY OF THE PA | Name Property of the Control of the | Free sections | The state of the s |
| -17 - | Whether this increase way from \$1.65 A failer (A) and the second value of an analysis of a failer of | Core chiefe (Flowing) on a surfage (in one of the chiefe (in one o | Total of a straining of the straining of | SA TO A STATE OF THE SAN OF THE S | TO CONTROL OF THE PARTY OF THE | OF STREET AND STREET ST | THE PART OF THE PA | The second secon | PETERSON OF THE PETERSON OF T | THE THE PARTY OF T | DEPENDED OF THE PARTY OF THE PA | Name Property of the Control of the | Free sections | The state of the s |
| | American inclusion and prof. No. 16.4 ft Section 16. A second of the control of | Core chiefe (Flowing) on a surfage (in one of the chiefe (in one o | Total of a straining of the straining of | SA TO A STATE OF THE SAN OF THE S | TO CONTROL OF THE PARTY OF THE | OF STREET AND STREET ST | THE PART OF THE PA | The second secon | PETERSON OF THE PETERSON OF T | THE THE PARTY OF T | DEPENDED OF THE PARTY OF THE PA | Name Property of the Control of the | Free sections | The state of the s |
| | Amendment includes any Park 1847 Add March 187 The Committee and Commit | Core chiefe (Flowing) on a surfage (in one of the chiefe (in one o | Total of a straining of the straining of | SA TO A STATE OF THE SAN OF THE S | TO CONTROL OF THE PARTY OF THE | OF STREET AND STREET ST | THE PART OF THE PA | The second secon | PETERSON OF THE PETERSON OF T | THE THE PARTY OF T | DEPENDED OF THE PARTY OF THE PA | Name Property of the Control of the | Free sections | The state of the s |
| CONTRACTOR CONTRACTOR AND CONTRACTOR CONTRAC | American inclusion and prof. No. 16.4 ft Section 16. A second of the control of | Core chiefe (Flowing) on a surfage (in one of the chiefe (in one o | Hardway (Construction of the Construction of t | A Transference (St. State of S | TO CONTROL OF THE PARTY OF THE | OF STREET AND STREET ST | Total June 1 (1991) Total Tot | Grand | PETERSON OF THE PETERSON OF T | THE THE PARTY OF T | DEPENDED OF THE PARTY OF THE PA | Name Property of the Control of the | Note that the same of the same | |

Obstation floridates and Security Services




Swall of Frage Meter (III) has been been as as as

Name Street Property



A&F ENGINEERING GROUP, INC.
600 INSERT IN. C. BRIEGO COLUMBIA, C. BRIE
102 (169) 841-3000 PLG: (169) 841-3001

TF-E0.2



PLAN NOTES

- REFER TO DRAWNS EQ. SNOLE LINE DIAGRAM, FOR POWER CONDUIT SIZE AND WIRE QUANTITIES.





A&P ENGINEERING GROUP, INC. 1000 HELDER BUT SEED FOR 1000 PAGE 100

MENLO PARK FIRE STATION NO. 01 & TRAINING TOWER











| | DATE 08/22/2024 NG HISTORY | PROJECT 230 | |
|------|----------------------------------|----------------|-------------------|
| No. | Descrip Plan Check | | Date 07-08-200 |
| _ | Tial Cities | ojen vo | 07-08-20 |
| | | | |
| | | | |
| PL | ANNING DEPART | MENT SUBI | MITTAL |
| BULD | NG NUMBER | | |
| | SITE PO | | |

E1.1





GENERAL NOTES:


- All grading is subject to observation by the City. Permittee or representative shall notify th Department of Public Works Project Inspector at least 48 hours before start of any grading
- The permittee or agent shall maintain the streets, sidewalks and all other public rights-of-way in a clean, safe and usable condition. All spills of soil, rock or construction debris shall be removed from the publicly owned properly during construction and upon completion of the project. All adjacent property, private or public shall be maintained in a clean, safe and usable condition.
- The Civil Engineer for this project is: Hanna & Brunetti, 7651 Eigleberry Street, Gilray, CA 95020
- This Rough Grading Plan has been prepared under the direction of a licensed engineer and designed based on the recommendations of the referenced project Geotechnical Report.
- The stormwater conveyance system has been designed in accordance with the appropria
- Soils Engineer Information and Requirements:
 A. The Soil Engineer for this project is:
 Attos Technical Consultants LLC 2001 Crox Canyon Rd, Suite 210, San Ramon, CA 94583
- B. The Geotechnical Report for this project is: Geotechnical Engineering Study Atlas No. 91-68237-PW
- Limited Phase II Subsurface Investigation Report Atlas No. 2054000398
- C. All grading work shall conform to the recommendations of the project Geotechnical Report and/or the project Soil Engineer.
- D. All grading work shall be observed and approved by the Soil Engineer. The Soil Engineer shall be notified at least 48 hours before beginning any grading. Unobserved and/or unapproved grading work shall be removed and replaced under observation.

Preliminary Grading & Drainage Plan

Menlo Park Fire Station No.1 & Training Tower

300 & 320 Middlefield Road - apn 062-460-100

City of Menlo Park, California San Mateo County



OVERALL SITE PLAN SCALE: 1"=40"





8

LEGEND:


ENGINEERING GEOLOGIST AND GEOTECHNICAL ENGINEER OF RECORD THIS PLAN HAS BEEN REVIEWED AND FOUND TO BE IN GENERAL CONFORMANCE WITH THE INTENT AND PURPOSE OF THE GEOTECHNICAL AND GEOLOGIC REPORT PREPARED BY (COMPANY NAME) BY C.E.G. # BY G.E. #

EARTH WORK QUANTITIES NOTE: EARTHWORK QUANTITIES SHOWN ARE APPROXIMATE. IT SHALL BE THE CONTRACTOR: RESPONSIBILITY TO INDEPENDENTLY ESTIMATE QUANTITIES FOR HIS/HER OWN USE. EXSTING LINGERGROUND UTILITIES ARE SHOWN IN THEIR APPROXIMATE (CLARIDO, SEED ON RECORD INFORMATION AND ADMINISTRATION ADMINISTRATION AND ADMINISTRATION ADMINISTRATION AND ADMINISTRATION ADMINISTRATION AND ADMINISTRATION ADMINISTRATION

WHERE THE FIRM OF HANNA & BRUNETTI DOES NOT PROVIDE CONSTRUCTION STAKES, SAID FIRM WILL ASSUME NO RESPONSIBILITY WHATSOEVER FOR IMPROVEMENTS CONSTRUCTED THEREFROM.

NOTE: 10 CONTRACTOR

CONTRACTOR AGESTS THAT HE SHALL ASSUME SIZE AND COMPLETE RESPONSIBILITY FOR JOB SITE CONDITIONS DURING THE CONTRACT OF THE PROJECT, INCLUDING SHETY OF ALL STEPLY PROJECT, INCLUDING SHETY OF ALL SHETY AND HAT THE CONTRACTOR SHALL DEPTON, INCOMPAT AND HOLD THE CONTRACTOR SHALL DEPTON, INCOMPAT AND HOLD THE CONTRACTOR SHALL SHETY OF ALL SHETY AND HAT ALL SHETY OF ALL SHETY O



PRELIMINARY PLANS NOT FOR CONSTRUCTION

(650) 688-8400

ARCHITECT PBK, INC. 1327 ARCHER ST, SUITE 110 SAN LUIS OBISPO, CA 93401 (805) 329-3076 P (805) 329-3076 F

SURVEYOR HANNA-BRUNETT 7651 EIGLEBERRY STREET GILROY, CA 95020

OFFICE 408 842-2173

CIVIL ENGINEER HANNA-BRUNETTI 7651 EIGLEBERRY STREET GLROY, CA 95020

OFFICE 408 842-2173 FAX 408 842-3662 EMAIL: ENCINEERING@HANNABRUNETTI.COM

(925) 314-7100

(916) 524-5614 WDSLA.COM

HANNA-BRUNETTI

PRELIMINARY GRADING & DRAINAGE PLAN

SHEET

COVER (

& 320 Middlefield F APN 062-460-100

GEOTECHNICAL ENGINEER

LANDSCAPE ARCHITECT WILSON DESIGN STUDIO LANDSCAPE ARCHITECTURI 1631 ALHAMBRA BLVD., SUITE 100 SACRAMENTO, CA 95816


SHEET INDEX


C1.0 COVER SHEET
C2.0 BOUNDARY & TOPOGRAPHIC SURVEY
C3.0 DEMOLITION PLAN


C3.0 DEMOLITION PLAN
C4.0 SITE DEVELOPMENT PLAN
C5.0 GRADING & DRAINAGE PLAN
C6.0 GRADING & DRAINAGE PLAN
C7.0 CROSS SECTIONS
C8.0 UTILITY PLAN
C9.0 STORMWATER MANAGEMENT PLAN
C1.0 CANSETPLICITION DETAILS


C10.0 CONSTRUCTION DETAILS C11.0 FROSION CONTROL PLAN


SHEET C1.0 Of 12 SHEETS PW PROJECT #






























R.C.E. # 69278



MENLO PARK JULY 2024

EROSION CONTROL NOTES

- EROSION CONTROL MEASURES SHALL BE EFFECTIVE FOR CONSTRUCTION DURING THE RAINY SEASON; OCTOBER 15 THROUGH APRIL 15.
- NO STORM WATER RUNOFF SHALL BE ALLOWED TO DRAIN INTO THE EXISTING AND/OR PROPOSED UNDERGROUND STORM SYSTEM UNTIL SUITABLE EROSION CONTROL MEASURES ARE FULLY IMPLEMENTED. NO STORM WATER RUNOFF SHALL BE ALLOWED TO ENTER THE STORM DRAIN SYSTEM THAT IS NOT CLEAR, AND FREE OF SILTS.
- A FBER ROLL BARRIER PER "DETAIL SE-5" SHALL BE INSTALL ALONG THE PERMETER OF THE PROJECT SITE. THE LOCATION OF THE FBER ROLL ALONG THE PERMETER SHALL BE ADJUSTED TO ELIMINATE SEDIMENT LADDR RUNDER FROM EXAMO. THE SITE. A FBER ROLL SHALL AS DE REQUIRED AROUND THE PERMETER OF ANY STOOPHEL OF OTHER SITE OF BARE, LOOSE EARTH.
 - ALL STORM DRAIN MANHOLES, CATCH BASINS, AND/OR DROP INLETS THAT ARE TO ACCEPT STORM WATER SHALL HAVE INLET PROTECTION MEASURES PER DETAIL SE-TO. STORM WATER RUNOFF SHALL BE DIRECTED TO THESE INLETS ONLY. STORM DRAIN CATCH BANISH THAT ARE NOT COMPILETELY.
- THE NAME, ADDRESS, AND 24 HOUR TELEPHONE NUMBER OF THE PERSON RESPONSIBLE FOR THE IMPLEMENTATION OF THE EROSION CONTROL PLAN SHALL BE PROVIDED TO THE CITY.
- PRIOR TO GRADING, AN ENTRANCE SHALL BE CONSTRUCTED, CONSISTING OF A MINIMUM OF 50 LF OF DRAIN ROCK, 3" IN DIAMETER, PLACED OVER MIRAFI 500X (OR EQUAL) PER DETAIL TC-1. THE ENTRANCE SHALL CONFORM TO "CONSTRUCTION ENTRANCE DETAIL TC-1". THEE SHALLE ONLY ONE DISTRIBUTE ONLY ONE DISTRIBUTE OF THE OUR THE RAINY SEASON, THE LOCATION SHALL BE AS SHOWN ON THESE PLANS, OR AT A LOCATION APPROVED BY THE CITY.
- ALL MEAS OF BARE, TURNED OR INSTINEND EARTH SHALL BE STABLIZED BY USE OF HYDROSEED PER THE TABLE BELOW.
 ALL STOOPHES, MAD/OR BORROW AREAS SHALL BE PROTECTED WITH PROPROPRIATE EROSION CONTROL MEASURES SUCH AS A
 PERMICIPES SITTEMEN. AND OTHER METHODS TO PROPRIAT MY EROSION OR SITS WIRRARDION, ALL BEROSION CONTROL MEASURES SHALL BE
 WANTIANED WITH DESTRUCTIONS, BY LOW WITH THE PROPRIATE OF AN IN THE DESCRIPT OF THE OTHER OTHER AND SHALL BE MADE TO
 SHALL BE MANTIANED, BY LOW WITH THE PAPPOOL OF OF AN IN THE DESCRIPT OF THE OTHER OTHER STOOM DATA
 BY THE DESCRIPTIONS, BY LOW WITH THE PAPPOOL OF OF AN IN THE DESCRIPT OF OTHER OTHER OTHER STOOM DATA
 BY THE DESCRIPTION OF THE OTHER DATA OF THE OTHER OTHER DATA OF THE OTHER DATA OF T
- All paved street, and areas adjacent to the site shall be kept clear of earth materials and debris. The site shall be maintained so as to <u>eliminate</u>, sediment laden runoff from entering the storm drain system.
- IT IS THE RESPONSIBILITY OF THE CONTRACTOR TO INSPECT AND REPAIR ALL EROSON CONTROL FACILITIES AT THE ENG OF EACH DAY DURING THE RAINY SEASON. ANY DAMAGED STRUCTIONA, MEASURES ARE TO BE REPAIRED BY DIG OF THE DAY. TRAPPED SEDIMENT IN "SO INLESS" (AND DIMER ESSON CONTROL MEASURES) SHALL BE REMOVED TO MANTAIN TRAP ETFIENCY. REMOVED SEDIMENT SHALL BE USPOSED BY SPREADING ON STIE, WHERE IT MILL NOT MEASURE.
- IT IS THE RESPOSIBILITY OF THE CONTRACTOR TO PREVENT THE FORMATION OF AIRBORNE DUST NUISANCE AND SHALL BE RESPOSIBLE FOR ANY DAMAGE RESULTING FROM A FAILURE TO DO SO.
- 11. ALL DRAIN SWALES SHALL BE PER DETAIL EC-9.
- NOOMPLETE CRADING SHALL NOT BE ALLONED, CONTRAITOR SHALL MAINATIN A DRAIN PATH AS SHOWN ON THIS PLAN. SAID DRAIN PATH SHALL BE MAINTANED LINED DRAIN SHALLES, BOWN LEF PROVEDING AT A MAINMAN. PER PORDING DOES ONCH ON THE STEE AFTER CRADING, THE WATER MUST BE FREE AND CLEAR OF SEDIMENT PRIOR TO DISOMRÉE TO THE STORM DRAIN SYSTEM. THIS REQUIREMENT MAY INCESSTATE THE USE OF MATURAL AND/OR MECHANICAL DESITING MERCHINGS, SUBJECT TO APPROVAL BY THE OTT ON REPORTS.
- 13. F THESE EROSION CONTROL MEASURE PROVE INADEQUATE, STRAW MULCH, TACKIFIER, AND ADDITIONAL HYDROSEEDING MAY BE REQUIRED.

HYDROSEED TABLE LBS/ACRE COMMON BARLEY ANNUAL RYEGRASS CRIMSON CLOVER FERTILIZER 7-2-3 FIBER MULCH TACKIFIER

- 14. ALL GRADING WORK BETWEEN OCTOBER 15th AND APRIL 15th IS AT THE DISCRETION OF THE CITY BUILDING OFFICIAL.
- 15. PROVIDE SHRUBS AND/OR TREES REQUIRED ON SLOPES GREATER THAN 15 FEET IN VERTICAL HEIGHT.
- THE OWNER/OWNER'S CONTRACTOR, ASSIST, AND/OR DIGINESS SHALL NETALL AND MANTAN THROUGHOUT THE DURANDING OF CONSTRUCTION AND UNIT. THE STREAMMENT OF FERMANIEST INSTRUCTION AND WELLOW TO STREAM WATER COUNTY MANTANED BOAD BRIOT OF WAY AND ANY PORTON OF THE STE WHERE STORM WATER RIN-OFF IS DIRECTLY TOWNING WITH DIRECTLY AND ORD FOR THE WATER MANAGEMENT FRANCESS (GMPS') TO PRESENT LOCKNISTORY. BUT IN THE STORM DEAN STREAM, AND THE AND THE STREAMS, AND ROADWAY INFRASTRUCTURE. BUT'S SHALL NOLLIDE, BUT NOT LIMITED TO, THE FOLLOWING PRINCIPS SPECIAL BY THE PRUISE OWN DEPRESENTATIONS.
- A) REDUCTION OF POLLUTANTS IN STORM WATER DISCHARGES FROM THE CONSTRUCTION SITE AND THE CONTRACTOR'S MATERIAL AND EQUIPMENT LAYDOWN/STAGING AREAS.
- B) PREVENTION OF TRACKING OF MUD, DIRT AND CONSTRUCTION MATERIALS ONTO PUBLIC ROAD RIGHT OF WAY.
- PREVENTION OF DISCHARGE OF WATER RUNOFF DURING DRY AND WET WEATHER CONDITIONS ONTO PUBLIC ROAD RIGHT OF
- THE OMER OWNERS CONTRATION AGENT, HID OR DUMBER SHALL RUBBER THAT ALL TRADEAMY CONTRIBUTION AGAINST
 BECLURING BUT HOW INTERT TO CONSTRUCTION MATERIANS, DIVINESS, HAZAROUS AND INDI-HAZAROUS MATERIAL STORMER
 EQUIPMENT, TOOLS, PORTABLE TOLETS, CONCRET WASHOLT, CORREAGE CONTRIBUTS, LANDOWN YARDS, SECONDARY CONTRIBUTE
 AREAS, ETC. ARE COLOTED OUTSED THE SHAT GLAPA COUNTY MAINTAINER PORD REFORT OF WAY AND ATT POPTION OF THE SITE OF THE SHAPE OF THE S

LEGEND



CONSTRUCTION ENTRANCE PER

FIBER ROLL BARRIER PER

STORM DRAIN INLET PROTECTION PER DETAIL SE-10

PORT-O-LET WITH SECONDARY CONTAINMENT MATERIAL STORAGE AND LAYDOWN AREA

VΡ CONSTRUCTION TRAILER AND VEHICLE PARKING AREA

CONCRETE WASHOUT AREA

PRELIMINARY PLANS NOT FOR CONSTRUCTION APPROVED FOR ISSUANCE REFER TO ENCROACHMENT AND/O CONSTRUCTION PERMIT AND PLAN

Erosion Control Plan

EO COUNTY CALIFORNIA

C11.0 23062 JOB NO. 23062

Menlo Park Fire Station No.1 & Training Tower - apn 062-460-100

DESIGNED BY: AM CHECKED BY: . DRAWN BY: APPLICANT: MENLO PARK FIRE PROTECTION DISTRICT

HORIZ SCALE: ["=40"

VERT. SCALE: NONE

HANNA-BRUNETTI

REET • GILROY • 95020 • CALIFORNI

ROAD: MIDDLEFIELD ROAD

MATE DATE

PLAN

REVISIONS:

Stabilized Construction Entrance/Exit TC-1

√ Grigino grade

SECTION B-B

BY:




Construction Best Management Practices (BMPs)

Construction projects are required to implement the stormwater best management practices (BMP) on this page, as they apply to your project, all year long.

Clean Water, Healthy Community,

Materials & Waste Management



Non-Hazardony Materials

- 23 Herm and cover succipiles of sand, duri or other construction material with tarps when cain is forecast or if not actively being used within 14 days.
- D Use (but don't overnise) reclaimed water for dust control.

Hazardan Majerials

ATIONS SHALL BERSTRETED TO HE GENERAL STEEP OF WHICH THE YOUNGE PERSONS AND PREACTION THE STEEP STEEP OF THE STEEP STEEP OF THE ACCEPTANCE OF HEEK RESTRICTIONS AND THE EVENTS WITH THE STEEP PLAN AND STEEP STEEP STEEP OF THE ACCEPTANCE OF HEEK RESTRICTIONS AND THE ACCEPTANCE OF HER ACCEPTANCE OF THE ACCEPTANCE OF TH

- D. Label all hazardous materials and hazardous wastes (such as pesticides, points, thinners, solvents, but, od, and antifecze) in accordance with any, youngs, state and federal regulations.
- 3 Store hazardnas materials and wastes in mater light containers, after in appropriate secondary containment, and cover them at the end of every work day or during wet weather or when run in forecost.
- D Fullow manufacturer's application instructions for hazardors materials and he cureful not to use more than necessary. Do not apply obsmittals emdosins when rate is forecast within 24 leates.
- Arrange for appropriate disposal of all fuzzodous wastes.

Waste Management

- Cover manu disposal containers securely with turps at the end of every work day and during wat worther.
- ② Check wante disposal containors frequently for leafs and to make sure they are not overfalled. Never best down a damping on the construction site.
- Clean is replace portable todays, and inspect them frequently for leaks and spills.
- 23 Dispose of all wastes and debuts properly. Recycle materials and wastes that can be recycled (such as in-plats, covaries, aggregate base materials, wood, gop bond, pipe, etc.)
- Dispose of liquid residues from paints, thinners, solvents, glues, and clusting fluids as hazanfous waste.

Construction Entrances and Perimeter

- D. Establish and maximum effective permeter controls and stabilize all construction entrances and exits to sufficiently control enotion and sediment discharges from sity and tracking off site.
- Sweep or vacuum any street tracking immediately and secure sedimere source to prevent further making. Never lose down street to clean up wacking.

Equipment Management & Spill Control



Maintenance and Parking

- Designate on sees, fitted with appropriate BMPs, for vehicle and occupant parking and storage.
- Perform major maintenance, repair jobs, and vehicle and equipment washing off site.
- If refueling or vehicle maintenance must be done ossite, work in a borned area as on firms storm drains and over a drip pan or drop cloths hig emugh to collect thirds. Recycle or dispose of fluids as hazardous wester.
- If which or equipment electing must be done omste, clean with water only in a bernaed area that will sat affest time water to tun site gatters, streets, steem dones, or earther waters.
- Do not alean vehicle or equipment moste using scaps, solvents, degreesers, or steam chaning equipment.

Spill Prevention and Control

- Keep spall channel materials (e.g., rags, absorbents and out litter) available at the construction site at all times.
- Inspect vehicles and equipment frequently for and sepair leaks promptly. Our drip pairs to catch leaks until reports are made.
- Clean up spills or leaks immediately and dispose of cleanup materials properly.
- Do not have shown surfaces where thirds have spilled.
 Use dry channel methods telesorbere materials, cas.
 Etter, and/or repost.
- Sweep up spilled dry materials immediately. Do not try to wish them way with water, or bury them.
- Clean up spills on dirt areas by diagong up and properly disposing of contaminated and.
- □ Region significant spills immediately. You are required by law to report all significant releases of financious materials, including oil. To report in spill: 10 field 91, or your local emergency sespective number, 21 Call the Governant's Office of Fineigency Services Warning Center, (1900) 852-1500 (24) hours).

Earthmoving



- Schodule grading and encavation work during day weather.
- Stabilize all denoted areas, install and maintain semponcy eroccor controls (such as cossion control libric at bouled fiber march) and beganition is established.
- 3 Remove existing regetation only when absolutely necessary, and seed in plant vegetation for arcsion control on slopes or othere construction is not immediately planned.
- Prevent sediment from migrating off-site and protect storm their index, gutters, disches, and datings courses by simuling and maintaining appropriate BSDPs, such as fiber rolls, site femose sediment begins, graved bugs, from, sit.
- Keep exercised soil are site and transfer it to along mades on site, not in the streets.

Comminuted Soils

- If any of the following conditions are observed, test for contamination and contact the Regional Water Quality Control Board.
- Unusual soil conditions, discoluration or odor.
- Abandoned underground testics.
- Ahundmed wells
- Buried framels, detris, or trust.

Paving/Asphalt Work



- A void paving and scal coating in wer weather or when rain in foreign, to proven rementels that have not cured from contacting sharms star ranoff.
- Cover storm drain tales; and manholes when applying seal cost, task cost, sharp seal, fng seal, etc.
- Collect and recycle or appropriately dispose of excess intrasive grand or sand.
 Du NOT sweep or week it into gettern.
- Do not use water to wash down fresh asphalt concrete pavement.

Suverating & Asphall/Concrete Removal

- Protect nearby storm drain index when saw cutting. Use filter fabric, each basin inlet filters, or gravel hags to keep alarny out of the storm drain system.
- Showd, abrourts or recomm ann-cut shary and dispose of all wrate as soon as you are finished in one became or at the end of each work day t whichever is sooned.)
- If sewout slarry enters a catch hasin, clean it up immediately.

Painting & Paint Removal



Painting Cleanup and Removal

- Never clean brashes or riuse point containers into a street, gutter, sterm drain, or stream.
- □ For water-based points, paint out brushes to the extent possible, and more rate a drain that gives to the sanitary sewer. Never pour point down a storm death.
- □ For nil-based paims, paint out intakes to the extent possible and clean with thinner or solvent in a proper common. Filter and trues thinners and solvents. Dispose of excess liquids as bazandou wase.
- Paint chips and that from non-hazardism dry stripping and soul blasting may be swept up or collected in plastic drop clottes and disposal of as much.
- Chemical paint suppose residue and chips and dark from manue paints or paints containing lead, mercary, or refunçitin must be disposed of as harmdons waste. Lead based point romoval requires a stracerified contractor.

Dewatering



- Descharges of groundwater or captured runnif from desaureing openniss must be properly mataged and disposed. Who possible and deswateing duclarge for landscaped orace cantainty sever call descharging in the century sever call your local wassessure treatment pleat.
- Diverting-on water from offsite away from all disturbed areas
- □ When slewatering, entify and obtain approval from the beed manicipality before discharging water to a stock gatter or mean drain. Pillyation or diversion through a basin, tank, or seilment trap may be required.
- D be seen of known or suspected consummerion, sall your best agency to determine whether the ground water must be total. Pumped groundwater may used to be collected and hanked off-site fits tearment and proper disposal.

Storm drain polluters may be liable for fines of up to \$10,000 per day!

MENLO PARK JULY 2024

HANNA-BRUNETTI
set mor

CIVIL DIGNIERS ® LAND SURVEYORS
CONSTRUCTION MANAGENERS
7851 BIGLEBERRY STREET ® GLIRIO 9 89000 © CULFORMA
OFFICE (80) 8024773
BMAL ENMERSHENG B HANNASKURETTLCOM

DATE: JLY 2024

HORIZ. SCALE: I-20

VERT. SCALE: NONE

DESIGNED BY: AM

CHECKED BY:

DRAWN BY: TM

manda Joy Musy-Verdel

C.E. # 69278

REFERENCES

Construction Best Management Practice (BMPs)

Concrete, Grout & Mortar

Application

Story concrete, great, and monter away

□ Wis8 out concrete equipment/tracks

offsite or in a designmed washout

that will prevent leaching into the

■ When working exposed aggregate,

and disposed of properly.

area, where the water will flow loss a

temporary waste nit, and in a mining

Let concrete hunden and dispuse of as

prevent washwater from entering storm

eutros, hose washwater onto dirt areas, or

drain onto a hormod surface to be purposed

Landscaping

2 Protect stockpiled landscaping materials

IJ Stack bugged muterial on pulls's and

Discontinue application of any crodible

landscape material within 2 days, before a

forecast usin event or during wet weather.

unifer cover.

from wind and rain by storing them under

drains. Block any infets and vacuum

andarlying seil or onto somounding areas

bare box. Bronn ster

from storm drains or staterways, and or

pallets under cover to protect them from

Menlo Park Fire Station No.1 & Training Tower - apn 062-460-100

AN MATEO CAL


JOB NO. 23062

APPLICANT: MENLO PARK FIRE PROTECTION DISTRICT

ROAD: MIDDLEFIELD ROAD

C53

C12.0



TREE REMOVAL LEGEND


(E) TREE TO BE REMOVED, TYP. REFER TO MENLO PARK FIRE STATION NO. 1 ARBORIST REPORT DATED APRIL 19, 2024 FOR MORE INFORMATION ON TREE SPECIES AND SIZE.

HERITAGE TREES PRESERVED AROUND THE PROPERTY MUST INCLUDE TREE PROTECTION AND PROJECT ARRORIST TREE PROTECTION MONITORING INSPECTIONS DURING ACTIVE DEMOLITION AND CONSTRUCTION.

| | | DISPOS | ITION | | |
|------|--------------------|--------|-------|---------------|--|
| TREE | NAME | RETAIN | RMV | DIAM (in.) | |
| 1 | Saucer magnolia | | х | 30 | |
| 2 | American sweetgum | 2 | X | 27 | |
| 3 | American sweetgum | - 21 | × | 20 | |
| 4 | American sweetgum | 38 | × | 25 | |
| 5 | American sweetgum | 125 | X | 19 | |
| 6 | N. CA black walnut | - 3 | X | 49 | |
| ₹ | Littleleaf knden | - \$5 | X: | 21 | |
| :8 | Littleleaf Inden | - 80 | X | 25 | |
| 9 | Olive tree | 8 | X | 22 | |
| 10 | Olive tree | +: | х | 19 | |
| 11 | Olive tree | -: | × | 19 | |
| 12 | Olive true | - 11 | X | 25 | |
| 13 | Olive tree | +- | × | 23 | |

| | | DISPOS | ITION | |
|------|--|--------|-------|---------------|
| TREE | # NAME 14 Olive free 16 Coast live oak 17 Monterey cypress 18 Monterey cypress 19 Monterey cypress 20 Coast live oak | RETAIN | RMV | DIAM (in.) |
| 14 | Olive tree | 18 | X | 22 |
| 16 | Coast live oak | - 90 | X: | 25 |
| 17 | Monterey cypress | 25 | × | 48 |
| 16 | Monterey cypress | ÷8 | × | 29 |
| 19 | Monterey cypress | 36 | × | 25 |
| 20 | Coast live oak | *8 | × | 25 |
| 21 | Coast Ive oak | 100 | × | 29 |
| 22 | Monterey cypress | - | × | 20 |














| \equiv | | | |
|----------|-----------------------|----------------|---------|
| | CLI O PARK FIRE PE | | DIOTOIO |
| MENL | | | |
| | DATE 18/13/2025 | PROJECT 230 | |
| | NO HISTORY | 230 | 302 |
| No. | Descrip | tion | Date |
| | | | |
| | | | |
| | | | _ |
| | | | |
| - | | | _ |
| | | | |
| PLA | INNING DEPART | MENT SUBI | MITTAL |
| BUILDI | NG NUMBER | | |
| | TREE R | EMOV | AL |

L1.0

CHECKED BY:

PLOT STAMP:




PLANNING DEPARTMENT SUBMITTAL PLANTING PLAN L1.1


B

C55

CHECKED BY:

PLOT STAMP:










200MOQEED ROLD







E1.0









| TOWER | |
|-------|--|
| G | |











| No. | Descrip | | Date | | | |
|-------|---------------|---------------------|--------|--|--|--|
| 1 | Plan Check | Plan Check Cycle #3 | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| PLA | INNING DEPART | MENT SUBI | MITTAL | | | |
| BULDI | NG NUMBER | | | | | |
| | | | | | | |


E1.1

PLAN












A&F ENGINEERING GROUP, INC.
6000 BARELINE ID., SUITE C, EMICING CUCAMBRIA, CA 60761
TEL: (1007) 941-3000 PAZ: (1009) 941-8211





LIGHT FIXTURE DATA SHEET N.T.S.

A&F ENGINEERING GROUP, INC. 1000 INC



ARBORIST REPORT

MENLO PARK FIRE STATION NO. 1 & TRAINING TOWER 300 MIDDLEFIELD RD MENLO PARK, CA (PLN2024-00043)

Submitted to:

Menlo Park Fire Protection District 170 Middlefield Road Menlo Park, CA 94025

Prepared by:

David L. Babby

Registered Consulting Arborist® #399

Board-Certified Master Arborist® #WE-4001B

Menlo Park Business License #73953

Prior: April 19, 2024 Current: December 13, 2024

TABLE OF CONTENTS

| | <u>PAGE</u> |
|----------------|--|
| EXECUTIVE SU | MMARY 1 |
| SECTION 1.0 | TITLE INTRODUCTION |
| 2.0 | TREE COUNT AND COMPOSITION 3 |
| 3.0 | SUITABILITY FOR PRESERVATION 5 |
| 4.0 | PROPOSED TREE DISPOSITION 6 |
| 5.0 | APPRAISED TREE VALUES AND REPLACEMENTS 7 |
| 6.0 | ASSUMPTIONS AND LIMITING CONDITIONS 9 |
| | |
| | LIST OF TABLES |
| <u>TABLE</u> | <u>TITLE</u> |
| 1 | TREE COUNT AND COMPOSITION |
| 2 | HERITAGE TREE REMOVAL SUMMARY 6 |
| | |
| | EXHIBITS |
| EXHIBIT | <u>TITLE</u> |
| Α | TREE INVENTORY TABLE (four sheets) |
| В | SITE MAP (one sheet) |
| С | PHOTOGRAPHS (five sheets) |
| D | HERITAGE TREE APPRAISAL CALCULATION TABLE (two sheets) |

EXECUTIVE SUMMARY

Menlo Park Fire Protection District is planning for the redevelopment of their Headquarters Fire Station No. 1 at 300 Middlefield Road, Menlo Park (PLN2024-00043). The project is named Menlo Park Fire Station No. 1 & Training Tower, and involves demolishing all existing buildings and constructing three new ones and an underground parking garage. This *Arborist Report* serves to supplemental their planning submittal and disclose the following information regarding 23 trees located within or immediately adjacent to the site: size, condition, and suitability for preservation; heritage and street tree status; proposed disposition; and appraised values for heritage trees and replacement standards. Exhibit A presents details of each tree, Exhibit B contains a site map showing tree locations and assigned numbers, and Exhibit C displays photographs.

Of the 23 inventoried trees, a summary of their heritage, non-heritage and street tree status is as follows:

- Heritage (21 in total): #1-14 and 16-22.
- Non-heritage (2 in total): #15 and 23.
- Street (1 in total): #20 (partially).

All 23 trees are in direct conflict with the proposed design as represented on the 8/30/24 plan set. Of these, all but #15 and 23 are designated as heritage trees.

Table 2 summarizes the underlying reasons for removing the 21 heritage trees, supporting City criteria for removal, and their appraised values.

The combined appraised value of the 23 heritage trees equals \$123,800. As mitigation for their removals, the City requires a replacement plan reflecting a value equal to or exceeding this amount; refer to Section 5.0 of this report for detailed information.

1.0 INTRODUCTION

Menlo Park Fire Protection District plans to redevelop their Headquarters Fire Station No. 1 at 300 Middlefield Road, Menlo Park, to include demolishing all existing buildings and constructing three new ones with an underground parking garage (the project is named Menlo Park Fire Station No. 1 & Training Tower). The site occupies a nearly 2-acre parcel located at the northwest corner of Middlefield Road and Santa Monica Avenue, bordered by Middlefield Road along the south, Santa Monica Avenue along the east, and the Lands of the Roman Catholic Seminary of San Francisco along the north and west boundaries. As part of their design study and future planning submittal, they have retained me to prepare this *Arborist Report*, and specific tasks assigned to execute are as follows (this report represents an update of my prior one to address City comments dated 10/15/24):

- Visit the site on 11/27/23, 12/2/23 and 4/12/24 to document information regarding 23 trees located either: [1] inside the site and having trunk diameters of ≥6 inches at 54 inches above grade; [2] on neighboring properties if they are of heritage tree¹ status and either overhang or are within 10 times their trunk diameter from the site; and [3] within the public ROW, either along the frontage or 30 feet from the boundary.
- Measure each tree's trunk diameter pursuant to 13.24.020(5) of the Menlo Park Municipal Code; diameters are rounded to the nearest whole number, and trees listed with more than one are formed by multiple trunks emerging at or below grade.
- Estimate tree heights and average canopy spreads (rounded to the nearest fifth).
- Obtain photographs of each tree; see Exhibit C.
- Identify which are regulated by City Code as heritage trees and/or street trees.
- Appraise the monetary value of each heritage tree.
- Evaluate each tree's health, structure and form, and assign an overall condition rating.
- Determine each tree's suitability for preservation (e.g. high, moderate or low).
- Plot each tree number onto the site map in Exhibit B (base map is the Site Plan of Proposed Lot Line Adjustment, prepared by MacLeod and Associates, dated 2/7/18).
- Review the entire plan set prepared by PBK, dated 8/30/24, to ascertain the proposed disposition and impacts.
- Nail round, silver tags with engraved corresponding numbers onto each tree.
- Prepare a written report presenting the above information.

Menlo Park Fire Station No. 1; 300 Middlefield Road, Menlo Park Menlo Park Fire Protection District

¹ Section 13.24.020(5) of the Menlo Park Municipal Code defines a heritage tree as follows: [1] any oak native to California and having a trunk diameter of ≥10" at 54" above grade; [2] any other tree having a trunk diameter ≥15" at 54" above grade; and [3] any multi-trunk tree ≥12' tall and with a trunk diameter ≥15" below the main union of trunks, except when the trunks' union occurs below grade, and in which case, each trunk is considered a stand-alone tree.

2.0 TREE COUNT AND COMPOSITION

Twenty-three (23) trees of seven various species were inventoried for this report. They are sequentially numbered and tagged as 1 thru 23, and Table 1 below identifies their common names, assigned numbers, counts and overall percentages.

Table 1 - Tree Count and Composition

| NAME | TREE NUMBER(S) | COUNT | % OF TOTAL |
|----------------------------|-----------------|-------|---------------|
| American sweetgum | 2-5 | 4 | 17% |
| Coast live oak | 15, 16, 20 & 21 | 4 | 17% |
| Littleleaf linden | 7 & 8 | 2 | 9% |
| N. California black walnut | 6 | 1 | 4% |
| Monterey cypress | 17-19 & 22 | 4 | 17% |
| Olive tree | 9-14 & 23 | 7 | 30% |
| Saucer magnolia | 1 | 1 | 4% |

Total 23 100%

As illustrated in the table above, the site is populated predominantly by olive trees (at 30%), followed by sweetgum, coast live oak and Monterey cypress (each at 17%).

Specific information regarding each tree is presented within the table in Exhibit A. The trees' numbers and locations can be viewed on the site map in Exhibit B, and photographs obtained in 2023 are presented in Exhibit C.

Twenty-one (21) are defined by City Code as heritage trees; they include #1-14 and 16-22. The other two, namely #15 and 23, are regarded as non-heritage trees.

Tree #20 is also defined as a street tree due to its trunk spanning over the eastern property boundary into the public ROW aligning Santa Monica Avenue. The trunks of all other trees are located entirely on private property.

Tree #6's trunk spans over the northern property boundary, and as such, is regarded as being partially offsite and jointly-owned.

Tree #15 is not shown on the site plan survey. I denote its trunk's location on the map in Exhibit B, but note that location is only roughly approximate and should not be construed as being surveyed.

The site plan survey labels three trees which either do not exist or are stumps, and callouts of each are noted on the map in Exhibit B. Of these, one is a stump adjacent to #16; another is also a stump (blanketed by ivy) adjacent to #23; and a third is adjacent to #9 and non-existent.

A general summary of the trees' locations is as follows:

- #1 is located at the east side of the main building, and its canopy spans along and grows away from the structure.
- #2 thru 5 form a row along the west side of the buildings.
- #6 thru 23 occupy the undeveloped section of ground north of the site. Of these, #6 spans the northern property boundary as previously mentioned; #7 and 8 are adjacent to another; #9 thru 14 form a row and grow under crowded conditions beneath and amongst #16 thru 21; and #15 thru 23 form a row along Santa Monica Avenue.

The following are notes regarding a few trees which are adjacent to the site but do not qualify for inclusion in the inventory:

- There is a dead Monterey cypress located immediately north of the site near the street, and I label it as such on the map in Exhibit B.
- There is a N. California black walnut located on the western adjoining property and slightly overhangs the site; its trunk is inside the fence and near the street, and is located nearly 20 feet from the property line. Due to its trunk diameter being measured as 14.9 inches at 54 inches above grade, it was not inventoried for this report due being less than the threshold of 15 inches to qualify as a heritage tree.

3.0 SUITABILITY FOR TREE PRESERVATION

Each tree has been assigned either a "high," "moderate" or "low" suitability for preservation rating as a means to cumulatively measure its existing health, structural integrity, anticipated life span, remaining life expectancy, prognosis, location, size, particular species, tolerance to construction impacts, growing space, frequency of care needed, and safety to property and persons within striking distance. Descriptions of these ratings are presented below; the high category comprises no trees (0%), the moderate category 13 (57%), and the low category 10 (43%).

<u>High</u>: Applies to none.

These trees appear relatively healthy and structurally stable; have no apparent, significant health issues or structural defects; present a reasonably good potential for contributing long-term to the site; and seemingly require only periodic or regular care and monitoring to maintain their longevity and structural integrity. They are typically the most suitable for retaining and incorporating into the future landscape.

Moderate: Applies to #1-7 and 16-21.

These trees contribute to the site, but at levels less than those assigned a high suitability; might have health and/or structural issues which may or may not be reasonably addressed and properly mitigated; and frequent care is typically required for their remaining lifespan. They may be worth retaining if provided proper care, but not seemingly at significant expense or major design revisions.

Low: Applies to #8-15, 22 and 23.

These trees have significant health and/or structural issues expected to worsen regardless of tree care measures employed (i.e. beyond likely recovery). As a general guideline, they are not suitable to incorporate into the future landscape, and removal is the appropriate action regardless of future redevelopment. Any which are retained require highly frequent pruning, monitoring, and care throughout their remaining lifespans to minimize any safety threat they present to persons and property within striking distance.

4.0 PROPOSED TREE DISPOSITION

Implementing the proposed design requires removing all 23 trees. For the 21 which are of heritage tree status, namely #1-14 and 16-22, information regarding each is summarized in the table below (and continued on the next page), which presents their trunk diameter, underlying reason(s) for removal, supporting City removal criteria, ² and appraised value.

Table 2 - Heritage Tree Removal Summary

| TREE # | NAME | DIAM (in.) | REASON(S) FOR REMOVAL | CITY RMVL CRITERIA | APPRAISED VALUE |
|--------|--------------------|---------------------------|--|-----------------------|-----------------|
| 1 | Saucer magnolia | 30 | Public & ADA parking, Bldg A construction, G & D | 5 | \$10,900 |
| 2 | American sweetgum | 27 | Bldg A | 5 | \$10,600 |
| 3 | American sweetgum | 20 | Bldg A | 5 | \$4,800 |
| 4 | American sweetgum | 25 | UG garage, drive lanes | 5 | \$6,100 |
| 5 | American sweetgum | 19 UG garage, drive lanes | | 5 | \$3,500 |
| 6 | N. CA black walnut | 49 | UG garage, Bldg B | 5 | \$27,400 |
| 7 | Littleleaf linden | 21 | UG garage, Bldg B | 5 | \$8,000 |
| 8 | Littleleaf linden | 25 | UG garage, Bldg B | 5 | \$5,700 |
| 9 | Olive tree | 22 | UG garage, Bldg B | 3, 5 | \$1,000 |
| 10 | Olive tree | 19 | UG garage, Bldg B | 1, 5 | \$200 |
| 11 | Olive tree | 19 | UG garage, Bldg B | 3, 5 | \$1,200 |
| 12 | Olive tree | 25 | UG garage, Bldg B | 1, 5 | \$300 |
| 13 | Olive tree | 23 | UG garage, Bldg B | 3, 5 | \$1,100 |

² Section 13.24.050(a) of the Menlo Park Municipal Code specifies removal criteria applicable towards obtaining a heritage tree removal permit (for reference, criteria #1 applies to a dead tree, #3 to health, and #5 to development).

_

TOTAL: \$123,800

Table continued:

| TREE # | NAME | DIAM (in.) | REASON(S) FOR REMOVAL | CITY RMVL CRITERIA | APPRAISED VALUE |
|-----------|------------------|---------------|-----------------------------|-----------------------|-----------------|
| 14 | Olive tree | 22 | UG garage, Bldg B | 3, 5 | \$1,600 |
| 16 | Coast live oak | 25 | Bldg B, G & D, Wlkwy | 5 | \$5,600 |
| 17 | Monterey cypress | 48 | Bldg B, G & D, Wlkwy | 5 | \$16,700 |
| 18 | Monterey cypress | 29 | Bldg B, G & D, Wlkwy | 5 | \$4,600 |
| 19 | Monterey cypress | 25 | Bldg B, G & D, Wlkwy | 5 | \$3,400 |
| 20 | Coast live oak | 25 | Bldg B, G & D, Wlkwy | 5 | \$3,600 |
| 21 | Coast live oak | 29 | Bldg B, G & D, Wlkwy | 5 | \$6,000 |
| 22 | Monterey cypress | 20 | Public & ADA parking, G & D | 3, 5 | \$1,500 |

DIAM = Diameter

Wlky = Walkway

UG = Underground

G & D = Grading & Drainage

5.0 APPRAISED TREE VALUES AND REPLACEMENTS

The 21 heritage trees were appraised, and the individual values are listed within the last columns of Exhibits A and D. Combined, their total value equals \$123,800.

Values are calculated using the *Trunk Formula Technique* derived from the 2019 *Guide for Plant Appraisal*, 10th *Edition*, and in conjunction with the *Species Classification and Group Assignment*, 2004 (published by the Western Chapter of the ISA). This method considers the cost of the largest commonly tree available from a nursery, plus the increase in value due to the larger size of the tree being appraised. The amount is then adjusted or depreciated by numerous factors, such as the particular tree's condition, functional and external limitations.

Pursuant to Section $13.24.090(b)^3$ of the Menlo Park Municipal Code, replacements to mitigate the removal of heritage trees shall be of a size and amount equal to or in excess of the trees' appraised values, equating to \$46,600. For reference, the City's *Heritage Tree Ordinance Administrative Guidelines* establishes the following replacement values to determine the amount and size of new trees to mitigate heritage tree removal: 5-gallon container = \$100; 15-gallon container = \$200; 24-inch box = \$400; 36-inch box = \$1,200; 48-inch box = \$5,000; and 60-inch box = \$7,000.

³ Specific language from Section 13.24.090(b) is as follows: "For development-related removals, the applicant shall provide replacement heritage trees on site in an amount equivalent to the appraised value of the removed heritage tree. The city arborist shall approve the location, size, species and number of replacement heritage trees. If the appraised value of the removed heritage tree exceeds the value of the replacement heritage trees that can be accommodated on the property, the applicant shall pay the difference in value to the heritage tree fund."

6.0 ASSUMPTIONS AND LIMITING CONDITIONS

- Information presented herein covers only inventoried trees, and reflects their size, condition, and areas viewed from the subject site and adjoining streets and sidewalks on 11/27/23, 12/2/23 and 4/12/24. Observations were performed visually and obtained from the ground without any probing, coring, dissecting or excavating.
- The documented condition and suitability ratings of dormant trees are subject to change once they can be observed following their annual regrowth of leaves.
- The assignment pertains solely to trees listed in Exhibit A. I hold no opinion towards other trees on or surrounding the project area.
- I cannot provide a guarantee or warranty, expressed or implied, that deficiencies or problems of any trees or property in question may not arise in the future.
- No assurance can be offered that if all my recommendations and precautionary measures (verbal or in writing) are accepted and followed that the desired results may be achieved.
- I cannot guarantee or be responsible for the accuracy of information provided by others.
- I assume no responsibility for the means and methods used by any person or company implementing recommendations presented in this report.
- Information presented herein represents my opinion. As such, my fee is in no way contingent upon the reporting of a specified finding, conclusion or value.
- Numbers shown on the site map in Exhibit B are solely intended to represent a tree's general location and shall not be construed as surveyed points.
- This report is proprietary to me and may not be copied or reproduced in whole or part without prior written consent. It has been prepared for the sole and exclusive use of the parties to whom submitted.

• If any part of this report or copy thereof be lost or altered, the entire evaluation shall be invalid.

Prepared By:

David L. Babby

Registered Consulting Arborist® #399

Board-Certified Master Arborist® #WE-4001B

CA Licensed Tree Service Contractor #796763 (C61/D49)





Date: December 13, 2024

EXHIBIT A:

TREE INVENTORY TABLE

(four sheets)

| | | | SIZE | | COND | ITION | | REGUI | LATED | | |
|---------------------|---|----------------------|--------------|---------------------|---|--|---|---------------|-------------|--------|-------------------------------------|
| TREE/ TAG NO. | TREE NAME | Trunk Diameter (in.) | Height (ft.) | Canopy Spread (ft.) | Overall Percentage (100%=Best, 0%=Worst) | Overall Description (Good/Fair/Poor/Dead) | Suitability for Preservation (High/Moderate/Low) | Heritage Tree | Street Tree | Remove | Appraised Value (Heritage Trees) |
| 1 | Saucer magnolia (Magnolia × soulangeana) | 30 | 25 | 35 | 50% | Fair | Moderate | X | - | X | \$10,900 |
| | Comments: | | _ | | • . | | ing and exter | , | - / | | |

Comments: One-sided form grows vertical along adjacent building and extends low (<6' high) over opposite pedestrian/parking side. Beneath high-voltage wires, and phone/cable wires are routed thru top. Multi-stem form with narrow attachments and bark inclusion. Canopy spread is 40' N to S (parallel to street) and 25' E to W (building to street). Within a planter covered by landscape fabric and river rock, and surrounded by pavement, a wood bench and posts.

| | American sweetgum | | | | | | | | | | |
|---|---------------------------|----|----|----|-----|------|----------|---|---|---|----------|
| 2 | (Liquidambar styraciflua) | 27 | 55 | 35 | 60% | Fair | Moderate | X | - | X | \$10,600 |

Comments: Multiple tops. Low canopy, and has a broken limb suspended in upper section. Buried root collar. History of branch failure. Base is within 2' of adjacent driveway. Has a large, old decaying wound at union of multiple leaders.

| | American sweetgum | | | | | | | | | | |
|---|---------------------------|----|----|----|-----|------|----------|---|---|---|---------|
| 3 | (Liquidambar styraciflua) | 20 | 45 | 35 | 50% | Fair | Moderate | X | - | X | \$4,800 |

Comments: Multiple tops. Low canopy with a history of limb failure, including a broken limb suspended midsection. Buried root collar. Sinuous trunk and a thin top. Base is 1' from adjacent driveway.

| | American sweetgum | | | | | | | | | | |
|---|----------------------------|----|----|----|-----|------|----------|---|---|---|---------|
| 4 | (Liquidambar styraciflua) | 25 | 65 | 35 | 40% | Poor | Moderate | X | - | X | \$6,100 |

Comments: Has a mostly one-sided canopy with excessive limb weight and a leggy top. Extensively pruned in past, including a few large wounds along the NW side. Adjacent to building, and asphalt and base material cover root zone in other directions. Extensively pruned in past.

| | American sweetgum | | | | | | | | | | |
|---|---------------------------|----|----|----|-----|------|----------|---|---|---|---------|
| 5 | (Liquidambar styraciflua) | 19 | 45 | 30 | 40% | Poor | Moderate | X | - | X | \$3,500 |

Comments: Along the trunk's NW side at 6' high is a large decaying wound. Narrow, asymmetrical form with a high canopy along S side due to past limb failure. Extensively pruned in past. Adjacent to building, and asphalt and base material cover root zone in other directions. Also has a buried root collar.

| | N. California black walnut | | | | | | | | | | |
|---|----------------------------|----|----|----|-----|------|----------|---|---|---|----------|
| 6 | (Juglans hindsii) | 49 | 60 | 90 | 40% | Poor | Moderate | X | - | X | \$27,400 |

Comments: Trunks spans property line, and is located on opposing side of fence (large cutout for trunk).

Unmaintained with *extensive* deadwood and history of limb failure throughout, including many broken limbs and branches suspended in thin canopy. Codominant leaders with a wide attachment emerge at 8' high. Low branches along perimeter reach/near ground. Would require substantial pruning if area beneath or within striking distance was to become occupied.

Project: MPFS No. 1

Prepared for: Menlo Park Fire Protection District Prepared by: David L. Babby, RCA #399

| | | | SIZE | | COND | ITION | | REGU | LATED | | | | |
|--|---|----------------------|--------------|---------------------|---|--|---|---------------|-------------|--------|-------------------------------------|--|--|
| TREE/ TAG NO. | TREE NAME | Trunk Diameter (in.) | Height (ft.) | Canopy Spread (ft.) | Overall Percentage (100%=Best, 0%=Worst) | Overall Description (Good/Fair/Poor/Dead) | Suitability for Preservation (High/Moderate/Low) | Heritage Tree | Street Tree | Remove | Appraised Value (Heritage Trees) | | |
| 7 | Littleleaf linden (<i>Tilia cordata</i>) | 21 | 35 | 40 | 60% | Fair | Moderate | X | _ | X | \$8,000 | | |
| | , | | | | | | crown. Dead | | l history o | II. | | | |
| 8 | Littleleaf linden (<i>Tilia cordata</i>) | 25 | 35 | 35 | 30% | Poor | Low | X | - | X | \$5,700 | | |
| Comments: One-sided crown grows towards SW. At 3.5' high is a large decaying hollow which ascends to 10' high. There is a large old stump near base. Lower canopy contains extensive watersprouts. | | | | | | | | | | | | | |
| 9 | Olive tree (Olea europaea) | 22 | 45 | 20 | 20% | Poor | Low | X | - | X | \$1,000 | | |
| | Comments: | | - | | • | | ressed benea failed along | | | - | ru #21's | | |
| 10 | Olive tree (Olea europaea) | 19 | 35 | 10 | 5% | Dead | Low | X | - | X | \$200 | | |
| | Comments: | | | | - | | ranches along | | | | | | |
| 11 | Olive tree (Olea europaea) | 19 | 30 | 30 | 30% | Poor | Low | X | - | X | \$1,200 | | |
| | Comments: | | | | - | • | W. Has large e, has a vertic | | | | | | |
| 12 | Olive tree (Olea europaea) | 25 | 35 | 10 | 5% | Dead | Low | X | - | X | \$300 | | |
| | Comments: | | | | | | s W (conside gh asymmetr | | | | | | |
| 13 | Olive tree (Olea europaea) | 23 | 35 | 35 | 20% | Poor | Low | X | - | X | \$1,100 | | |

Comments: Suppressed beneath and at edge of #16's canopy. One-sided canopy with heavy limb weight and large deadwood throughout. Significant decline - roughly 60% dead. History of limb failure. Low branches near 3.5' above grade.

Project: MPFS No. 1

Prepared for: Menlo Park Fire Protection District Prepared by: David L. Babby, RCA #399

SIZE

CONDITION

REGULATED

| TREE/ TAG NO. | TREE NAME | Trunk Diameter (in.) | Height (ft.) | Canopy Spread (ft.) | Overall Percentage (100%=Best, 0%=Worst) | Overall Description (Good/Fair/Poor/Dead) | Suitability for Preservation (High/Moderate/Low) | Heritage Tree | Street Tree | Remove | Appraised Value (Heritage Trees) | | |
|---------------------|---|---|--------------|---------------------|---|--|---|--|-------------|---------|-------------------------------------|--|--|
| 14 | TREE NAME Cost live oak (Quercus agrifolia) Comments: Formed by two trunks emerging at grade, one measuring 4" and another 6.2" - both represent suckers. Asymmetrical growth towards street and high-voltage wires. Coast live oak (Quercus agrifolia) 25 55 50 50% Fair Moderate X - X \$5,600 | | | | | | | | | | | | |
| | Comments: | | | | | | | X - X \$1,600 Inced by large and extensive deadwood tory of limb failure. X - Ind another 6.2" - both represent ge wires. Ite X - X \$5,600 Ite small limb which has been reduced e, and there is a dead limb along the N. | | | | | |
| 15 | | Comments: Grows partly beneath #6's canopy. Significant decline, evidenced by large and extensive deadwood throughout, as well as a large vertical crack along trunk. History of limb failure. ast live oak rous agrifolia) Comments: Formed by two trunks emerging at grade, one measuring 4" and another 6.2" - both represent suckers. Asymmetrical growth towards street and high-voltage wires. ast live oak rous agrifolia) 25 55 50 50% Fair Moderate X - X \$5,600 Comments: Beneath high-voltage wires, and section beneath consists of a small limb which has been reduced in height. The remaining section rises along the wires' W side, and there is a dead limb along the N. | | | | | | | | | | | |
| | Comments: | | - | | | | - | | .2" - both | represe | nt | | |
| 16 | | 25 | 55 | 50 | 50% | Fair | Moderate | X | _ | X | \$1,600 deadwood | | |
| | Coast live oak (Quercus agrifolia) 6, 4 20 15 30% Poor Low - X - X - Comments: Formed by two trunks emerging at grade, one measuring 4" and another 6.2" - both represent suckers. Asymmetrical growth towards street and high-voltage wires. Coast live oak (Quercus agrifolia) 25 55 50 50% Fair Moderate X - X \$5,600 Comments: Beneath high-voltage wires, and section beneath consists of a small limb which has been reduced in height. The remaining section rises along the wires' W side, and there is a dead limb along the N. | | | | | | | | | | | | |

at 3.5' high. History of limb failure and has excessive limb weight.

| | Monterey cypress | | | | | | | | | | |
|----|-----------------------------|----|----|----|-----|------|----------|---|---|---|----------|
| 17 | (Hesperocyparis macrocarpa) | 48 | 45 | 40 | 40% | Poor | Moderate | X | - | X | \$16,700 |

Comments: Grows beneath high-voltage wires, and some branches rise above along the W side. Section of canopy beneath was reduced in height, in a sloped fashion, and has large deadwood throughout. Trunk grows against fence and bifurcates at 5.5' high. Low branches.

| I | | Monterey cypress | | | | | | | | | | |
|---|----|-----------------------------|----|----|----|-----|------|----------|---|---|---|---------|
| | 18 | (Hesperocyparis macrocarpa) | 29 | 55 | 30 | 30% | Poor | Moderate | X | - | X | \$4,600 |

Comments: Grows partly beneath high-voltage wires, and branches rise above W side. Section below wires was reduced in height (flat top), and canopy rising above has declined, being sparse, thin or dead. Has a very limited canopy. There is large basal depression along S side. Trunk bifurcates at 3.5' high; one vertical leader grows towards the wires and has a highly elevated canopy, and the opposing one divides into multiple limbs, one of which grows several feet against the vertical by several feet (with bark inclusion). Trunk is 3' from #19's. Live and dead ivy stems along trunk. Large deadwood, including a dead limb lying on #11.

| | Monterey cypress | | | | | | | | | | |
|----|-----------------------------|----|----|----|-----|------|----------|---|---|---|---------|
| 19 | (Hesperocyparis macrocarpa) | 25 | 30 | 30 | 30% | Poor | Moderate | X | - | X | \$3,400 |

Comments: Directly beneath high-voltage wires and reduced in height (flat top). Has a very limited and highly elevated canopy growing into #18 and 20. Branches surround utility pole and comm. wires. Trunk is 3' from #18's, and has a large, 2' tall x 8" wide x 6" deep decaying hollow along S side at 4.5' high. Large deadwood. Upper crown curves S towards horizontal. Old, dead ivy stems along trunk.

Project: MPFS No. 1

Prepared for: Menlo Park Fire Protection District Prepared by: David L. Babby, RCA #399

| | | | SIZE | | COND | ITION | | REGUI | LATED | | |
|---------------------|--|----------------------|--------------|---------------------|---|--|---|---------------|-------------|--------|-------------------------------------|
| TREE/ TAG NO. | TREE NAME | Trunk Diameter (in.) | Height (ft.) | Canopy Spread (ft.) | Overall Percentage (100%=Best, 0%=Worst) | Overall Description (Good/Fair/Poor/Dead) | Suitability for Preservation (High/Moderate/Low) | Heritage Tree | Street Tree | Remove | Appraised Value (Heritage Trees) |
| 20 | Coast live oak (Quercus agrifolia) | 25 | 50 | 45 | 40% | Poor | Moderate | X | X | X | \$3,600 |

Comments: Trunk partially extends into the public ROW (qualifying it as a street tree). Trunk grows against chain link fence and top rail, and is covered by ivy. Has a large old cut along street side. Section of canopy beneath high-voltage wires has been reduced, and along the W side, several limbs with rangy form rise above the wires.

| | Coast live oak | | | | | | | | | | |
|----|---------------------|----|----|----|-----|------|----------|---|---|---|---------|
| 21 | (Quercus agrifolia) | 29 | 45 | 45 | 40% | Poor | Moderate | X | - | X | \$6,000 |

Comments: Trunk leans SW away from #20, and its canopy is one-sided due to being pruned away from high-voltage wires. Has elongated branches extending a significant distance away from the trunk and at risk of failure due to excessive limb weight. A scaffold limb emerges from the trunk at 4' high, grows SW, and forms some bark inclusion at its attachment. Deadwood.

| | Monterey cypress | | | | | | | | | | |
|----|-----------------------------|----|----|----|-----|------|-----|---|---|---|---------|
| 22 | (Hesperocyparis macrocarpa) | 20 | 40 | 25 | 20% | Poor | Low | X | - | X | \$1,500 |

Comments: Located directly beneath high-voltage wires, the entire canopy being reduced in height (flat), except for one branch rising above the wires along the W side (and the branch top is dead with a smaller broken branch below). Elevated canopy with a very minor amount of foliage (at roughly 20%). Extensive deadwood along top and has many stubs. Its canopy is also suppressed beneath #21's. Trunk bifurcates at 5.5' high, and at the shared union is 8" of bark inclusion with a 3' long decay column below. Buried root collar from spoils.

| - | | | | | | | | | | | | |
|---|----|-----------------|----|----|----|-----|------|-----|---|---|---|---|
| | | Olive tree | | | | | | | | | | |
| | 23 | (Olea europaea) | 11 | 25 | 15 | 40% | Poor | Low | - | - | X | - |

Comments: Grows beneath and curves S away from #22. Beneath high-voltage wires and has been reduced in height sometime ago. Poor, highly asymmetrical form. Low branches over planter along street.

Project: MPFS No. 1

| David L | Rahhy | Registered | Consulting | Arhorist® |
|----------|--------|------------|------------|--------------------------------------|
| Duviu L. | Duoby, | Registerea | Consuming | $\Delta i \cup \cup i \cup i \cup i$ |

December 13, 2024

EXHIBIT B:

SITE MAP

(one sheet)




EXHIBIT C:

PHOTOGRAPHS

(five sheets)

Photo Index

Page C-1: Trees #1 thru 6 Page C-4: Trees #16 thru 21

Page C-2: Trees #7 thru 11 Page C-5: Trees #21 thru 23

Page C-3: Trees #12 thru 16









Menlo Park Fire Station No. 1; 300 Middlefield Road, Menlo Park Menlo Park Fire Protection District












Menlo Park Fire Station No. 1; 300 Middlefield Road, Menlo Park Menlo Park Fire Protection District



Menlo Park Fire Station No. 1; 300 Middlefield Road, Menlo Park Menlo Park Fire Protection District















Menlo Park Fire Station No. 1; 300 Middlefield Road, Menlo Park Menlo Park Fire Protection District













Menlo Park Fire Station No. 1; 300 Middlefield Road, Menlo Park Menlo Park Fire Protection District

Page C-5

EXHIBIT D:

TREE APPRAISAL CALCULATION TABLE

(two sheets)

HERITAGE TREE APPRAISAL CALCULATION TABLE

| | | SI | 7E | | | DEDDEC | IATION FA | VCTOPS | | |
|---------------------|---|----------------------|----------------------|---|--|--------------------------|------------------------|----------------------|------------------------|---|
| | | 31. | <u> </u> | | _ | DEPREC | IATION FA | ACTORS | | |
| TREE/ TAG NO. | TREE NAME | Trunk Diameter (in.) | Cross Sectional Area | Replacement Tree Basic Price (inch)² | Basic Cost (Cross Sectional Area x Basic Price) | Overall Condition Rating | Functional Limitations | External Limitations | Total Depreciated Cost | Appraised Value (round to nearest \$100) |
| 1 | Saucer magnolia (Magnolia × soulangeana) | 30 | 706.86 | 77.04 | \$54,456 | 50% | 40% | 100% | \$10,891 | \$10,900 |
| | American sweetgum | 27 | | | · | | 40% | 100% | | \$10,600 |
| 2 | (Liquidambar styraciflua) American sweetgum | | 572.56 | 77.04 | \$44,110 | 60% | | | \$10,586 | |
| 3 | (Liquidambar styraciflua) | 20 | 314.16 | 77.04 | \$24,203 | 50% | 40% | 100% | \$4,841 | \$4,800 |
| 4 | American sweetgum (Liquidambar styraciflua) | 25 | 490.88 | 77.04 | \$37,817 | 40% | 40% | 100% | \$6,051 | \$6,100 |
| 5 | American sweetgum (Liquidambar styraciflua) | 19 | 283.53 | 77.04 | \$21,843 | 40% | 40% | 100% | \$3,495 | \$3,500 |
| 6 | N. California black walnut (<i>Juglans hindsii</i>) | 49 | 1885.75 | 45.46 | \$85,726 | 40% | 80% | 100% | \$27,432 | \$27,400 |
| 7 | Littleleaf linden (Tilia cordata) | 21 | 346.36 | 77.04 | \$26,684 | 60% | 50% | 100% | \$8,005 | \$8,000 |
| 8 | Littleleaf linden (Tilia cordata) | 25 | 490.88 | 77.04 | \$37,817 | 30% | 50% | 100% | \$5,673 | \$5,700 |
| 9 | Olive tree (Olea europaea) | 22 | 380.13 | 45.46 | \$17,281 | 20% | 30% | 100% | \$1,037 | \$1,000 |
| 10 | Olive tree (Olea europaea) | 19 | 283.53 | 45.46 | \$12,889 | 5% | 30% | 100% | \$193 | \$200 |
| 11 | Olive tree (Olea europaea) | 19 | 283.53 | 45.46 | \$12,889 | 30% | 30% | 100% | \$1,160 | \$1,200 |
| 12 | Olive tree (Olea europaea) | 25 | 490.88 | 45.46 | \$22,315 | 5% | 30% | 100% | \$335 | \$300 |
| 13 | Olive tree (Olea europaea) | 23 | 415.48 | 45.46 | \$18,888 | 20% | 30% | 100% | \$1,133 | \$1,100 |
| 14 | Olive tree (Olea europaea) | 22 | 380.13 | 45.46 | \$17,281 | 30% | 30% | 100% | \$1,555 | \$1,600 |
| 16 | Coast live oak (Quercus agrifolia) | 25 | 490.88 | 45.46 | \$22,315 | 50% | 50% | 100% | \$5,579 | \$5,600 |
| | Monterey cypress | | | | | | | | | · |
| 17 | (Hesperocyparis macrocarpa) Monterey cypress | 48 | 1809.56 | 77.04 | \$139,409 | 40% | 30% | 100% | \$16,729 | \$16,700 |
| 18 | (Hesperocyparis macrocarpa) | 29 | 660.52 | 77.04 | \$50,887 | 30% | 30% | 100% | \$4,580 | \$4,600 |

Project: Menlo Park Fire Station No. 1 Prepared for: Menlo Park Fire Protection District Prepared by: David L. Babby, RCA #399

HERITAGE TREE APPRAISAL CALCULATION TABLE

| | | SI | ZE | | | DEPREC | ATION FA | ACTORS | | |
|---------------------|---|----------------------|----------------------|---|--|--------------------------|------------------------|----------------------|------------------------|---|
| TREE/ TAG NO. | TREE NAME | Trunk Diameter (in.) | Cross Sectional Area | Replacement Tree Basic Price (inch)² | Basic Cost (Cross Sectional Area x Basic Price) | Overall Condition Rating | Functional Limitations | External Limitations | Total Depreciated Cost | Appraised Value (round to nearest \$100) |
| 19 | Monterey cypress (Hesperocyparis macrocarpa) | 25 | 490.88 | 77.04 | \$37,817 | 30% | 30% | 100% | \$3,404 | \$3,400 |
| 20 | Coast live oak (Quercus agrifolia) | 25 | 490.88 | 45.46 | \$22,315 | 40% | 40% | 100% | \$3,570 | \$3,600 |
| 21 | Coast live oak (Quercus agrifolia) | 29 | 660.52 | 45.46 | \$30,027 | 40% | 50% | 100% | \$6,005 | \$6,000 |
| 22 | Monterey cypress (Hesperocyparis macrocarpa) | 20 | 314.16 | 77.04 | \$24,203 | 20% | 30% | 100% | \$1,452 | \$1,500 |

Project: Menlo Park Fire Station No. 1 Prepared for: Menlo Park Fire Protection District Prepared by: David L. Babby, RCA #399

ARBORIST REPORT

MENLO PARK TEMPORARY FIRE STATION NO. 1 114 SANTA MARGARITA AVE MENLO PARK, CA (APN 062-272-610)

Submitted to:

Menlo Park Fire Protection District 170 Middlefield Road Menlo Park, CA 94025

Prepared by:

David L. Babby

Registered Consulting Arborist® #399

Board-Certified Master Arborist® #WE-4001B

Menlo Park Business License #73953

July 18, 2025

TABLE OF CONTENTS

| <u>SECTION</u> | <u>TITLE</u> | <u>PAGE</u> |
|----------------|---|-------------|
| 1.0 | INTRODUCTION | 1 |
| 2.0 | TREE DESCRIPTION | 2 |
| 3.0 | SUITABILITY FOR PRESERVATION | 3 |
| 4.0 | IMPACT ANALYSIS | 4 |
| 5.0 | APPRAISED TREE VALUES AND REPLACEMENTS | 6 |
| 6.0 | TREE PROTECTION MEASURES | 7 |
| 6.1 | Design Guidelines | 7 |
| 6.2 | Before Demolition, Grading and Construction | 8 |
| 6.3 | During Demolition, Grading and Construction | 10 |
| 7.0 | ASSUMPTIONS AND LIMITING CONDITIONS | 12 |

EXHIBITS

| <u>EXHIBIT</u> | <u>TITLE</u> |
|----------------|---|
| Α | TREE INVENTORY TABLE (one sheet) |
| В | SITE MAP (one sheet) |
| С | PHOTOGRAPHS (four sheets) |
| D | HERITAGE TREE APPRAISAL CALCULATION TABLE (one sheet) |

1.0 INTRODUCTION

Menlo Park Fire Protection District plans to utilize 114 Santa Margarita Avenue as a temporary fire station during the construction of Fire Station No. 1 at 300 Middlefield Road. The project is named Menlo Park Temp Fire Station No. 1, and involves demolishing the existing home and sections of asphalt pavement; installing a new driveway and pavement; and placing a fire station trailer, apparatus bay tent, utility trailer and Conex box. Due to the site being occupied by four heritage trees, the district has retained me to prepare this report, and specific tasks assigned to execute are as follows:

- Visit the site on 4/25/25 and 6/27/25 to document information of the four trees, which account for all located inside the property and with trunk diameters of ≥6 inches (at 54 inches above grade); heritage trees on neighboring properties if they overhang the site or are within 10 times their trunk diameters; and those within the public ROW, either along the frontage or within 30 feet from the boundaries.
- Measure each trunk diameter pursuant to 13.24.020(5) of the Menlo Park Municipal Code; diameters are rounded to the nearest whole number.
- Estimate tree heights and average canopy spreads (rounded to the nearest fifth).
- Obtain photographs of each tree; see Exhibit C.
- Evaluate each tree's health, structure and form, and assign an overall condition rating.
- Determine each tree's suitability for preservation (e.g. high, moderate or low).
- Appraise their monetary values.
- Assign numbers 24 thru 27, which represent a continuation of the sequential pattern already established for the future Fire Station No. 1.
- Nail round silver tags with engraved, corresponding numbers onto each trunk.
- Plot each tree number onto the site map in Exhibit B (base map is a copy of the *Topography Map* prepared by Hanna Brunetti, dated July 2025).
- Review an undated aerial map showing the proposed driveway and trailer configuration, and discuss potential options with the district to limit impacts while achieving required project parameters for the temporary station.
- Prepare a written report presenting the above information, and email a copy as a PDF document.

_

¹ Section 13.24.020(5) of the Menlo Park Municipal Code defines a heritage tree as follows: [1] any oak native to California and having a trunk diameter of ≥10" at 54" above grade; [2] any other tree having a trunk diameter ≥15" at 54" above grade; and [3] any multi-trunk tree ≥12' tall and with a trunk diameter ≥15" below the main union of trunks, except when the trunks' union occurs below grade, and in which case, each trunk is considered a stand-alone tree.

2.0 TREE DESCRIPTION

The four (4) trees include two coast redwoods (#24 and 26) and two shamel ash (#25 and 27). Tree #24 is located in front of the existing residence; #25 is along the front, west side of the property; #26 is along the rear, southern boundary; and #27 is along the rear, eastern boundary. Note that all compass references mentioned in this report consider project north being towards Santa Margarita Avenue.

The trunks of #26 and 27 also span over the respective south and east boundaries, and as such, are regarded as being partially offsite and jointly-owned.

Specific information regarding each tree is presented within the table in Exhibit A. The trees' numbers and locations can be viewed on the site map in Exhibit B, and photographs are presented in Exhibit C.

All four qualify as heritage trees pursuant to Section 13.24.020(5)(A) of the Menlo Park Municipal Code due to having trunk diameters exceeding the minimal trunk diameter threshold of 15 inches for trees other than native oaks.

A summary of the trees' sizes and conditions is as follows:

- #24 (redwood): 66" trunk diameter, 100' tall, 50' canopy spread, fair health, poor structure and good form.
- #25 (ash): 44" trunk diameter, 60' tall, 60' canopy spread, good health, poor structure and fair form.
- #26 (redwood): 72" trunk diameter, 120' tall, 65' canopy spread, poor health, good structure and good form.
- #27 (ash): 28" trunk diameter, 45' tall, 45' canopy spread, fair health, poor structure and fair form.

3.0 SUITABILITY FOR TREE PRESERVATION

Each tree has been assigned either a "high," "moderate" or "low" suitability for preservation rating as a means to cumulatively measure its existing health, structural integrity, anticipated life span, remaining life expectancy, prognosis, location, size, particular species, tolerance to construction impacts, growing space, frequency of care needed, and safety to property and persons within striking distance. Descriptions of these ratings are presented below, and the high category comprises no trees (0%), the moderate category three (75%), and the low category one (25%).

<u>High</u>: Applies to none.

These trees appear relatively healthy and structurally stable; have no apparent, significant health issues or structural defects; present a reasonably good potential for contributing long-term to the site; and seemingly require only periodic or regular care and monitoring to maintain their longevity and structural integrity. They are typically the most suitable for retaining and incorporating into the future landscape.

Moderate: Applies to #24 thru 26.

These trees contribute to the site, but at levels less than those assigned a high suitability; might have health and/or structural issues which may or may not be reasonably addressed and properly mitigated; and frequent care is typically required for their remaining lifespan. They may be worth retaining if provided proper care, but not seemingly at significant expense or major design revisions.

Low: Applies to #27.

This ash tree has significant health and/or structural issues which cannot be reasonably mitigated. As a general guideline, it is unsuitable to incorporate into the future landscape, and removal is the appropriate action regardless of the upcoming site renovation. If retained, highly frequent pruning, monitoring, and care is needed throughout its remaining lifespan to minimize any safety threat to persons and property within striking distance.

4.0 IMPACT ANALYSIS

PROPOSED REMOVAL (#24)

Implementing the proposed design requires removing coast redwood #24 due to its trunk being in conflict with the future driveway proposed along the lot's eastern section. The driveway's proposed 20-foot wide entry is necessitated and constrained by the lot size and dimensions, and requires being located and configured so the fire station trailer and apparatus bay tent can be properly placed to provide sufficient space for the fire engine and ambulance to travel and park. Note that a heritage tree removal application will be needed, and would occur under City removal criteria #5.²

An additional noteworthy item includes it having a significant structural defect where the main trunk bifurcates into codominant leaders at 12 feet high, and at their shared union, a weak attachment is formed. Of particular concern is the attachment being located so low in its crown, increasing the potential for one or both leaders to break. Measures to address and potentially abate this defect include significantly reducing the height, installing a cable support, and performing highly frequent inspections and maintenance. The height reduction component, however, would dramatically and adversely change its appearance and function to the extent that removal becomes a practical and viable option, regardless of the proposed project.

If retention is required, design considerations to achieve some minimal level of protection are listed below, and applies to the area up to the existing home's foundation, up to the existing asphalt sidewalk, up to the property boundary, and 20 feet from its trunk in all other directions (i.e. its Tree Protection Zone, or TPZ, hereinafter). Note that even with close adherence to the below design considerations, the tree may still be irreparably impacted due to the amount of root area affected, and the substantial compaction and load requirements of a fire engine.

a. The nearest driveway edge should be at least 6.5 feet from the trunk's closest side (which represents the closest edge of the existing walkway).

_

² Section 13.24.050(a) of the City Code specifies removal criteria applicable towards obtaining a heritage tree removal permit (for reference, criteria #1 applies to a dead tree, #3 to health and #5 to development).

- b. The driveway surface, base material, edging and forms should be established entirely above-grade (i.e. no-dig design), and direct compaction of soil grade must be avoided. These specifications can be achieved by utilizing Tensar[®] BX Geogrid pinned on existing soil grade, then base material spread on top and compacted to the necessary proctor density. A possible superior design includes omitting base material altogether, and designing a thickened and super-reinforced, concrete driveway surface. Soil fill used to bevel the top of drive to grade must be sharply sloped and not be piled against the trunk. Also, ensure the approach can rise sharply from the street to achieve the raised elevation.
- c. In the event base material is needed within the TPZ and requires being placing beneath existing grade, it shall consist of CU-Structural Soil.™ The process involved with installing this material is time consuming, with the initial step utilizing an Air-Spade® to remove soil to the required subgrade depth, then manually spreading the material around all exposed roots ≥1-inch in diameter. Subgrade must not be directly compacted, but the structural soil can be compacted to the necessary proctor density. The driveway surface would then be poured on top. There may also be the need to manually remove any existing base underlying the artificial turf.

RETAINED TREES (#25 thru 27)

Protecting #25 thru 27 appears highly probable by retaining existing asphalt paving³ and avoiding trenching or other ground disturbance within their following TPZs (which are also delineated on the map in Exhibit B):

- #25: 15 feet N, S and E from its trunk; up to the existing fence; and a rectangular pattern in all other directions.
- #26: 20 feet N, S and E, and a rectangular pattern in all other directions.
- #27: 12 feet N, S and E from its trunk; up to the existing home's foundation; and a rectangular pattern in all other directions.

Additional protection measures are presented within Section 6.0 of this report, and should be carefully followed and incorporated into the design.

Menlo Park Temp Fire Station No. 1; 114 Santa Margarita Ave., Menlo Park Menlo Park Fire Protection District

³ The application of seal coat or slurry seal of existing asphalt is acceptable provided no materials are placed or spread on unpaved ground within a TPZ.

5.0 APPRAISED TREE VALUES AND REPLACEMENTS

The four heritage trees were appraised, and the individual values are listed within the last columns of Exhibits A and D. Combined, their total value equals \$82,900.

Values are calculated using the *Trunk Formula Technique* derived from the 2019 *Guide for Plant Appraisal*, 10th *Edition*, and in conjunction with the *Species Classification and Group Assignment*, 2004 (published by the Western Chapter of the ISA). This method considers the cost of the largest commonly tree available from a nursery, plus the increase in value due to the larger size of the tree being appraised. The amount is then adjusted or depreciated by numerous factors, such as the particular tree's condition, functional and external limitations.

Pursuant to Section 13.24.090(b)⁴ of the Menlo Park Municipal Code, replacements to mitigate the removal of a heritage tree shall be of a size and amount equal to or in excess of its appraised value. For removing heritage tree #24, replacements would need to equal or exceed its value of \$29,900. As reference, the City's *Heritage Tree Ordinance Administrative Guidelines* establishes the following replacement values to determine the amount and size of new trees to mitigate heritage tree removal: 5-gallon container = \$100; 15-gallon container = \$200; 24-inch box = \$400; 36-inch box = \$1,200; 48-inch box = \$5,000; and 60-inch box = \$7,000.

-

⁴ Specific language from Section 13.24.090(b) is as follows: "For development-related removals, the applicant shall provide replacement heritage trees on site in an amount equivalent to the appraised value of the removed heritage tree. The city arborist shall approve the location, size, species and number of replacement heritage trees. If the appraised value of the removed heritage tree exceeds the value of the replacement heritage trees that can be accommodated on the property, the applicant shall pay the difference in value to the heritage tree fund."

6.0 TREE PROTECTION MEASURES

Recommendations presented within this section consider the proposed design, and serve as protection measures to help mitigate or avoid impacts to heritage trees being retained. They should be carefully followed and incorporated into project plans, and I (hereinafter "project arborist") should be consulted in the event any cannot be feasibly implemented. Please note that all referenced distances from trunks are intended to be from their outermost perimeter near soil grade.

6.1 Design Guidelines

- 1. Tree Protections Zones (TPZs) are listed within Section 4.0 and are also delineated on the map in Exhibit B. Where within these setbacks, all approved work must be manually performed without the operation or travel of heavy equipment, including small tractors; highly mitigated (e.g. hand-digging and root retention); and conducted under supervision of the project arborist. In general, a TPZ is intended to restrict or highly limit the following activities within specified distances: removing asphalt, trenching, soil surface scraping, compaction, mass/finish-grading, overexcavation, subexcavation, tilling, ripping, swales, bioswales, storm drains, dissipaters, equipment cleaning, removal of underground utilities and vaults, altering existing water/drainage flows, stockpiling and dumping of materials, and equipment and vehicle operation. In the event an impact encroaches slightly within a setback, it can be reviewed on a case-by-case basis by the project arborist to determine whether measures can sufficiently mitigate impacts to less-than-significant levels.
- 2. On all site-related plans, add each trunk location and assigned number and delineate their TPZs reflected in Exhibit B. Also, include the following note (or notes) on the demolition and site plans: all protection measures specified within the Arborist Report shall be followed; existing asphalt within the TPZs shall remain; no ground work is permitted within TPZs, including trenching for utilities or storm drains; and the placement of temporary facilities within a TPZ shall be on existing asphalt only, require no digging for footings, supervised by the project arborist.
- 3. Avoid specifying hardscape over existing unpaved areas within a TPZ.

- 4. Should erosion control measures be required, add a note onto the related plan specifying that any installed within a TPZ shall be established up against or beyond curbs, and require a maximum vertical soil cut of 2 inches for their embedment.
- 5. The temporary and permanent drainage design, including downspouts, should not require water being discharged towards a tree's trunk.
- 6. Adhere to the following additional guidelines for any new landscape:
 - a. Establish irrigation and lighting features beyond TPZs (e.g. main line, lateral lines, valve boxes, wiring, electrical lines, controllers, sensors, backflow preventers and meters). For any line(s) where this is not feasible, route them in a radial direction to a tree's trunk, and terminate a specific distance from a trunk (versus crossing past it). The routes and overall layout should be reviewed with the project arborist prior to any trenching or excavation occurring, and note that any open trench may require being dug using an AirSpade. Irrigation inside TPZs should consist of Netafim soaker hoses, or equivalent, laid on grade and covered by mulch. Additionally, header lines should terminate beyond TPZs.
 - b. Avoid tilling, ripping and compaction within TPZs.
 - c. Establish any bender board or other edging material within TPZs to be on top of existing soil grade (such as by using vertical stakes).
 - d. Utilize a 3- to 4-inch layer of coarse wood chips or other high-quality mulch for new ground cover beneath canopies (avoid using gorilla hair, bark or rock, stone, gravel, black plastic or other synthetic ground cover). Do not pile mulch against trunk, rather taper the depth to 1/2- or 1/4-inch at the trunk.
- 7. Avoid specifying to apply herbicide in a TPZ; any used on site should be labeled for safe use near trees. Also, liming shall not occur within 50 feet from a tree's canopy.

6.2 Before Demolition, Grading and Construction

8. Conduct a site meeting between the general contractor and project arborist several weeks prior to demolition for the purpose of reviewing staked locations, tree fencing, routes of access, watering, trenching, staging and other protection measures presented in this report. These items are detailed within this report.

- 9. Provide supplemental and potable over unpaved ground beneath their canopies, beginning as soon as possible prior to demolition, and continuing throughout construction. The methodology, frequency and amounts can be reviewed with the project arborist, and possible methodologies include flooding the ground or deep-root injection.
- 10. Manually spread a 4- to 6-inch layer of coarse wood chips (½- to ¾-inch in size) over unpaved ground within TPZs of #25 and 26 (up to, but not piled against their trunks). The chips shall be derived from a tree-service company and approved by the project arborist beforehand.
- 11. Prior to demolition and mobilizing equipment to the site, install tree protection fencing to restrict access inside unpaved areas of TPZs. For this particular site and project, due to the extent of existing pavement and size of the trees' root crowns at the asphalt edges (where driven posts would adversely impact the trees), fencing should consist of 6-foot tall chain link panels mounted on concrete blocks or metals stands and made immobile. It shall be kept in place and upright throughout construction, and removed or modified only under the knowledge and direct consent of the project arborist. Note that fencing must remain on existing asphalt and not encroach inside unpaved areas of TPZs, and the sections of existing paved areas of TPZs can be utilized during construction to provide space to temporarily place materials; parking vehicles; operate equipment; and accommodate the fire station trailers, apparatus bay tent, and Conex box.
- 12. Signs of 8.5- by 11-inch in size (minimum) shall be affixed to each long side of fence and contain the following language: "TREE PROTECTION FENCE DO NOT MOVE OR REMOVE WITHOUT APPROVAL BY THE CITY ARBORIST."
- 13. Once tree fencing has been installed, the project arborist shall revisit the site to inspect and confirm protection adheres to instructions within this report. A verification letter, to include photos, shall be subsequently prepared. Also, note that prior to tree protection fencing being removed towards the end of the project, a final inspection by the City arborist is required.

14. The project arborist must also regularly inspect the project site to evaluate the effectiveness of tree protection measures, as well as recommend any additional measures, treatment and care. Inspections shall occur at least every four weeks, and continue through final inspection. Additional site visits may be necessary to observe/advise regarding tree care and/or services. A summary of pertinent observations and recommendations shall coincide with each inspection.

6.3 During Demolition, Grading and Construction

- 15. Any authorized work inside a TPZ shall be by foot-traffic only, manually performed under supervision by the project arborist, and not require the use of heavy equipment or tractors.
- 16. The approved demolition of existing hardscape, landscape or other features within a TPZ shall be carefully performed to avoid damaging a tree's trunk, canopy, soil and roots within a TPZ, including ground underlying existing features.
- 17. During any seal coat or slurry seal of existing asphalt, avoid the overpour or placement of materials on unpaved ground within a TPZ.
- 18. Prior to mechanical excavation within 5 feet from a TPZ, manually dig a 1-foot wide trench along the cut edge, to include overexcavation, and down to the required subgrade depth or 18 inches, whichever is shallower. Advise the project arborist when this work is scheduled so observations of cut roots can be made. Exposed roots shall be cleanly severed and their surfaces kept continually moist, by draping burlap over the cut face and applying water daily or twice daily.
- 19. Existing broken asphalt at the bases of #26 and 27 should manually peeled back using a shovel or crowbar (and leaving any underlying base in place).
- 20. Great care must be taken by all equipment operators to position their equipment and avoid trunks and branches, including the scorching of foliage. Any tree damage or injury should be immediately reported to the project arborist.

- 21. Avoid damaging or cutting roots with diameters of ≥2 inches without prior assessment by the project arborist. Should roots of this size be encountered, within one hour of exposure, they should either be covered by burlap that remains continually moist until the root is covered by soil. If they are approved for cutting, cleanly severe at 90° to the angle of root growth against the cut line (using loppers or a sharp hand saw), and then immediately after, the cut end either buried with soil or covered by a plastic sandwich bag (and secured using a rubber band, and removed just before backfilling). Roots encountered with diameters <2 inches and requiring removal can be cleanly severed at right angles to the direction of root growth (although those originating from the oaks and have diameters between 1 to 2 inches should be approached on a case-by-case basis).
- 22. Spoils created during digging shall not be piled or spread on unpaved ground within a TPZ. If essential, spoils can be temporarily piled on plywood or a tarp.
- 23. Avoid using tree trunks as winch supports for moving or lifting heavy loads, as well as for tying rope, cables, chains or other items around.
- 24. Any pruning shall be highly selective, targeted, and performed under direction of the project arborist. The work shall be conducted in accordance with the most recent ANSI A300 standards, and by a California licensed tree-service contractor (D-49) that has an ISA certified arborist in a supervisory role, carries General Liability and Worker's Compensation insurance, and abides by ANSI Safety Operations.
- 25. Avoid disposing harmful products (such as cement, paint, chemicals, oil and gasoline) beneath canopies or anywhere on site that allows drainage within or near TPZs. Herbicides should not be used with a TPZ; where used on site, they should be labeled for safe use near trees. Also, liming should not occur within 50 feet of a tree's canopy.

7.0 ASSUMPTIONS AND LIMITING CONDITIONS

- Information presented herein covers only inventoried trees, and reflects their size, condition, and areas viewed from the subject site and adjoining streets and sidewalks on 4/25/25 and 6/27/25. Observations were performed visually and obtained from the ground without any probing, coring, dissecting or excavating.
- The assignment pertains solely to trees listed in Exhibit A. I hold no opinion towards other trees on or surrounding the project area.
- I cannot provide a guarantee or warranty, expressed or implied, that deficiencies or problems of any trees or property in question may not arise in the future.
- No assurance can be offered that if all my recommendations and precautionary measures (verbal or in writing) are accepted and followed that the desired results may be achieved.
- I cannot guarantee or be responsible for the accuracy of information provided by others.
- I assume no responsibility for the means and methods used by any person or company implementing recommendations presented in this report.
- Information presented herein represents my opinion. As such, my fee is in no way contingent upon the reporting of a specified finding, conclusion or value.
- Numbers shown on the site map in Exhibit B are solely intended to represent a tree's general location and shall not be construed as surveyed points.
- This report is proprietary to me and may not be copied or reproduced in whole or part without prior written consent. It has been prepared for the sole and exclusive use of the parties to whom submitted.
- If any part of this report or copy thereof be lost or altered, the entire evaluation shall be invalid.

Prepared By:

David L. Babby

Registered Consulting Arborist® #399

Board-Certified Master Arborist® #WE-4001B

CA Licensed Tree Service Contractor #796763 (C61/D49)





Date: July 18, 2025

EXHIBIT A:

TREE INVENTORY TABLE

(one sheet)

TREE INVENTORY TABLE

| | | | SIZE | | COND | ITION | | REGUI | LATED | | |
|---------------------|------------------------|----------------------|--------------|---------------------|---|--|---|---------------|-------------|------------------|-------------------------------------|
| TREE/ TAG NO. | TREE NAME | Trunk Diameter (in.) | Height (ft.) | Canopy Spread (ft.) | Overall Percentage (100%=Best, 0%=Worst) | Overall Description (Good/Fair/Poor/Dead) | Suitability for Preservation (High/Moderate/Low) | Heritage Tree | Street Tree | Proposed Removal | Appraised Value (Heritage Trees) |
| | Coast redwood | | | | | | | | | | |
| 24 | (Sequoia sempervirens) | 66 | 100 | 50 | 40% | Poor | Moderate | X | - | X | \$24,900 |

Comments: Trunk bifurcates into codominant leaders (E and W configuration) at 12' high, and forms a weak union containing 4-5' of included bark. The vast majority of tree, ±85%, ascends above the union. The E leader also divides into codominant branches at 40' higher. Elongated limbs along crown, a condition creating excessive weight and a higher potential for one or more to break. Ground beneath canopy is comprised of artificial turf, installed sometime in last few years; the impact to roots during the process, and the extent of compaction of soil and any underlying base material are unknown. Overall, the tree appears in fair health, and has a poor structure and good form.

| | Shamel ash | | | | | | | | | | |
|----|------------------|----|----|----|-----|------|----------|---|---|---|----------|
| 25 | (Fraxinus uhdei) | 44 | 60 | 60 | 40% | Poor | Moderate | X | - | - | \$11,100 |

Comments: Trunk is nearly 6' from shared fence along W boundary. Multiple leaders emerge along trunk at 11' high and form narrow and weak attachments, some with included bark. Asphalt mounds formed by roots. Asymmetrical canopy grows away from the W direction. Highly elevated canopy, quite dramatically over structure beneath its W side. Overall, tree appears healthy, and has a poor structure and fair form.

| | Coast redwood | | | | | | | | | | |
|----|------------------------|----|-----|----|-----|------|----------|---|---|---|----------|
| 26 | (Sequoia sempervirens) | 72 | 120 | 65 | 50% | Fair | Moderate | X | - | - | \$35,000 |

Comments: Trunk spans over the S fence line, indicating joint ownership with the adjoining neighbor. Raised asphalt formed by its base and roots along both sides of fence. Has a very thin top, symptomatic of low vigor, and historic imagery reveals this condition has existed for many years, likely due to insufficient water availability due to most of the ground being covered by asphalt. Formed by a single trunk. Nearly 3/4 of branches overhanging site have been reduced in length. Overall, the tree appears in relatively poor health, and has good structure and form.

| | Shamel ash | | | | | | | | | | |
|----|-------------------|----|----|----|-----|------|-----|---|---|---|---------|
| 27 | (Fraxinus uhdei) | 28 | 45 | 45 | 30% | Poor | Low | X | - | - | \$2,700 |

Comments: Borders the E fence line, and the trunks spans the boundary and fence line, the majority of which is on the adjoining property. Asphalt is located up to its base and fence line. Trunk leans slightly NE. Has a thin, sparse, leggy and asymmetrical canopy with excessive limb/branch weight and deadwood. Excessively pruned in past with numerous reduction/topping cuts. Crowded-growing conditions adjacent to #26. Overall, tree appears in fair health, has a poor structure and fair form.

Project: Menlo Park Temp Fire Station No. 1 Prepared for: Menlo Park Fire Protection District Prepared by: David L. Babby, RCA #399

EXHIBIT B:

SITE MAP

(one sheet)




EXHIBIT C:

PHOTOGRAPHS

(four sheets)

Photo Index















Menlo Park Temp Fire Station No. 1; 114 Santa Margarita Ave., Menlo Park Menlo Park Fire Protection District













Menlo Park Temp Fire Station No. 1; 114 Santa Margarita Ave., Menlo Park Menlo Park Fire Protection District













Menlo Park Temp Fire Station No. 1; 114 Santa Margarita Ave., Menlo Park Menlo Park Fire Protection District

Page C-3













Menlo Park Temp Fire Station No. 1; 114 Santa Margarita Ave., Menlo Park Menlo Park Fire Protection District

Page C-4

EXHIBIT D:

TREE APPRAISAL CALCULATION TABLE

(one sheet)

HERITAGE TREE APPRAISAL CALCULATION TABLE

| | | SI | ZE | | | DEPREC | IATION FA | ACTORS | | |
|---------------------|---|----------------------|----------------------|---|--|--------------------------|------------------------|----------------------|------------------------|---|
| TREE/ TAG NO. | TREE NAME | Trunk Diameter (in.) | Cross Sectional Area | Replacement Tree Basic Price (inch)² | Basic Cost (Cross Sectional Area x Basic Price) | Overall Condition Rating | Functional Limitations | External Limitations | Total Depreciated Cost | Appraised Value (round to nearest \$100) |
| 24 | Coast redwood (Sequoia sempervirens) | 66 | 3421.20 | 36.36 | \$124,395 | 40% | 60% | 100% | \$29,855 | \$29,900 |
| 25 | Shamel ash (Fraxinus uhdei) | 44 | 1520.53 | 36.36 | \$55,287 | 40% | 60% | 100% | \$13,269 | \$13,300 |
| 26 | Coast redwood (Sequoia sempervirens) | 72 | 4071.51 | 36.36 | \$148,040 | 50% | 50% | 100% | \$37,010 | \$37,000 |
| 27 | Shamel ash (Fraxinus uhdei) | 28 | 615.75 | 36.36 | \$22,389 | 30% | 40% | 100% | \$2,687 | \$2,700 |

Project: Menlo Park Temp Fire Station No. 1 Prepared for: Menlo Park Fire Protection District Prepared by: David L. Babby, RCA #399

California Environmental Reporting System (CERS)

Submittal Summary

Submitted TBD

FIRE STATION #1 (CERSID: 10064581)

Facility Information

FIRE STATION #1 (MENLO PARK, CA)

- · Business Activities
- · Business Owner/Operator Identification

Guidance Messages

- · Warning:
 - 9.
 1. Business Activities The federal EPA ID Number for CERSID: 10064581 has changed from: 'CAL000224631' to "
 - 2. Business Owner/Operator Identification The Facility ID for CERSID: 10064581 has changed from: '220223_011224' to '41-000-011224'.

Hazardous Materials Inventory

- · Hazardous Material Inventory (4)
- Site Map (Official Use Only)
 - Figure 2 Site Plan (Adobe PDF, 265KB)
 - Figure 1 Facility Location Map (Adobe PDF, 344KB)

Emergency Response and Training Plans

- Emergency Response/Contingency Plan
 - Emergency Response/Contingency Plan (Adobe PDF, 496KB)
- Employee Training Plan
 - Employee Training Plan (Adobe PDF, 56KB)

California Environmental Reporting System (CERS)

Business Activities

Site Identification

FIRE STATION #1

300 MIDDLEFIELD RD MENLO PARK, CA 94025

County San Mateo

CERS ID 10064581

EPA ID Number

Submittal Status

Submitted TBD

Hazardous Materials

Does your facility have on site (for any purpose) at any one time, hazardous materials at or above 55 gallons for liquids, 500 pounds for solids, or 200 cubic feet for compressed gases (include liquids in ASTs and USTs); or is regulated under more restrictive inventory local reporting requirements (shown below if present); or the applicable Federal threshold quantity for an extremely hazardous substance specified in 40 CFR Part 355, Appendix A or B; or handle radiological materials in quantities for which an emergency plan is required pursuant to 10 CFR Parts 30, 40 or 70?

Yes

Underground Storage Tank(s) (UST)

Does your facility own or operate underground storage tanks?

No

Hazardous Waste Is your facility a Hazardous Waste Generator?

No

Does your facility treat hazardous waste on-site?

No

ls your facility's treatment subject to financial assurance requirements (for Permit by Rule and Conditional Authorization)?

No

Does your facility consolidate hazardous waste generated at a remote site?

No

Does your facility need to report the closure/removal of a tank that was classified as hazardous waste and cleaned on-site?

No No

Does your facility generate in any single calendar month 1,000 kilograms (kg) (2,200 pounds) or more of federal RCRA hazardous waste, or generate in any single calendar month greater than 1 kg (2.2 pounds) of RCRA acute hazardous waste; or generate more than 100 kg (220 pounds) of spill cleanup materials contaminated with RCRA acute hazardous waste.

No

Is your facility a Household Hazardous Waste (HHW) Collection site?

Excluded and/or Exempted Materials

Does your facility recycle more than 100 kg/month of excluded or exempted recyclable materials (per HSC 25143.2)?

No

Aboveground Petroleum Storage

Does your facility own or operate aboveground petroleum storage tanks or containers AND:

No

have a total aboveground petroleum storage capacity of 1,320 gallons or more, OR * have one or more petroleum tanks in an underground area?

Regulated Substances

Does your facility have Regulated Substances stored onsite in quantities greater than the threshold quantities established by the California Accidental Release prevention Program (CalARP)?

No

Additional Information

No additional comments provided.

California Environmental Reporting System (CERS)

Business Owner Operator

Facility/Site

FIRE STATION #1

300 MIDDLEFIELD RD

MENLO PARK, CA 94025

CERS ID 10064581

Submittal Status

Submitted on 10/10/2023 by *Briana Lipka* of FIRE STATION #1 (MENLO PARK, CA)

Business Fax

Identification

Menlo Park Fire Protection District

Operator Phone **Business Phone**

(650) 688-8400 (650) 688-8400 **Beginning Date**

Ending Date

Dun & Bradstreet

SIC Code

Primary NAICS

Facility/Site Mailing Address

170 Middlefield Road

Menlo Park, CA 94025

Primary Emergency Contact

On Duty Battalion Chief

On Duty Battalion Chief

Business Phone 24-Hour Phone

(650) 688-8400

(650) 269-3735

Pager Number

Pager Number

Owner

Menlo Park Fire Protection District

(650) 688-8400

300 MIDDLEFIELD AVE

MENLO PARK, CA 94025

Secondary Emergency Contact

Gage Schlice

Title

Signer Title

Fire Marshal

Fire Marshal

Business Phone 24-Hour Phone

(650) 688-8400 (650) 388-6339

Billing Contact

Menlo Park Fire

Protection District

mpfpd@menlofire.gov (650) 688-8400

170 Middlefield Road Menlo Park, CA 94025 **Environmental Contact**

Gage Schlice

(650) 688-8400 170 Middlefield Road mpfpd@menlofire.gov

Menlo Park, CA 94025

Name of Signer

Jon Johnston Additional Information

Briana Lipka, QISP, CHMM

Environmental Director

Du-All Safety, LLC | 45950 Hotchkiss St. | Fremont, CA 94539

(510) 651-8289 | (408) 318-2156 - Cell

brianal@du-all.com | www.du-all.com

Document Preparer Briana Lipka

Locally-collected Fields

Some or all of the following fields may be required by your local regulator(s).

Property Owner

Phone

Mailing Address

Assessor Parcel Number (APN)

Number of Employees

Facility ID

41-000-011224


| | | | Hazardo | ous Materials / | And Waste | es Inventor | y Matrix | Report | | | | | |
|--|----------|--|--|--|--------------------------|---|----------------------------------|---|--|--|-------------|--|--|
| CERS Business/Org. Facility Name | FIRE STA | ATION #1 ATION #1 LEFIELD RD , MENLO PARK 94025 | | | Chemical Loc Generato | | | | CERS ID 10064581 Facility ID 220223_011224 Status Submitted on TBD | | | | |
| DOT Code/Fire Haz. Cl Combustible Liquid, | | Common Name DIESEL FUEL NO. 2 CAS No. 68334-30-5 Map: Site Plan Grid: Generator | Unit Max. Daily Largest Cont. Avg. Da Gallons 1000 1000 850 State Storage Container Pressue Liquid Aboveground Tank Ambient Type Pure Days on Site: 365 Ambient | | | | Annual Waste Amount 0 Waste Code | Federal Hazard Categories - Physical Flammable - Health Acute Toxicity - Health Skin Corrosion Irritation | Component Name | Hazardous Componen (For mixture only) % Wt | EHS CAS No. | | |
| | | DIESEL FUEL NO. 1 CAS No 68334-30-5 Map: Site Plan Grid: Generator | Liquid Type | 1000 Storage Container Aboveground Tank Days on Site: 365 | 1000 | 850 Pressue Ambient Temperature Ambient | 0 Waste Code | - Physical Flammable - Health Acute Toxicity - Health Skin Corrosion | | | | | |
| | | Propane CAS No 68334-30-5 Map: Site Plan Grid: Generator | Liquid A | 1000 torage Container Aboveground Tank Days on Site: 365 | 1000 | 850 Pressue Ambient Temperature Ambient | 0 Waste Code | Irritation - Physical Flammable - Health Acute Toxicity - Health Skin Corrosion Irritation | | | | | |

E4 Page 1 of 3

| Hazardous Materials And Wastes Inventory Matrix Report | | | | | | | | | | | | | |
|--|---|---------------|--------------------------------------|--------------------------|--|---------------------------|--|---|---|-------------|--|--|--|
| acility Name | FIRE STATION #1 FIRE STATION #1 300 MIDDLEFIELD RD , MENLO PARK 94025 | | | Chemical Local Shop - Ox | ation Tygen Room | | | CERS ID 10064581 Facility ID 220223_011224 Status Submitted TBD | | | | | |
| OT Code/Fire Haz. C | · | Unit | Max. Daily | Quantities Largest Cont. | Avg. Daily | Annual Waste Amount | Federal Hazard Categories | Component Name | Hazardous Component (For mixture only) % Wt | EHS CAS No. | | | |
| Oxidizing, Class 2 | OXYGEN, GAS CAS No 7782-44-7 Map: Site Plan Grid: Storage Bldg | Gas C Type | 1750 torage Container Cylinder | 250 | 1500 Pressue > Ambient Temperature Ambient | 0 Waste Code | - Physical Gas Under Pressure - Physical Oxidizer - Physical Hazard | | | | | | |
| | Storage Bidg | ruie L | ays on site. 303 | | Ambient | | Not Otherwise Classified | | | | | | |

E5 Page 3 of 3

Fire Station 1 Site Plan



Fire Station #1 Location Map



CALIFORNIA ENVIRONMENTAL REPORTING SYSTEM (CERS) CONSOLIDATED EMERGENCY RESPONSE / CONTINGENCY PLAN Prior to completing this Plan, please refer to the INSTRUCTIONS FOR COMPLETING A CONSOLIDATED CONTINGENCY PLAN

| A. FACILITY IDENTIFICATION AND OPERATIONS OVERVIEW | | | | | | | | | | | | | |
|--|---|--|---|---------------------------------|---|------------------------------------|--|---|--|--|--|--|----------------|
| FACILITY ID# | | | | | | A1. | CERS | ID# | A2. | DATE OF I | | EPARATION/REVISIO | |
| BUSINESS NAME (Same as F | Facility Na | me or L | DBA - D | oing Bı | usiness | As) | | | | | | | A4. |
| BUSINESS SITE ADDRESS | | | | | | | | | | | | | A5. |
| BUSINESS SITE CITY | | | | | | | | | A6. | CA | ZIP COE | DE | A7. |
| TYPE OF BUSINESS (e.g., Pa | inting Co | ntractor) |) | | | | A8. | INCIDENTAL C | PERA | TIONS (e.g., | Fleet Mair | ntenance) | A9. |
| THIS PLAN COVERS CHEM | ICAL SPI | LLS, FI | RES, A | ND EA | RTHQ | UAK | ES INVO | OLVING (Check al | ll that a | apply): | | | A10. |
| ☐ 1. HAZARDOUS MATER | IALS; | 2. HA | ZARDO | OUS W | ASTES | S | | | | | | | |
| | | B | INT | ERN | NAL | RE | SPON | NSE | | | | | |
| INTERNAL FACILITY EMER 1. CALLING PUBLIC EMI 2. CALLING HAZARDOU 3. ACTIVATING IN-HOUS | ERGENC' S WASTI | Y RESP E CONT | ONDEF RACTO | RS (e.g. DR | ., 9-1-1 | | heck all | that apply): | | | | | B1. |
| C. EMERG | ENCY | Z CO | MM | UNI | CAT | ION | IS. PI | HONE NUM | 1BE | RS AND | NOTI | FICATIONS | |
| In the event of an emergency in 1. Notify facility personnel and 2. Notify local emergency responsors, Notify the local Unified Prog 4. Notify the State Warning Certains. | volving hat evacuate in onders by gram Ager | zardous f necess calling 9 cy (UP) | s materia sary in a 9-1-1; A) at the | als and | or haza | ardous h the l | waste, a | all facilities must IN | MMED | DIATELY: | | | |
| Facilities that generate, treat, sto is an imminent or actual emerge of facility and type of release in 1. Title 22 California Code of R 2. Title 22 California Code of R 3. Title 40 Code of Federal Reg 4. Title 22 California Code of I hazardous waste in any calen | ncy situat volved: Legulation Legulations sulations § Regulation | ion such s §6626 s §6626 302.6. I as §6620 | as an e 5.56. Er 5.196. F Notifica | xplosionergen Responsion req | on, fire, cy Proc se to Le quireme | or releadure eaks or eaks fo | ease, the s for gen r Spills a r a releas | Emergency Coord terators of 1,000 ki and Disposition of I se of a hazardous so | inator i logram Leaking ubstand | must follow the sor more of lag or Unfit-for- ce equal to or | ne appropri nazardous v -Use Tank greater tha | ate requirements for the waste in any calendar many calendar many systems. In the reportable quantity | category onth. |
| Following notification and before and the local fire department's hand the facility; and 2. Ensure that no material that is procedures are completed. | nazardous nd disposa | materia l of reco | ls progra overed w | am, if r | necessa: ontami | ry, tha | t the fac soil or si | ility is in complian urface water, or any | ce with y other | n requirements material that | s to: results from | m an explosion, fire, or | release at |
| EMERGENCY RESPONSE | AMBUI | ANCE | FIRE, | POLIC | E AND | CHP | | | | | | 9-1-1 | |
| PHONE NUMBERS: | CALIFO | RNIA | STATE | WARN | NING C | ENTI | ER (CSV | VC)/CAL OES | | | | (800) 852-7550 | |
| | NATIO | NAL RE | ESPONS | SE CEN | TER (| NRC) | | | | | | (800) 424-8802 | |
| | POISON | CONT | ROL C | ENTE | ₹ | | | | | | | (800) 222-1222 | |
| | LOCAL | UNIFI | ED PRO | GRAN | 4 AGE | NCY (| (UPA) | | | | | | C1. |
| | OTHER | (Specif | y): | | | | | | | | C2. | | C3. |
| NEAREST MEDICAL FACILI | TY / HOS | PITAL | NAME | • | | | | | | | C4. | | C5. |
| AGENCY NOTIFICATION PH | IONE NU | MBERS | S: (| CALIFO | ORNIA | DEP | T. OF TO | OXIC SUBSTANC | ES CC | ONTROL (DT | SC) | (916) 255-3545 | |
| | | | F | REGIO | NAL W | ATE | R QUAI | LITY CONTROL E | BOARI | O (RWQCB). | | | C6. |
| | | | | | | | | ROTECTION AGE | | | | (800) 300-2193 | |
| | | | (| CALIFO | ORNIA | DEP | T. OF FI | SH AND WILDLI | FE (CI | OFW) | | (916) 358-2900 | |
| | | | Ţ | J.S. CC | OAST (| GUAR | D (USC | G) | | | | (202) 267-2180 | |
| | | | | | | | | | | | | (916) 263-2800 | |
| | | | | | | | OF THE | E STATE FIRE MA | RSHA | AL (OSFM) | | (916) 323-7390 | C8. |
| | | | | | R (Spec | | | | | | C9. | <u> </u> | C10. |
| | | | (| OTHER | (Speci | ify): | | | | | | | C10. |

| INTERNAL FACILITY EMERGENCY C | OMMUNICATIONS OR ALARM NOTIF | FICATION WILL OCC | UR BY (Check all that apply): | C11. |
|--|--|---------------------------------------|--|------|
| ☐ 1. VERBAL WARNINGS; | 2. PUBLIC ADDRESS OR INTERC | OM SYSTEM; | 3. TELEPHONE; | |
| ☐ 4. PAGERS; NOTIFICATIONS TO NEIGHBORING F | 5. ALARM SYSTEM; | BY AN OFF-SITE RE | 6. PORTABLE RADIO ELEASE WILL OCCUR BY (Check all that apply): | C12. |
| ☐ 1. VERBAL WARNINGS; | 2. PUBLIC ADDRESS OR INTERC | | ☐ 3. TELEPHONE; | |
| ☐ 4. PAGERS; | ☐ 5. ALARM SYSTEM; | | ☐ 6. PORTABLE RADIO | |
| EMERGENCY COORDINATOR CONTA | CT INFORMATION: | | | C13. |
| PRIMARY EMERGENCY COORDINAT | OR NAME: | PHONE NO.: | PHONE NO.: | |
| ALTERNATE EMERGENCY COORDIN | ATOR NAME: | PHONE NO.: | PHONE NO.: | |
| ☐ Check if additional Emergency Coordin | nator contact and address information is ava | ailable onsite or by calli | ing PHONE NO.: | |
| Note: If more than one alternate emergence | ey coordinator is designated, attach a list in | order of responsibility. | | |
| | RGENCY CONTAINMENT | | | |
| Check the applicable boxes to indicate you | r facility's procedures for containing spills | and preventing and mit | tigating releases, fires and/or explosions. | D1. |
| ☐ 1. MONITOR FOR LEAKS, RUPTURES, PRESSURE BUILD-UP, ETC.; | | | | |
| _ | CAL BARRIERS (e.g., Portable spill conta | · · · · · · · · · · · · · · · · · · · | perms); | |
| | AL BARRIERS (e.g., Pads, spill pigs, spill | pillows); | | |
| 4. COVER OR BLOCK FLOOR AND 5. LINED TRENCH DRAINS AND/O | | | | |
| ☐ 6. AUTOMATIC FIRE SUPPRESSIO | , | | | |
| ☐ 7. ELIMINATE SOURCES OF IGNIT | | | | |
| ☐ 8. STOP PROCESSES AND/OR OPE | | | | |
| 9. AUTOMATIC / ELECTRONIC EQ | ~ | | | |
| 10. SHUT OFF WATER, GAS, ELECT | TRICAL UTILITIES; GENCY RESPONDER ASSISTANCE AN | D/OP MEDICAL AID | | |
| - | ONS IN ALL THREATENED AND/OR II | | , | |
| | ERSONS IMMEDIATELY AFTER EVAC | * | | |
| _ | MENT FOR ON-SITE EMERGENCY RES | · · | | |
| ☐ 15. REMOVE CONTAINERS AND/O | R ISOLATE AREAS; | | | |
| ☐ 16. HIRE LICENSED HAZARDOUS V | WASTE CONTRACTOR; | | | |
| 17. USE ABSORBENT MATERIAL F | | | | |
| | PROPRIATE VACUUM (e.g., Intrinsically | | | |
| | L AND EQUIPMENT WITHIN DESIGNA TORAGE OF HAZARDOUS WASTE GE | | SPOSE OF WASTEWATER AS HAZARDOUS WA | STE; |
| 21. OTHER (Specify): | TORRIGE OF TIME/INDOORS WHOTE GE | NEIGHED DOMING | EVILLOCITY TO TIONS, | D2. |
| | E. FACILITY E | VACUATION | | |
| THE EQUI OWING ALARM SIGNAL(S) | | | | E1. |
| THE FOLLOWING ALARM SIGNAL(S) ☐ 1. BELLS; | WILL BE USED TO BEGIN EVACUATI | ION OF THE FACILIT | Y (Check all that apply): | E2. |
| ☐ 2. HORNS/SIRENS; | | | | |
| 3. VERBAL (i.e., Shouting); | | | | |
| ☐ 4. OTHER (Specify): | L BE USED FOR AN EMERGENCY ASS | FMRI V ARFA(S) (e o | Parking lot street corner) | E3. |
| THE TOLLOWING EGENTION(S) WILL | JBE OSED FOR AIVENERGENCE FASS. | EMBET MEM(S) (e.g | ,,, I making fot, succe corner). | |
| Note: The Emergency Coordinator must ac | ecount for all onsite employees and visitors | after evacuation. | | |
| EVACUATION ROUTE S AND ALTERN | | | WS: | E4. |
| ☐ 1. WRITTEN PROCEDURES DESCR | IBING ROUTES, EXITS, AND ASSEMB | LY AREAS: | | |
| | NG ROUTES, EXITS, AND ASSEMBLY | | | |
| ☐ 3. OTHER (Specify): | | | E5. | |
| Note: Evacuation procedures and/or maps | should be posted in visible facility locations | s and must be included | in the Contingency Plan. | |
| E | ARRANGEMENTS FOR | EMEDOENO | VEEDVICES | |
| Г. | ARRANGEMENTS FOR | EMERGENC | SERVICES | |
| ADVANCE ARRANGEMENTS FOR LO | CAL EMERGENCY SERVICES (Check of | one of the following): | | F1. |
| 1. HAVE BEEN DETERMINED NOT | * | | | E2 |
| ☐ 2. THE FOLLOWING ARRANGEME | ENTS HAVE BEEN MADE (Specify): | | | F2. |
| | re and police departments, hospitals, state a ty, if necessary. Large Quantity Generators | | | |

Rev. 05/18/22 Page 2 of 4

G. EMERGENCY EQUIPMENT Check the applicable boxes to list emergency response equipment available at the facility, identify the location(s) where the equipment is kept, and indicate the equipment's capability, if applicable. **TYPE** EQUIPMENT AVAILABLE LOCATION **CAPABILITY** G2. G1. **EXAMPLE ⋈** CHEMICAL PROTECTIVE GLOVES SPILL RESPONSE KIT SINGLE USE, OIL RESISTANT ONLY 1. ☐ CHEMICAL PROTECTIVE SUITS, APRONS, Safety AND/OR VESTS and 2. CHEMICAL PROTECTIVE GLOVES First Aid 3. CHEMICAL PROTECTIVE BOOTS 4. SAFETY GLASSES, GOGGLES, AND FACE **SHIELDS** 5. HARD HATS 6. AIR-PURIFYING RESPIRATORS ☐ SELF-CONTAINED BREATHING APPARATUS (SCBA) 8. FIRST AID KITS 9. PLUMBED EYEWASH FOUNTAIN AND/OR **SHOWER** 10. PORTABLE EYEWASH KITS AND/OR STATION 11. OTHER Fire 12. PORTABLE FIRE EXTINGUISHERS **Fighting** 13. FIXED FIRE SUPPRESSION SYSTEMS AND/ OR SPRINKLERS 14. FIRE ALARM BOXES 15. OTHER Spill 16. ☐ ALL-IN-ONE SPILL KIT Control 17. ABSORBENT MATERIAL and Clean-Up 18. ☐ CONTAINER FOR USED ABSORBENT 19. BERM AND/OR DIKING EQUIPMENT 20. BROOM 21. SHOVEL 22. VACUUM 23. EXHAUST HOOD 24. SUMP AND/OR HOLDING TANK 25. CHEMICAL NEUTRALIZERS 26. GAS CYLINDER LEAK REPAIR KIT 27. SPILL OVERPACK DRUMS 28. OTHER Communi- 29. TELEPHONES (e.g., Cellular) cations 30. INTERCOM AND/OR PA SYSTEM and Alarm 31. PORTABLE RADIOS Systems 32. AUTOMATIC ALARM CHEMICAL MONITORING EQUIPMENT 33. OTHER Other 34. OTHER

| H. EARTHQUAKE VULNERABILITY | | | | | | |
|---|---|--|--|--|--|--|
| | | | | | | |
| Identify areas of the facility that are vulnerable to hazardous materials releases due to seismic motion. These areas require immediate isolated VULNERABLE AREAS (Check all that apply): I. HAZARDOUS MATERIALS AND/OR WASTE STORAGE AREAS 2. PROCESS LINES AND PIPING 3. LABORATORY 4. WASTE TREATMENT AREA | | | | | | |
| Identify mechanical systems vulnerable to releases / spills due to earthquake-related motion. These systems require immediate isolation and | d inspection. | | | | | |
| VULNERABLE SYSTEMS AND/OR EQUIPMENT (Check all that apply): 1. SHELVES, CABINETS AND/OR RACKS 2. TANKS AND SHUT-OFF VALVES 3. PORTABLE GAS CYLINDERS 4. EMERGENCY SHUT-OFF AND/OR UTILITY VALVES 5. SPRINKLER SYSTEMS 6. STATIONARY PRESSURIZED CONTAINERS (e.g., Propane tank) | H4. | | | | | |
| I. EMPLOYEE TRAINING | | | | | | |
| Employee training is required for all employees and/or contractors handling hazardous materials and/or hazardous wastes during normal an | d/an amangan ay an anations | | | | | |
| Most facilities will need to submit a separate Training Plan. However, your CUPA may accept this section as the Training Plan for some set Employee training plans may include the following content: Applicable laws and regulations; Emergency response plans and procedures; Safety Data Sheets; Hazard communication related to health and safety; Methods for safe handling of hazardous substances; Hazards of materials and processes (e.g., fire, explosion, asphyxiation); Hazard mitigation, prevention and abatement procedures; Coordination of emergency response actions; Notification procedures for local emergency responders, CUPA, Cal OES, and onsite personnel; OTHER (Specify): | onse equipment and supplies control materials); | | | | | |
| Check the annicable haves below to indicate how the employee training program is administered | | | | | | |
| Check the applicable boxes below to indicate how the employee training program is administered. 1. FORMAL CLASSROOM 2. VIDEOS 3. SAFETY MEETINGS 4. STUDY GUIDES / M. 5. OTHER (Specify): | ANUALS II. I2. | | | | | |
| ☐ 6. NOT APPLICABLE SINCE FACILITY HAS NO EMPLOYEES ☐ 7. CHECK IF A SEPARATE EMPLOYEE TRAINING PLAN IS USED AND UPLOADED TO CERS AS A PDF DOCUMENT ☐ 8. CHECK IF EMPLOYEE TRAINING IS COVERED BY THE ABOVE REFERENCED CONTENT AND OTHER DOCUMENTS EMPLOYEE TRAINING FREQUENCY AND RECORDKEEPING TRAINING MUST BE: | ONSITE I3. | | | | | |
| Provided initially for new employees as soon as possible following the date of hire. New employees should not work in an unsuper hazardous materials handling and/or hazardous waste management without proper training; Provided within six months from the date of hire for new employees at a large quantity generator; Ongoing and provided at least annually; Amended prior to a change in process or work assignment; Given upon modification to the Emergency Response/Contingency Plan. | ervised position that involves | | | | | |
| Large Quantity Generator Training: Large quantity generators (1,000 kg or more) must retain written plan and documentation of employed A written description of the type and amount of both initial and ongoing training that will be given to persons filling each job position having waste management and/or emergency response. The name, job title and job description for each position at the facility related to hazardous waste management. Current employee training records must be retained until closure of the facility and former employee training records must be retained termination of employment. | g responsibility for hazardous | | | | | |
| Small Quantity Generator Training: Small quantity generators (less than 1,000 kg) must include basic hazardous waste managem procedures but a written employee training plan and training records are not required. In order to show that the facility has met the small training requirement, an employee training plan and training records may be made available. | | | | | | |
| Hazardous Materials Business Plan Training : Businesses must provide initial and annual employee training that includes the content re may be based on the job position and training records must be made available for a period of at least three years. | ferenced above. The training | | | | | |
| J. LIST OF ATTACHMENTS | | | | | | |
| Check one of the following: 1. NO ATTACHMENTS ARE REQUIRED; or 2. THE FOLLOWING DOCUMENTS ARE ATTACHED: | J1. J2. | | | | | |

Rev. 05/18/22 Page 4 of 4

EMPLOYEE TRAINING PLAN 1. FACILITY INFORMATION BUSINESS NAME (Same as FACILITY NAME or DBA – Doing Business As) FACILITY ID FIRE STATION #1 FA0011224 ADDRESS 300 MIDDLEFIELD RD 2. TRAINING FOR PERSONNEL Not applicable because facility has no employees Personnel are trained in the following procedures: X Internal alarm/notification X Evacuation/re-entry procedures & assembly point locations X Emergency incident reporting External emergency response organization notification X Location(s) and contents of Emergency Response/Contingency Plan Facility evacuation drills, that are conducted at least: (Specify: "Quarterly", etc.) Specify 3. TRAINING FOR CHEMICAL HANDLERS Chemical Handlers are additionally trained in the following: X Safe methods for handling and storage of hazardous materials X Location(s) and proper use of fire and spill control equipment X Spill procedures/emergency procedures X Proper use of personal protective equipment Specific hazard(s) of each chemical to which they may be exposed, including routes of exposure X (i.e., inhalation, ingestion, absorption) Hazardous Waste Handlers/Managers are trained in all aspects of hazardous waste management X specific to their job duties (e.g., container accumulation time requirements, labeling requirements, storage area inspection requirements, manifesting requirements, etc.) 4. EMERGENCY RESPONSE TEAM Members are capable of and engaged in the following: Complete this section only if you have an in-house emergency response team $|\mathbf{X}|$ Personnel rescue procedures X Shutdown of operations X Liaison with responding agencies X Use, maintenance, and replacement of emergency response equipment X Refresher training, which is provided at least annually Emergency response drills, which are conducted at least: (Specify: "Quarterly", etc.) Specify **Employees** are

| 5. RECORD KEEPING | | | | |
|--|--|--|--|--|
| The following records are maintained at the facility (Check all that apply). | | | | |
| Note: This facility. | list of records does not necessarily identify every type of record required to be maintained by the | | | |
| X | Current employees training records (to be retained until closure of the facility) | | | |
| X | Former employees' training records (to be retained at least three years after termination of employment) | | | |
| × | Training Program(s) (i.e., written description of introductory and continuing training) | | | |
| X | Current copy of this Emergency Response/Contingency Plan | | | |
| X | Record of recordable/reportable hazardous material/waste releases | | | |
| X | Record of hazardous material/waste storage area inspections | | | |
| | Record of hazardous waste tank daily inspections | | | |
| X | Description and documentation of facility emergency response drills | | | |